





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/09/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB347K
Case Reference Number	BUS/09/20/7001
Registration Date	20/11/2012
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Tan Chun Kuen
Type of Accident	Side Swipe
Accident Date and Time	9/9/2020 3:05 PM
Accident Reported Date and Time	11/9/2020 10:40 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108125
Special Instruction to ARC,if any	SMB347K-RIGHT REAR PORTION GBD2293M (TP) INSURED WITH
Prepared Date and Time	11/9/2020 1:05 PM
Chassis Number	WMAA22ZZ5C7001509
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,325.00	\$795.00
Total Spray Cost	\$616.00	\$528.00
Total Spare Part Cost	\$3,258.25	\$2,561.40
Total Other Cost	\$0.00	(\$264.60)
TOTAL COST	\$5,199.25	\$3,619.80
Lump Sum Total	\$0.00	\$3,600.00
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Kok Khoon Goh	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	11/09/2020 1:18 PM	11/09/2020 3:57 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/09/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,325.00				\$795.00		
Total Labour			\$1,325.00				\$795.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$616.00				\$528.00		
Total Spray Painting & Panel Beating			\$616.00				\$528.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Lump Sum Adjustment by Surveyor			\$0.00				(\$264.60)		
Total Other Costs			\$0.00				(\$264.60)		
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010169	GLASS	4001X01-GLASS5178	GLASS,SIDE:R6,FOR MAN A22 BUS	0.00	\$543.40	0.00	\$0.00	Replace	Check X SVC
4006315			ACTIVATOR	0.00	\$80.00	0.00	\$0.00	Replace	Not Given X SVC
4006314			SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given X SVC
4006313	CONSUMABLE	SIKA® Primer-206 G+P	PRIMER (SIKA 206 G+P)	0.00	\$80.00	0.00	\$0.00	Replace	Not Given X SVC
6010299			SIGNAL LAMP LED	1.00	\$1,274.10	10.00	\$1,146.69	Replace	Replace / SCR
6010298			LAMP,STOP:LED (MAN BUS)	2.00	\$1,141.70	10.00	\$2,055.06	Replace	Replace / SCR
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair X R
6009992	BODY RH	A01001-CW564	PANEL,SIDE:R11,FOR MAN A22 BUS	1.00	\$1,782.50	100.00	\$0.00	Repair	Repair X R
Total					\$5,913.40		\$3,201.75		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

3,201.75  
795  
528  
-----  
4,524.75  
- 2040  
-----  
3,619.8  
  
415  
\$3,600      2 days