

ASS. REC. BY:

REF:

CS/AH20009803/Rivf3

7286

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKS 1039C

at Workshop m/s CYCLO &amp; CARRIAGE

of 28 PANDAN GARDEN

Insured:

AH

Policy No.

Claims No.

Sum Insured:

Excess:

TBA 600

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

69K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKS 1039C

Yr Regn:

2015 / MAR

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI OUTLANDER 2.4 c.c 2360

Colour:

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

114063

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JMYXTHF3WF2001657

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / 3/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/09/2020

D.O.A.

14/09/2020

Survey held at

CYCLO &amp; CARRIAGE (PH)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

16/10/20

Final fig \$12,912.24 confirmed by email (Red 3720.58, 22%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Rep. Format:

Merimen

Lump Sum / F.B. (\$12,912.24)



CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

## ESTIMATE

No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV13801/Mr Tan Peng Seng (chen Bingchen) Reg No/Reg Date SKS1039C / 25/03/201 Date In/Mileage / 114063 Chassis No JMYXTGF3WFZ001657 Engine No 4B12PG7136 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	14/09/2020/ 11:26	QUD	247 / DonBong	57305			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH FRONT FENDER, RH MOULDING GARNISH, REPAIR REAR BUMPER FACE								1125 1350.00
E PNT88000 REMOVE AND INSTALL FRONT PARKING ASSIST								60.00
E PNT98000 PAINT WORK SPRAY FRONT BUMPER, RH FRONT FENDER, BOTH RH DOOR, REAR BUMPER FACE AND AFFECTED PORTION								1050 2100.00
M SUNDRY APPLY BODY SEALANT								X 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A 30000001 RENEW UNDERCARRIAGE DAMAGES								450? 675.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY LABOUR RENEW RH FRONT AND RH REAR SPORT RIM INCLUDING BALANCING								60.00
M SUNDRY SUPPLY RH FRONT AND RH REAR TIRE								400 (1pc) 800.00
M SUNDRY SUNDRIES								30 50.00
M	HEADLAMP ASSY, RH				1.00	1852.00	23.00	1426.04
M	TANK, WINDSHIELD WASHER				1.00	88.00	23.00	67.76
M	MOTOR, HEADLAMP WASHER				1.00	354.00	23.00	272.58
M	GROMMET, WINDSHIELD WASHER				1.00	5.00	23.00	3.85
M	COVER, ENG ROOM UNDER, RR RH				1.00	32.00	23.00	24.64
M	COVER, ENG ROOM UNDER, RR LH				1.00	32.00	23.00	24.64
M	COVER, ENG ROOM UNDER, FR				1.00	348.00	23.00	267.96

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV13801/Mr Tan Peng Seng (chen Bingchen) Reg No/Reg Date SKS1039C / 25/03/201 Date In/Mileage / 114063 Chassis No JMYXTGF3WFZ001657 Engine No 4B12PG7136 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F27) Colour/Trim U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	14/09/2020/ 11:26	QUD	247 / DonBong	57305

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M COVER,ENG ROOM UNDER,FR ?	1.00	149.00	23.00	114.73
M BRACKET,FR BUMPER SIDE,LH X	1.00	24.00	23.00	18.48
M BRACKET,FR BUMPER SIDE,RH re	1.00	24.00	23.00	18.48
M FACE,FR BUMPER de	1.00	1036.00	23.00	797.72
M COVER,FR FOG LAMP ms	1.00	20.00	23.00	15.40
M GARNISH,FR BUMPER,RH X	1.00	32.00	23.00	24.64
M GARNISH,FR FOG LAMP,RH ms	1.00	50.00	23.00	38.50
M REINFORCEMENT,FR BUMPER X	1.00	503.00	23.00	387.31
M MOULDING,FR BUMPER,RH sca	1.00	116.00	23.00	89.32
M MOULDING,RR WHEEL ARCH,RH sca	1.00	199.00	23.00	153.23
M MOULDING,RR BUMPER,RH sca	1.00	106.00	23.00	81.62
M FENDER,FR RH ?	1.00	688.00	23.00	529.76
M AIR DAM,SIDE,RH ?	1.00	541.00	23.00	416.57
M HUB ASSY,FR WHEEL ?	1.00	235.00	23.00	180.95
M SNAP RING,FR WHEEL HUB ?	1.00	25.00	23.00	19.25
M BEARING,FR WHEEL HUB ?	1.00	151.00	23.00	116.27
M KNUCKLE,RH ?	1.00	356.00	23.00	274.12
M ARM ASSY,FR SUSP,LWR RH ?	1.00	337.00	23.00	259.49
M CROSSMEMBER,FR AXLE,NO.1 ?	1.00	1114.00	23.00	857.78
M STRUT,FR SUSP,RH ?	1.00	484.00	23.00	372.68
M PAD,FR SUSP SPRING,UPR ?	1.00	71.00	23.00	54.67
M DAMPER,FR SUSP STRUT ?	1.00	35.00	23.00	26.95
M INSULATOR,FR SUSP STRUT ?	1.00	136.00	23.00	104.72
M LINK,FR SUSP STABILIZER ?	1.00	137.00	23.00	105.49
M GEAR & LINK ASSY,STEERING ?	1.00	1211.00	23.00	932.47
M END ASSY,TIE ROD ?	2.00	62.00	23.00	95.48
M RH REAR HUB ASSY,RR WHEEL ?	1.00	416.00	23.00	320.32
M RH FRONT WHEEL,DISC sca	1.00	1102.00	23.00	848.54
M RH REAR WHEEL,DISC sca	1.00	1102.00	23.00	848.54

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rama - 48 9001008SURVEYOR SIGNATURE: [Signature]DATE: 14/09/2020 P1600

Confirm &amp; accepted by

REMARKS: 6 daysRehony before printEXCESS: TBA / REVERS

7% GST on **Nett** 15,635.95  
1094.52

**Total Payable** 16,730.47

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or the rubber seal or other repair requiring the removal of the windscreen. In the event of inadvertent breakage in the course of renewing

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT:

Date Of Report	14/09/2020 13:46
Date Of Accident	13/09/2020 17:10
Exact Location Of Accident	TOWARDS PIE FROM CHANGI AIRPORT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE:

Vehicle Registration Number	SKS1039C
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN PENG SENG
NRIC No	SXXXX798E
Email Address	LUCKYCOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98559852
Alternative Phone No	OTHERS-98559852
<b>Vehicle Particulars</b>	
Manufacturer	MITSUBISHI
Model	OUTLANDER-2.4 CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100406599
Cover Note Number	
<b>Driver</b>	
Name of Driver	TAN PENG SENG
NRIC No	SXXXX798E
Date Of Birth	02/12/1973
Occupation	INDOOR
Date Of Driving Pass	05/07/1997
Driving Experience	23 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98559852
Fax Number	
Contact Number	OTHERS-98559852
Email Address	LUCKYCOW@GMAIL.COM

ess 61 PASIR RIS GROVE #14-04  
 stcode 518215  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 Vehicle -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLIDED INTO PROPERTY  
 Weather Conditions RAINING  
 Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles (including own vehicle) involved in the accident 1  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: : SHARON SOH  
 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? NO  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number  
 Vehicle Make/Model/Colour  
 Details Of Properties RAILING AT THE BEND  
 Vehicle Category NA/UNKNOWN  
 Name of Driver  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)



## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

14/11/2020  
10:30am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

### SKETCH PLAN

riding →

Refer to AITR Report A.

I/We declare the foregoing particulars are true in every respect.

14 Sept 2020 / 0600 Hrs

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



# SINGAPORE POLICE FORCE



T/20200913/2076

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

1 of 3

Report No. T/20200913/2076

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 13/09/2020 19:54	Vide Report No.: G/20200913/0224	Station Diary No.: 34
--	-------------------------------------	--------------------------

**Informant's Particulars**

Name of Informant: TAN PENG SENG			Address: 61 PASIR RIS GROVE #14-04 SINGAPORE 518215		
ID Type / ID No.: NRIC NO / S7346798E			Contact No.: Home/Office: Mobile: 98559852		
Nationality: SINGAPORE CITIZEN			Email: luckycow@gmail.com		
Sex: Male	Age: 46	Date of Birth: 02/12/1973	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: IT CONSULTANT			Driving Licence Information: Class: 3 Date of Expiry:		

**General Information of the Accident**

Type of Accident: Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 13/09/2020 17:10	Type of Location: Bend
Location:  PAN-ISLAND EXPRESSWAY			
Weather: Drizzling	Road Surface: Wet	Road Speed Limit: 50 Km/h	
Traffic Flow: One Way	Traffic Control: Not Controlled	Traffic Volume: No Traffic	
Type of Collision: Moving Vehicle Against - Road Divider/Kerb/Railings	Anyone conveyed by ambulance: No		

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SKS1039C	Car	MITSUBISHI	OUTLANDE R 2.4 CVT ABS D/AIRBAG AWD S/R	Grey	Slightly Damaged	1

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKS1039C	AIG ASIA PACIFIC INSURANCE PTE. LTD.	2100406599-05	25/03/2020	24/03/2021





# SINGAPORE POLICE FORCE



T/20200913/2076

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

2 of 3

Report No. T/20200913/2076

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	TAN PENG SENG	ID No.	S7346798E
Related Vehicle	NIL	Contact No.	98559852
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

### Brief Details.

On 13/09/2020 at about 1710hrs, I was travelling at 55km/hr at the roundabout when I lost control of my vehicle thus hitting the right railing at the bend. After alighting the vehicle, I realized that my front right tire had burst thus resulting in the lost of control of the vehicle. I wish to state my wife and I did not suffer any injuries from this accident. The supporting beam behind the railing fell off and there was a slight damages caused to the right side of my car front bumper.

LTA marshal was at scene at 1745hrs to assist us with the accident. Shortly after, traffic police arrived at scene and instructed me to proceed to any neighborhood police station to lodge a report to facilitate with further investigation. A case card (G/20200913/0224) was then issued to us by Sgt Alfian.



# SINGAPORE POLICE FORCE



T/20200913/2076

Police Station Of Origin:  
Changi N.P.C  
9 Simei Street 2 SINGAPORE 529914  
Tel No: 1800-5872999

3 of 3

Report No. T/20200913/2076

## CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /  
Sgt 2 ROY WANG

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / GIT /  
SI YEO CHUN JIAN  
Contact No.: 65476213

Authentication Stamp  
NP168

Signature Of Informant:

Date/Time:  
13/09/2020 19:54

Classification Of Case:



AIG Asia Pacific Insurance Pte. Ltd

AIG Building

78 Shenton Way

#07-16

### MOTOR ACCIDENT INTERVIEW FORM

NAME : TAN PENG SENG  
VEHICLE NUMBER : SKS 1039C  
DATE/ TIME OF ACCIDENT : 13 SEPT 2021 / 1710 HRS  
PLACE OF ACCIDENT : TOWARD PIE (FROM AIRPORT)  
THIRD PARTY VEHICLE (IF ANY) : NA

\*\*\*\*\*  
WHERE DID YOU START YOUR JOURNEY AND WHERE WAS THE INTENDED DESTINATION BEFORE THE ACCIDENT?

TERMINAL B 3 to PASIR RIS GROVE (HOME)

DID YOU DRINK ANY ALCOHOLIC DRINKS BEFORE YOU DRIVE ON THE DAY OF THE ACCIDENT? IF YES, DID THE TRAFFIC POLICE CONDUCT ANY BREATHE-ANALYSER TEST ON YOU? IF YES, WHAT WAS THE RESULTS?


NOPE

WHAT IS THE TYPE OF COLLISION AND THE EXTENSIVENESS OF THE DAMAGES TO ALL VEHICLES INVOLVED?

ONLY My Car. Front Right and Back Rim & Body (Right)

WERE YOU OR YOUR PASSENGER/S INJURED? IF INJURED, WHICH HOSPITAL? WERE YOU TAKEN TO THE TRAFFIC POLICE FOR INVESTIGATION?

NOPE

  
NAME: TAN PENG SENG

I AFFIRMED THE ABOVE INFORMATION IS GIVEN TO MY BEST KNOWLEDGE

## UNDERTAKING

I, TAN PENG SENG, (NRIC No. S7346798E), hereby confirm that the Singapore Accident Statement lodged by me on 14 Sept 2021 at 1000 hours pertaining to the accident involving motor car Reg. No: SKS1039C, in which I was the driver are true and accurate to the best of my knowledge, information and belief.

I acknowledge that my insurers are not liable under the contract of insurance if there is a breach of policy terms and conditions.

In the event that an unrelated/unreported third party property or injury claim arises or there is evidence emerges that there is a breach of policy terms and conditions, I irrevocably undertake to absolve my insurer from all liability under the contract of insurance and I undertake to re-pay any sums paid by my insurers pursuant to the contract of insurance upon receipt of written demand by my insurers.

Signature

:



Name of Insured / Driver

:

TAN PENG SENG

Nric No.

:

S7346798E

Date

:

14 SEPT 2021

Signature

:



Name of Policyholder

:

TAN PENG SENG

Nric No.

:

S7346798E

Date

:

14 SEPT 2021

Enquiry  
Motoring

# PARF/COE Rebate for Registered Vehicle

## Owner Particulars

ID Type:

Singapore NRIC

ID:

798E

## Vehicle Details

Vehicle No.:

SKS1039C

Vehicle to be Exported:

No

Intended Deregistration Date:

14 Sep 2020

Vehicle Make:

MITSUBISHI

Vehicle Model:

OUTLANDER 2.4 CVT ABS D/AIRBAG AWD S/R

Primary Colour:

Grey

Manufacturing Year:

2014

Engine No.:

4B12PG7136

Chassis No.:

JMYXTGF3WFZ001657

Maximum Power Output:

123.0 kW (164 bhp)

Open Market Value:

\$17,866.00

Original Registration Date:

25 Mar 2015

First Registration Date:

25 Mar 2015

Transfer Count:

0

Actual ARF Paid:

\$17,866.00

## Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

24 Mar 2025

PARF Rebate Amount:

\$12,506.00

## Intended COE Rebate Details

COE Expiry Date:

24 Mar 2025

COE Category:

E - Open Category

COE Period(Years):

10

QP Paid:

\$73,990.00

COE Rebate Amount:

\$33,494.00

Total Rebate Amount:

\$46,000.00

The information contained herein is correct as at 14 Sep 2020

OK





Merimen e-Claims



Used 2015 Mitsubishi Outlander



PARF/COE Reb

gcar mart.com/used\_cars/info.php?ID=915255&amp;DL=3133

## ► Mitsubishi Outlander 2.4A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

## CAR BUYERS

CLUB

BY CAR BUYERS AUTOMOTIVE PTE LTD

Price \$62,800

Depreciation ⓘ \$10,190 /yr  
View models with similar depreReg Date 26-Nov-2015  
(5yrs 2mths 11days COE left)

Mileage 73,000 km (15.2k /yr)

Manufactured ⓘ 2015

Road Tax ⓘ \$1,636 /yr

Transmission Auto

Dereg Value ⓘ \$45,889 as of today (change)

OMV ⓘ \$19,606

COE ⓘ \$61,300

ARF ⓘ \$19,606

Engine Cap 2,360 cc

Power 123.0 kW (164 bhp)

Curb Weight ⓘ 1,530 kg

No. of Owners ⓘ 1

Type of Vehicle SUV

## Features

Refined Power Through It's 2.4L Engine Combined With Huge Cabin Space Makes The Outlander The Most Value For Money Large 7-Seater SUV In It's Class! View specs of the Mitsubishi Outlander (2014-2015)

STORY