

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR:

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315





NTUC INCOME INSURANCE CO-OPERATIVE LTD				NS/INC20009804/Qsf3s2		
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	01-10-2020 INC4		
1.		Policy Particulars	:- THIRI	D PARTY CLAIN		
	Insured Veh.	SMG 4560H	т —	nspected	SMB 3C	
	Policy No.	5109921641-01	+	 age (\$)	0.00	
	Claim No.	MT/1102188-002	Exces		0.00	
	Assign From		Assign	n Date	09/09/2020	
2. Vehicle Particulars & Condition						
	Make & Model	MERCEDES BENZ OC500	c.c		11967	
	Engine No.	HIDDEN	Year o	f Reg.	2008	
	Chassis No.	WEB63442021000060	Coloui	r	GREEN	
	Odometer	96294	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	FIRENZ	ZA	6 mm	
	L/H Front Tyre	275/70 R22.5	FIRENZ	ZA	6 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FIRENZ	ZA	6/6 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FIRENZ	ZA	6/6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.					
	DAMAGES SEE DETAILS.					
5.		Genera	Inform	ation		
	Accident Date	02/09/2020	Inspec	tion Date	09/09/2020	
	Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD				
		60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

Estimate Days of Repair

4 Working Days