


ASS. REC. BY: John REF: CC3/A1420009809/R16A3 8722

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SME 7751P
at Workshop m/s Volkswagen
of 247, ALEXANDRA RD
Insured: ALH
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 93K
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SME 7751P Yr Regn: 2018 10CT
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: VOLKSWAGEN PASSAT 381-8TFSI c.c 1798
Colour: BLUE A/C: Insured / Std / NI / NA
Sp. Reading: 36764 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WVWZZZ3CZKE012357
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Order / Jammed / Leaked / Burnt or _____
Brake: Order / Jammed / Leaked / Burnt or _____
Modi: Nil / S/Rim / STD A/Rim or _____
Tyre Size: F: 215/55R17
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____
Front: _____ Rear: _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 13/09/2020 D.O.I. 15/09/2020
Survey held at 247, ALEXANDRA RD
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or _____
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / I.B.A. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS. SI _____

Photos _____

Others _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	872Z
Vehicle No.:	SME7751P
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Sep 2020
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	PASSAT B8 1.8 TFSI AT 3G24JZ
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	CJS296730
Chassis No.:	WWZZZ3CZKE012351
Maximum Power Output:	132.0 kW (177 bhp)
Open Market Value:	\$26,305.00
Original Registration Date:	16 Oct 2018
First Registration Date:	16 Oct 2018
Transfer Count:	0
Actual ARF Paid:	\$28,827.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Oct 2028
PARF Rebate Amount:	\$21,620.00
COE Expiry Date:	15 Oct 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,307.00
COE Rebate Amount:	\$25,293.00
Total Rebate Amount:	\$46,913.00

The information contained herein is correct as at 16 Sep 2020

OK

Blue



Merimen e-Claims



Used 2018 Volkswagen Passat 1.8 TSI



PARF/COE F

art.com/used_cars/info.php?ID=917594&DL=2425

► Volkswagen Passat 1.8A TSI

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$94,500

Depreciation ⓘ

\$9,830 /yr

View models with similar depre

Reg Date

09-Nov-2018

(8yrs 1mth 23days COE left)

Mileage

43,234 km (23.3k /yr)

Manufactured ⓘ

2018

Road Tax ⓘ

\$976 /yr

Transmission

Auto

Dereg Value ⓘ

\$47,138 as of today (change)

OMV ⓘ

\$26,305

COE ⓘ

\$31,307

ARF ⓘ

\$28,827

Engine Cap

1,798 cc

Power

132.0 kW (177 bhp)

Curb Weight ⓘ

1,480 kg

No. of Owners ⓘ

1

Type of Vehicle

Luxury Sedan

Features

Original Condition. View specs of the Volkswagen Passat (2005-2011)

Accessories

Factory Fitted Interior.

Description

10
Dee With Hassle Free One Owner Only Superb Well Maintenance The Cheapest And Lowest
100% Guaranteed White Spacious Passat B8 1.8 TFSI In The Market. Fully Maintained And Well