

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Ave 2, #01-17
Singapore 417921
Tel No. : +65 6744 0510 / 6842 0051 Fax No. : +65 6741 0510
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Our Ref: **EZ 3113 S**
Your ref: **GBH 3634 K**

14 September 2020

LONPAC INSURANCE BHD
100 BEACH ROAD
#19-00 SHAW TOWER
SINGAPORE 189702
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : KHOO LENG HOW
VEHICLE NUMBER : EZ 3113 S
YOUR INSURED VEHICLE NUMBER : GBH 3634 K
ACCIDENT ON 13 Sept 2020 ALONG JOO SENG ROAD, INFRONT OF 134 JOO SENG RD
AT ABOUT 17:05 HOURS

We refer to your email / fax dated **14 Sept 2020** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **Steve Chen Tsue Yee** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

TWINCAR AUTOMOTIVE PTE LTD
Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-17
Singapore 417921
6842 0051 / 6744 0510 (Melody)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
TwinCar Automotive Pte Ltd

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!

Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: