Kaki Bukit Autohub, 2 Kaki Bukit Ave 2, #01-18 Singapore 417921

Tel No.: +65 6842 0051 / 6744 0510 Fax No.: +65 6741 0510

Company Reg. No.: 200616038C GST Registration No.: 200616038C

Our Ref:

**SLH 5925 P** 

Your ref:

SHD 3134 L

14 September 2020

## INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711 Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT: GRAB RENTALS PTE LTD

**VEHICLE NUMBER: SLH 5925 P** 

YOUR INSURED VEHICLE NUMBER: SHD 3134 L

ACCIDENT ON 12 Sept 2020 ALONG JUNC OF NEWTON CIRCUS / DUNEARN RD

AT ABOUT 00:15 HOURS

We refer to your email/fax dated **14 Sept 2020** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

## N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub 2 Kaki Bukit Avenue 2 #01-18 Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



(Name & Signature):

inspection. Thank you! Appointed surveyor:

FOR SURVEYOR:

Date & Time of Inspection:

Please initial here after completion of pre-repair

N-51 AUTOMOTIVE PTE LTD