

ASS. REC. BY:

REF:

Smo / 2000 9873/Kt

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lump Sum:

1.13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMK 79916

Yr Regn:

04, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Nante c.c 1591

Colour

M.D. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

8004

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM11D 841CMK 4 880779

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hunhe

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

12/9/20

D.O.I.

15/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Q 674

agreed and accepted the finalized amount @ P/P \$800.32 (before GST) &amp; 2 repair pair

RED:17863.96; 95%

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$



# SMK7991G

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)  
60 Jalan Lam Huat #03 - 35/36, Singapore (737869)  
Tel : 6358 3031 | Fax No : 6694 4929

## ACCIDENT REPAIR ESTIMATE

TP INSURER : SOMPO  
OWN INSURER : AXA  
CLAIM TYPE : TP  
Date of Accident : 12/9/2020

Vehicle Reg. No. : SMK7991G  
Vehicle Reg. Date: 25-Apr-2019  
Make / Model : HYUNDAI AD AVANTE 1.6  
Engine No. : G4FGKU112303  
Chassis No. : KMHD841CMKU880779

## COST OF CLAIMS

Parts Cost / List Items :	\$	13,135.32
Plus/Less <u>20%</u>	\$	2,627.06
Total Cost / List :	\$	10,508.26
Special Nett Items :	\$	1,175.00
Total Parts Amount :	\$	11,683.26
Total Labour Amount :	\$	5,760.00
Gross Total :	\$	17,443.26
GST % : <u>7%</u>	\$	1,221.03
Nett Amount :	\$	18,664.28

## Surveyor Name and Company :

Date of survey : \_\_\_\_\_  
Part by Part / Lump Sum : \_\_\_\_\_ days  
Resurvey Before Paint / After Paint  
Authorize/Not Authorize/Without Prejudice  
Email : \_\_\_\_\_  
Fax No : \_\_\_\_\_  
HP No : \_\_\_\_\_

This claim is handled by : PAULO



Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Tel : 6358 3031 | Fax No : 6694 4929

Not Authored  
86741

2 day

Vehicle Reg. No. : **SMK7991G**  
Vehicle Reg. Date: **25/4/2019**  
Make / Model : **HYUNDAI AD AVANTE 1.6 GLS (A) ELITE**  
Engine No. : **G4FGKU112303**  
Chassis No. : **KMHD841CMKU880779**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	REAR BUMPER	N	\$ 469.40		X
2	2	REAR BUMPER RETAINER LH/RH	Sm	\$ 62.00		X
3	2	REAR BUMPER REFLECTOR LH/RH	Sm	\$ 97.00		X
4	1	REAR BUMPER REINFORCEMENT	N	\$ 460.00		X
5	2	REAR BUMPER STAY	Sm	\$ 157.20		X
6	1	REAR BUMPER LOWER SKIRT	Sm	\$ 353.00		X
7	2	REAR BUMPER UNDER COVER LH/RH	Sm	\$ 119.52		X
8	1	ANTENNA SENSOR	Sm	\$ 167.50		X
9	1	REAR NUMBER PLATE BASE	Sm	\$ 42.10		X
10	5	REAR BUMPER REINFORCEMENT BRACKET	N	\$ 91.20		X
11	1	REAR BOOT	N	\$ 1,782.40		X
12	1	REAR BOOT LOCK	N	\$ 118.20		X
13	1	REAR BOOT LOCK CATCH	N	\$ 31.00		X
14	1	REAR BOOT WEATHERSTRIP	Sm	\$ 141.00		X
15	1	REAR BOOT EMBLEM - LOGO with lock	Sm	\$ 39.00		X
16	1	REAR BOOT EMBLEM - AVANTE	Sm	\$ 34.00		X
17	1	REAR BOOT EMBLEM - S	Sm	\$ 32.00		X
18	1	REAR BOOT INNER TRIM	Sm	\$ 156.30		X
19	1SET	REAR BOOR INNER TRIM CLIPS	N	\$ 50.00		X
20	2	REAR BOOT LAMP LH/RH	Sm	\$ 604.80		X
21	2	TAIL LAMP LH/RH	Sm	\$ 876.80		X
22	2	TAIL LAMP CLIPS	N	\$ 30.00		X
23	2	TAIL LAMP PANEL LH/RH	N	\$ 390.20		X
24	1	REAR END PANEL	N	\$ 454.60		X
25	1	REAR END PANEL TOP GARNISH	Sm	\$ 69.80		X
26	1SET	REAR END PANEL TOP GARNISH CLIPS	N	\$ 50.00		X
27	1	SPARE TYRE PANEL	N	\$ 713.00		X
28	1	SPARE TYRE PANEL TOP BOARD	Sm	\$ 259.10		X
29	2	REAR FENDER LH/RH	N	\$ 3,537.00		X
30	2	REAR FENDER INNER SHIELD (REAR)	Sm	\$ 120.20		X
31	2	REAR FENDER INNER SHIELD (FRONT)	Sm	\$ 142.40		X
32	2SET	REAR FENDER INNER SHIELD CLIPS	N	\$ 60.00		X
33	2	REAR FENDER LOWER TRIM BOARD	Sm	\$ 439.60		X
34	2SET	REAR FENDER LOWER TRIM BOARD CLIPS	N	\$ 60.00		X
35	2	REAR NUMBER PLATE LAMP ASSY	Sm	\$ 79.60		X
36	1	EXHAUST MOUNTING	Sm	\$ 50.00		X
37	1	EXHAUST HEAT SHIELD	N	\$ 97.00		X
38	1	EXHAUST PIPE (REAR)	N	\$ 698.40		X
39	1	REVERSE SENSOR	Sm		\$ 350.00	X
40	2	TAIL LAMP PAD LH/RH	Sm		\$ 80.00	X

196.9

**Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)**  
 60 Jalan Lam Huat #03 - 35/36, Singapore (737869)  
 Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SMK7991G**  
 Vehicle Reg. Date: **25/4/2019**  
 Make / Model : **HYUNDAI AD AVANTE 1.6 GLS (A) ELITE**  
 Engine No. : **G4FGKU112303**  
 Chassis No. : **KMHD841CMKU880779**

PAGE 2

**Estimates on Parts**

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	REAR END PANEL SEALANT		nn	\$ 80.00	X
42	1	REVERSE CAMERA		nn	\$ 500.00	X
43	1	SPARE TYRE PANEL SEALANT		nn	\$ 80.00	X
44	1	REAR NUMBER PLATE WITH FRAME		nn	\$ 55.00	X
45	1	WEEKEND SEAL		nn	\$ 30.00	X
46	0	0				
47	0	0				
48	0	0				
49	0	0				
50	0	0				
51	0	0				
52	0	0				
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

\$ 745.00 \$ -



60 Jalan Lam Huat #03 - 35/36, Singapore (737869)

Vehicle Reg. No. :	<b>SMK7991G</b>
Vehicle Date:	<b>25/4/2019</b>
Make / Model :	<b>HYUNDAI AD AVANTE 1.6 GLS (A</b>
Engine No. :	<b>G4FGKU112303</b>
Chassis No. :	<b>KMHD841CMKU880779</b>

### Estimates on Labour

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed \$
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/09/2020 17:14
Date Of Accident	12/09/2020 11:35
Exact Location Of Accident	NORTHPOINT CITY NORTH WING CAR PARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMK7991G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ONG CHEE KHOON
NRIC No	SXXXX752F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98269403
Alternative Phone No	OFFICE-98269403

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPAP2281744
Cover Note Number	

### Driver

Name of Driver	ONG KANG RUI JAMES
NRIC No	SXXXX706A
Date Of Birth	18/07/1992
Occupation	INDOOR
Date Of Driving Pass	27/01/2015
Driving Experience	5 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81384808
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	APT BLK 241 BUKIT PANJANG RING ROAD #05-149
Postcode	670241
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - SON
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLEASE REFER TO ATTACHMENT.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF6859U
Vehicle Make/Model/Colour	NISSAN NV200
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	CAMACHO OLIVER CUTAMORA
NRIC/Passport Number	
Contact Number	68623830
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 1135, 12/05/20, I was travelling towards the car park at Northpoint North wing.  
At that time, I was queuing to enter the car park.  
Then, I felt a jerk as the van had knock onto the back of my car as a result of his tail gating (GBF 68594)

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:



PAULO

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

31ARAC SketchPlanForm\_V3