

ASS. REC. BY:

REF: CS3/MSG20009876/Qqf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): CRYSTAL LEE of MSIG Date/Time: 15/9/2020 1:15 PM

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FBH 8656P Insured: SLK 5108Rat Workshop m/s Multi-Storey Carpark Tel: 8454 5676of Blk 762A Choa Chu Kang North 5Policy No: 29141713 Claim No: 624855

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 13/06/20  
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 15-09-20 1.40P.M Person Contacted: ROSLI Vehicle ☒ IN/OUT

| Date/Time | Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate |
|-----------|---------------------------------------------------------------------|
|           | FBH 8656P- <input checked="" type="checkbox"/>                      |
|           | SLQ 5186R- <input checked="" type="checkbox"/>                      |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |
|           |                                                                     |