





SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/09/2020

User ID : CatherineLee

Section A - Accident Details	
Registration Number	SMB1415R
Case Reference Number	BUS/09/20/1007
Registration Date	6/1/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Ooi Lay Tin
Type of Accident	Side Swipe
Accident Date and Time	8/9/2020 11:56 AM
Accident Reported Date and Time	8/9/2020 1:45 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108124
Special Instruction to ARC,if any	SMB1415R-RIGHT CENTER PORTION SLQ5907U (TP) INSURED WITH
Prepared Date and Time	11/9/2020 11:18 AM
Chassis Number	WMAA22ZZ3D7001994
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,590.00	\$1,060.00
Total Spray Cost	\$1,388.00	\$1,048.00
Total Spare Part Cost	\$160.00	\$160.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,138.00	\$2,268.00
Lump Sum Total	\$3,150.00	\$2,250.00
Number of Repair Days	6.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	11/09/2020 11:25 AM	11/09/2020 3:54 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/09/2020

User ID : CatherineLee

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$1,590.00				\$1,060.00 ✓		
Total Labour			\$1,590.00				\$1,060.00		
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$1,388.00				\$1,048.00 ✓		
Total Spray Painting & Panel Beating			\$1,388.00				\$1,048.00		
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009987	BODY RH	A01001-CW568	PANEL,SIDE:R6,FOR MAN A22 BUS	1.00	\$1,776.80	100.00	\$0.00	Repair	Repair XR
6009988	BODY RH	A01001-CW567	PANEL,SIDE:R7,FOR MAN A22 BUS	1.00	\$885.50	100.00	\$0.00	Repair	Repair XR
6009989	BODY RH	A01001-CW566	PANEL,SIDE:R8,FOR MAN A22 BUS	1.00	\$330.70	100.00	\$0.00	Repair	Repair XR
6009990	BODY RH	A01001-CW565	PANEL,SIDE:R9 WITH FRAME,FOR MAN A22 BUS	1.00	\$710.70	100.00	\$0.00	Repair	Repair XR
6009991	BODY RH	4000F06-ACCE4526	PANEL,SIDE:R10,FOR MAN A22 BUS	1.00	\$192.70	100.00	\$0.00	Repair	Repair XR
6010330			WHEEL ARCH TRIM	1.00	\$124.20	100.00	\$0.00	Repair	Repair XR
6010062	Body	F01001-CW273	COVER:REAR TAIL LAMP,RH,FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Repair XR
			STICKER SMRT	1.00	\$200.00	0.00	\$200.00	Replace	Replace / Nec
Total					\$5,195.30		\$200.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

4/5
\$ 2,250
3days

260
- 20%
160
1,060
1,048
2,268