

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133 62717433 FAX:62745715

ESTIMATE REPAIR

Pg1

AIG Asia Pacific Insurance Pte Ltd

Date: 15.9.2020

Owner's Name : Po San Transportation Pte Ltd

Vehicle No : XE2086D

Claim Type: Third Party Claim

Vehicle Make & Model : UD Trucks

Chassis No: JNCM1F1AGU009456

Registration Date : 23 Aug 2016 (YOM 2016) COE Expiry Date 22 Aug 2026

DOA: 12.9.2020

No	Description	Unit	(\$)
	Special Nett For Trailer Repair TRA2759C (40ft)		
1	REAR BUMPER (4 x 4 x 8ft x 4.5mm) ✓ DD	1	\$ 240.00
2	BUMPER TOP SUPPORT BRACKET ✓ BT	2	\$ 230.00
3	SUPPORT BRACKET FLAT PLATE ✓ BT	2	\$ 160.00
	Labour		
1	Equipments & Labour Charge For Cutting, Welding, Changing Rear Bumper Damage Parts,Bumper Support & Bumper Flat Damage Parts and Paint Works	1	\$ 500 ✓ 800.00
		Total (A) :	\$ 1,430.00

LKK Auto Consultants hence notify
Steve (LKK)

Total (A) :	\$	1,430.00
-------------	----	----------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date:

Steve (LKK)
Without Prejudice
16/09/20, 11.00 am
Part By Part
Resurvey Before Spray
3 repair days