




PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD		Ref: CS/ASM20009912/Dtf3e2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date: 30-10-2020		
Code: ASM				
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SMQ 8290H	
	Policy No. VCX/P2360036	Coverage (\$)	0.00	
	Claim No. S0M02K2L	Excess (\$)	0.00	
	Assign From PETER WANG	Assign Date	15/09/2020	
2. Vehicle Particulars & Condition				
	Make & Model HONDA SHUTTLE	c.c	1496	
	Engine No. HIDDEN	Year of Reg.	2019	
	Chassis No. GK82100186	Colour	WHITE	
	Odometer 10750 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Front Tyre	185/60 R15	BRIDGESTONE	6 mm
	R/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
	L/H Rear Tyre	185/60 R15	BRIDGESTONE	6 mm
4. Description of Damages				
5. General Information				
	Accident Date 27/03/2020	Inspect Date / Time	18/09/2020 ( 10:30 AM )	
	Survey held at SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711			
5a. Remarks				

Report Ref No. CS/ASM20009912/Dtf3e2

Inspected By

ANG BRYAN TANI

Automotive Assessor / Investigator

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.