

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	LONPAC INSURAN	NCE BHD		Ref:	CS/LPC20009942/Kqf3n2	
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	07/02/2022	
				Code:	LPC2	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLE 1611L	Veh. Inspected	t	SMM 8162R	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/20/20/VP05/023662	Excess (\$)		0.00	
	Assign From	ONG LI LI	Assign Date		16/09/2020	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA VOXY (A)	c.c		1797	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	ZWR800386855	Colour		METALLIC BLACK	
	Odometer	103503 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	APLUS		8 mm	
	L/H Front Tyre	195/65 R15	APLUS		8 mm	
	R/H Rear Tyre	195/65 R15	CONTINENTAL		5 mm	
	L/H Rear Tyre	195/65 R15	CONTINENTAL		5 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT N/S PORTION.					
	DAMAGES SEE DI	DAMAGES SEE DETAILS.				
5.	General Information					
	Accident Date	13/09/2020	Inspection Dat	te	17/09/2020	
	Survey held at	HENG YAP SENG AUTO SERVI	CE			
		160 SIN MING DRIVE #08-13 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days					