

ASS. REC. BY:

REF: MSG- / 20009936 / kv

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP / 24 HRS

Date:

7/25

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

STX 7849C

Yr Regn: 06.10

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy A111S

c.c

1598

Colour

M. Green

A/C:

Insured / Std / NI / NA

Sp. Reading

321813

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NR0537EE106175275

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Nexen

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

15/19/20

D.O.I.

17/9/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 8

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Parking

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

2) 21/10/20-Typist

Report Format: Merimen

Lump Sum H.B. (\$ 8,000)

Kenworth (Ukkk) NOT Authorized
 1/1 Rmg &
 Repairing After Paint
 Today

Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)
 60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
 Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**
 Vehicle Reg. Date: **12/7/2010**
 Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**
 Engine No. : **3Z24998288**
 Chassis No. : **MR053ZEE106175275**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	BONNET	R X			
2	1	BONNET HINGE RH	R X			
3	1	FRONT BUMPER	Sn X			
4	1set	FRONT BUMPER CLIPS	na X			
5	1	FRONT BUMPER RETAINER RH	Sn X			
6	1	FRONT BUMPER SPONGE	Sn X			
7	1	WASHER TANK	Sn X			
8	1	FOG LAMP RH	Sn X			
9	1	FOG LAMP GARNISH RH	Sn X			
10	1	FRONT FENDER RH	Ry			✓
11	1	FRONT FENDER EMBLEM RH	na			✓
12	1	FRONT FENDER INNER SHIELD RH	Di			✓
13	1set	FRONT FENDER INNER SHIELD CLIPS	na			✓
14	1	FRONT FENDER APRON RH	R X			
15	1	FRONT FENDER GARNISH RH	Sn X			
16	1	FRONT RIM RH	na		\$ 400.00	✓
17	1	FRONT TYRE RH			\$ 300.00	?
18	1	FRONT SHOCK ABSORBER RH				?
19	1	FRONT SHOCK ABSORBER MOUNTING RH				?
20	1	FRONT STABILIZER LINK RH	Sn			X
21	1	FRONT LOWER ARM RH				?
22	1	FRONT LOWER ARM BALL JOINT RH	Sn			X
23	1	FRONT WHEEL HUB RH				?
24	1	FRONT KNUCKLE ARM RH				?
25	1	FRONT WHEEL BEARING RH				?
26	1	ROCKER PANEL RH	R			X
27	1	FRONT WINDSCREEN PILLAR RH	R			X
28	1	FRONT DOOR RH	Ry			✓
29	1	FRONT DOOR OUTER GARNISH RH	Sn			X
30	1	FRONT DOOR WEATHERSTRIP RH				?
31	1	FRONT DOOR LOCK	R			X
32	1	FRONT DOOR TOP HINGE RH	Di			✓
33	1	FRONT DOOR LOWER HINGE RH	Ry			✓
34	1	FRONT DOOR CHECKER RH	Sn			X
35	1	FRONT DOOR STRIKER RH	R			X
36	1	FRONT DOOR POWER WINDOW MOTOR RH				?
37	1	FRONT DOOR OUTER HANDLE RH	Di			✓
38	1	FRONT DOOR INNERHANDLE RH	Sn			X
39	1	FRONT DOOR INNER TRIMBOARD RH	Sn			X
40	1	FRONT DOOR OUTER MOULDING RH	na			X

HEAD LAMP RH
 ROCKER PANEL GARNISH RH Di

?

Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SJX7849C**
Vehicle Reg. Date: **12/7/2010**
Make / Model : **TOYOTA COROLLA ALTIS 1.6 AUTO**
Engine No. : **3ZZ4998288**
Chassis No. : **MR053ZEE106175275**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	FRONT DOOR UPPER MOULDING RH <i>Sm</i>				X
42	1	FRONT DOOR GLASS RH <i>Sm</i>				X
43	1	SIDE MIRROR ASSY RH <i>o M Sm</i>				X
44	1	CENTER PILLAR RH <i>R</i>				X
45	1	REAR DOOR RH <i>R</i>				X
46	1	REAR DOOR OUTER GARNISH RH <i>Sm</i>				X
47	1	REAR DOOR WEATHERSTRIP RH <i>Sm</i>				X
48	1	REAR DOOR LOCK <i>R</i>				X
49	1	REAR DOOR TOP HINGE RH <i>R</i>				X
50	1	REAR DOOR LOWER HINGE RH <i>R</i>				X
51	1	REAR DOOR CHECKER RH <i>Sm</i>				X
52	1	REAR DOOR STRIKER RH <i>R</i>				X
53	1	REAR DOOR POWER WINDOW MOTOR RH <i>Sm</i>				X
54	1	REAR DOOR OUTER HANDLE RH <i>Sm</i>				X
55	1	REAR DOOR INNERHANDLE RH <i>Sm</i>				X
56	1	REAR DOOR INNER TRIMBOARD RH <i>Sm</i>				X
57	1	REAR DOOR OUTER MOULDING RH <i>Sm</i>				X
58	1	REAR DOOR UPPER MOULDING RH <i>Sm</i>				X
59	1	REAR DOOR GLASS RH <i>Sm</i>				X
60	1	REAR FENDER RH <i>R</i>				X
61	1	REAR FENDER INNER SHIELD RH <i>Sm</i>				X
62	1set	REAR FENDER INNER SHIELD CLIPS <i>Nu</i>				X
63	1	REAR RIM RH <i>Od Fax</i>			\$ 400.00	X
64	1	REAR TYRE RH <i>Sm</i>			\$ 300.00	X
65	1	REAR SHOCK ABSORBER RH <i>Sm</i>				X
66	1	REAR WHEEL HUB ASSY RH <i>SLC</i>				X
67	1	REAR BEAM ASSY <i>Ng</i>				X
68	1	REAR BUMPER <i>Sm</i>				X
69	1set	REAR BUMPER CLIPS <i>Nu</i>				X
70	1	REAR BUMPER RETAINER <i>Sm</i>				X
71	1	DASH BOARD COVER <i>Sm</i>				X
72	1	ROCKER PANEL SEALANT <i>Nu</i>			\$ 100.00	X
73	1	REAR FENDER SEALANT <i>Nu</i>			\$ 100.00	X
74	1	SUNDRIES			\$ 60.00	7
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 201606023C)
60 Jalan Lam Huat # 03-35/36 Carros Centre Singapore 737869
Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. :	SJX7849C
Vehicle Reg. Date:	12/7/2010
Make / Model :	TOYOTA COROLLA ALTIS 1.6 AUT
Engine No. :	3ZZ4998288
Chassis No. :	MR053ZEE106175275

PAGE 1

Estimates on Labour

[illegible]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/09/2020 14:06
Date Of Accident	15/09/2020 22:00
Exact Location Of Accident	LORONG 6 TOA PAYOH TOWARDS LORONG 1 TOA PAYOH
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJX7849C
Insured/Policyholder	
Name Of Registered Owner	POON SIEW KWONG (PAN ZHAOGUANG)
NRIC No	SXXXX676J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94524774
Alternative Phone No	OTHERS-94524774

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100223617-02 (DRIVO CLASSIC)
Cover Note Number	

Driver

Name of Driver	POON SIEW KWONG (PAN ZHAOGUANG)
NRIC No	SXXXX676J
Date Of Birth	03/09/1973
Occupation	OUTDOOR
Date Of Driving Pass	19/12/1991
Driving Experience	28 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94524774
Fax Number	
Contact Number	OTHERS-94524774
Email Address	NOEMAIL

Address APT BLK 486 SEGAR ROAD #10-526
Postcode 670486
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OWNER
Vehicle Registration Number of Driver's Own Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : KIM TAE IN
GENDER: : MALE

Passenger 2 NAME: : GOH MIN TAT LESLIE
GENDER: : MALE

Passenger 3 NAME: : LUCIEN GOH HAN MING
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO STATEMENT ATTACH

Attachment(s)

Are accident photos available for attachment? YES


Was there any video captured by Car Camera? YES

Remarks/ Reasons: CANNOT BE UPLOADED

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGR5244C
Vehicle Make/Model/Colour TOYOTA RUSH /BLACK
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 15/9/2020 at about 10pm, I was driving along Lorong 6 Toa Payoh towards Lorong 1 Toa Payoh. I was driving in the middle lane at a constant speed limit. From far, traffic light was green and I continue my drive. As I was very near to the stop line, the traffic light turn amber so I proceed straight on. Suddenly Veh B from the opposite direction that was making a right turn did not stop and speed up. I then sound my horn and tried to move to the left to avoid the collision but still Veh B hit onto my veh. I have 3 passengers inside my veh when this accident happen. I also have a in-car camera.

Passenger 1: Kim Jee in

Passenger 2: Goh Min tat Leslie

Passenger 3: Lucien Goh Han Ming.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature

Date & Time: 16/9/2020
2pm

[Signature]

Driver's Signature
(If driver is not the policyholder)

Date & Time: 16/9/2020
2pm

IDAC BUREAU (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.: