

(08/11/13) - wef

ASS. REC. BY: Marcus

REF: CCG/A1620009963/Up3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SJT1259R
at Workshop m/s Super 2nd loan
of _____
Insured: SLE 5137M
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £60
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

8766
Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SJT1259R Yr Regn: 9.09
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Mer Benz E250 c.c. 1796
Colour: Grey A/C: Insured / Std / NI / NA
Sp. Reading: 180097 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: WDD2120472A074010
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: _____ R: 225/50ZR17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or X speed
Front _____ Rear _____
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 15/9/20 D.O.I. 17/9/20
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
015 Rec
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

we 23-9-2029 LTA 3420

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee: _____

2)

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI

Transportation: _____

☐ : Interview (\$ _____) Photos

☐ : Tech. Invs (\$ _____) Others

☐ : Weekend (\$ _____)

Report Format : _____

Lump Sum / I.B.I. (\$) _____

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	876G
Vehicle Details	
Vehicle No.:	SJT1259R
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Sep 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E 250CGI
Primary Colour:	Grey
Manufacturing Year:	2009
Engine No.:	27186030003078
Chassis No.:	WDD2120472A074010
Maximum Power Output:	150.0 kW (201 bhp)
Open Market Value:	\$53,009.00
Original Registration Date:	24 Sep 2009
First Registration Date:	24 Sep 2009
Transfer Count:	3
Actual ARF Paid:	\$53,009.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	23 Sep 2029
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
PQP Paid:	\$37,941.00
COE Rebate Amount:	\$34,210.00
Total Rebate Amount:	\$34,210.00

The information contained herein is correct as at 17 Sep 2020

OK