

Certification for Bus Repairs

CBR REF NO. : HG20203873Depot : HGReport No.: W35082020BUS VEHICLE NO. : SG1773JDriver's Co no. & Name : 17047 Krishnamoorthy A/L DoraisamyAccident Date : 04/09/2020Date in : 05/09/2020Date Out : 24/09/2020

Yr Of Reg	Make / Model	Chassis No.
2018	MAN A22 EU6, SD, AC, 2 Axle	WMAA22ZZ8JF006951

Stock Code	Description	Quantity	Total Material cost (S\$)
		0	\$0.00
30730009	BOSTICK SEALANT 7008 ✓ NEC	2	\$31.00
30122030	FLAP DOOR FL~GL+FR~GR;0.25X0.3M ✓ CUT	1	\$79.00
30400320	SIDE PANEL R8.E6 ✓ CUT	1	\$229.00
TOTAL FOR PARTS			S\$ 339.00
S/N	Labour / Spray Painting / Contractor Cost		Amount
1	(2) Workshop Labour	×	S\$ 192.00
2	Contractor's repair charges	✓	S\$ 1200.00
TOTAL LABOUR / SPRAY PAINTING / CONTRACTOR COST			S\$ 1392.00
Repair cost of Advertisement / Livery			S\$ -
TOTAL DAMAGE			S\$ 1731.00

Certification for Bus Repairs

CBR REF NO. : HG20203873Depot : HGReport No.: W35082020BUS VEHICLE NO. : SG1773JDriver's Co no. & Name : 17047 Krishnamoorthy A/L DoraisamyAccident Date : 04/09/2020Date in : 05/09/2020Date Out : 24/09/2020

Yr Of Reg	Make / Model	Chassis No.
2018	MAN A22 EU6, SD, AC, 2 Axle	WMAA22ZZ8JF006951
TOTAL DAMAGE		S\$ 1731.00
Overheads		S\$ 519.30
Towing Charges		S\$ -
Repair Period : 2 day(s)	Loss of Use	S\$ 712.58
TOTAL LOSS		S\$ 2962.88

Prepared By : Zakaria Bin AhmadDate : 01/10/2020Approved By
Workshop Mgr : Aw Boon HuanDate : 06/10/2020

	Survey Fee	refer to Group Claims
TOTAL DUE		S\$ 2962.88

Acknowledged By
Depot Safety : Ang Kiat SiangDate : 07/10/2020

* This is computer generated document and does not require signature