ASS. Filed By: GQ | REF: CS3/AIG20009975/Gcf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s SBS TRANSIT

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SG 1773J Yr Regn: 19 Jul/2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: MAN A22 c.c 10518

Colour GREEN A/C: Insured / Std / NI / NA

Sp.Reading 101853 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WMAA22ZZ8JF006951 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 275/70R22.5

R: 275/70R22.5

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	17-09-2020

Survey held at W/S 1pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Yes/No BI Involved — W/S not sure
	Estimate give later
	Submit final fig $1,539.00 ; 2 days (Red $192.00 ; 11%)

Date/Time, File Pass to? ☐ : Preli. Report

1) ☑ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: -

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weeland ($)

Report Format: TP

Lump Sum / I.B.I.: IBI $1,539.00

Survey Fee:

Transportation: S + RS. SI

Photos

Other:

TOTAL