

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R				
Affiliated to Federation Internationale Des Experts En Automobile					
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI20010080/Bqf3e2		
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date: 18-11-2020		
			Code: AGI		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SLG 3614E	Veh. Inspected	SMT 4192T	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	C10007365	Excess (\$)	0.00	
	Assign From	IVY RATILLA	Assign Date	21/09/2020	
2. Vehicle Particulars & Condition					
	Make & Model	B.M.W 316I	c.c	1598	
	Engine No.	HIDDEN	Year of Reg.	2013	
	Chassis No.	WBA3A12020J721294	Colour	WHITE	
	Odometer	117176	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	225/50 ZR17	MICHELIN	6 mm	
	L/H Front Tyre	225/50 ZR17	MICHELIN	6 mm	
	R/H Rear Tyre	225/50 ZR17	MICHELIN	6 mm	
	L/H Rear Tyre	225/50 ZR17	MICHELIN	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	19/09/2020	Inspection Date	21/09/2020	
	Survey held at	TEAM AUTOPRO PTE LTD			
		160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Days of Repair			

**6 Working Days** 

ESTIMATED NORMAL PERIOD FOR REPAIR: