

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 21.09.2020
Time: 15:09:55
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305423728
REGN NO : SH 8080Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 11.01.2017
DATE/TIME IN : 21.09.2020 09:10
ACCIDENT DATE : 21.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de ✓
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	net ✓
0003	04-01-0103-0638-G	I40VC BRKT ASSY-FR BPR UP	1	22.40	20.00	17.92	?
0004	04-01-0103-0640-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	?
0005	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	net ✓

SUB-TOTAL : 986.96

JOB NATURE

0000	20-05	FRT FENDER ADVERTISMENT LOGO RH				100.00	net ✓
0001	L	PANEL BEATING		500.00		420	
0002	23-502	SPRAYPAINT ON AFFECTED AREA				450.00	400
0003	20-00	TUFF COAT ON AFFECTED PARTS.				50.00	✓
0004	20-08	ADJUST FRONT WHEEL ALIGNMENT				80.00	✓

SUB-TOTAL : 1,180.00

Tanphir 92495749
UP 21/7/20 @ Spn
1/5 Resurvey after repair
tanphir@thant.com
2-5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969 24 Seroko Loop Singapore 758156
383 Sin Ming Drive Singapore 575717 7 Suncor Kidul Way Singapore 728791
45 Pandan Road Singapore 309286 501 Yishun Industrial Park A Singapore 768773
420 12 Road Singapore 6143

Date/Time: 21.09.2020 13:59

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305423728

COMER ,
AS " COMFORT TRANSPORTATION PTE LTD
COMER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)
(P)


COUNT CARD NO.

REGN NO. SH 8080Z	MILEAGE
MAKE : HYUNDAI	FUEL E.....1/2.....F
MODEL I-40	DATE/TIME IN 21.09.2020 09:10
YR OF MANU. 11.01.2017	TARGET DATE
CHASSIS CODE KMHLB41UMHU098179	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 21.09.2020
NATURE: 3P 21.09.2020

S/NO LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

No.: SH 8080Z

LKE

Exit Pass

Vehicle No.:

SH 8080Z

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard