CS/MSG20010100/Qtf3

EC4/FC120010031/Quas

ASS. REC. BY: Sun Pin ASSIGNMENT SKZ9330× Yr Regn: 16/62/2016 Veh No: Date: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / **Estimated Cost:** Truck / Trailer or OD / TP / WS / TP RES / OD RES / EVA / INV / MV c.c 1598 Toyota Corolla Altis Make: To Inspect Vehicle No: Insured / Std / NI / NA at Workshop m/s Colour Silver 223099 T/Radio: Insured / Std / NI / NA Sp.Reading Insured: Eng/No: MR053 REH 104539903 C/No: Policy No. Gen. Cond: Good / Fall / Poor / Burnt Claims No. Steering: Inorder / Jammed / Leaked / Burnt or Sum Insured: Excess: Brake: Inorder / Jammed / Leaked / Burnt or (Client's Record) Modi: Nil /S/Rim / STD A/Rim or Make of Veh: 205/55 R16 Tyre Size: 205/55 R16 (Policy Condition) BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI / Remark: The veh had commenced its repair at the time of inspection. TOYO / YOKO or Bal. or Market Value: Front Rear R/Bal. R/Bal. Consistent?: Yes or No mm IDAC Accident Rport: L/Bal. Consistent?: Yes or No mm GIA / PR Seen: D.O.A. 20/09/2020 D.O.I. Res.: Yes or No days Est. Repairs: Carz Haver 3 Val.: Yes or No Survey held at Lum Sum: Des. of Damages : Frt Rear / O/S / N/S / U/C / Rooftop or CA / REV / REP. / 24 HRS Vehicle: IN / OUT Person Contacted: The U/C / Chassis frame / Body Structure affected due to collision. Date / Time Action / Instruction MV, 55,000 PV.38,529 NV:16,471 lump sum 2950, (red:1522.60;34%) 3 Date/Time, File Pass to? Days Of Repair: : Preli. Report Resurvey No. of Trip: Survey Fee: **Final Report** Date/Time, File Return to? Transportation: Add Fee: : Site Insp _S + RS,__SI : Interview (\$ **Photos**

: Tech. Invs (\$

Weel:end (\$

Report Format: Lump Sum / I.B.I: (\$ Others

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	332H
Vehicle Details	
Vehicle No.:	SKZ9330X
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Sep 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1ZRX534006
Chassis No.:	MR053REH104539903
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,804.00
Original Registration Date:	16 Feb 2016
First Registration Date:	16 Feb 2016
Transfer Count:	2
Actual ARF Paid:	\$17,804.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Feb 2026
PARF Rebate Amount:	\$13,353.00
Intended COE Rebate Details	
COE Expiry Date:	15 Feb 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$46,651.00
COE Rebate Amount:	\$25,176.00
Total Rebate Amount:	\$38,529.00

The information contained herein is correct as at 24 Sep 2020

MVMG20081768 / Vermogen Ace Pte Ltd - HQ ENTRY DATE & TIME. 21/09/2020 12:33 SUBMITTED BY, Juan Paulo Bongon Baldoz

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurence Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

•	\sim		VΤ	 	-		м	
 -		18		 -41	-		ч.	

Date Of Report 21/09/2020 12:33 Date Of Accident 20/09/2020 12:00

LOYANG DRIVE OUTSIDE COMFORTDELGRO **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

SKZ9330X Vehicle Registration Number

Insured/Policyholder

SUPERTEC LIMOUSINE PTE LTD Name Of Registered Owner

2XXXXX332H Co Reg No

NOEMAIL **Email Address**

Mobile Phone No

OFFICE-87824933 Alternative Phone No

Vehicle Particulars

TOYOTA Manufacturer **ALTIS**

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

THIRD PARTY

If No, Please state action to be taken

PRIVATE HIRE

Vehicle Category

Insurance Company

AXA INSURANCE PTE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

VFX/P2385062 Policy Number

Cover Note Number

Driver

CHAY WAI SENG Name of Driver

SXXXX470A NRIC No 15/07/1968 Date Of Birth INDOOR Occupation 18/04/1995 **Date Of Driving Pass**

25 YEARS AND 5 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-87222869 Mobile Number

Fax Number

Contact Number

NOEMAIL **EMail Address**

Address

APT BLK 132 JALAN BUKIT MERAH #09-1344

Postcode

160132

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

SIDE SWIPE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

YES

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: PASSENGER

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

FBN3947B

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

MOTORCYCLE

Name of Driver

RAJENDRAN MANIKANDAN

NRIC/Passport Number

GXXXX635L

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such. Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

00: 100911332H m


Policyholder's Signature Date & Time: Driver's Signature
(If driver is not the policyholder)
Date & Time:

COEN AC.

PAULO

Reporting Centre Personnel's Signature Name: NRIC/FIN No.: Sketch Plan Pg. 2





DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE SAID PATE DUD TIME I WAS DENVIUG MAKE
LOYANG DRIVE. I UNS TURNING PIGHT SLOW BOING TO
CONFIRMATION TO SENO MY PASCENCES WHEN CHODENLY
A MOTOPCYCLE (FBW39478) PRIM BENMNO OVERTAME FROM
THE PIGHT SIDE AGAINST TRAPPIC THEN GILLIDED
outs MY CKR FIGHT FRANT PORTON. AFFER THE
ALCIDENT WE EXCHANGE PINOTICOLARS.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

PAULO

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

CARZ HAVEN PTE.LTD.

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869 Tel : 6904 4596 | Fax No : 6694 4929

SKZ9330X

ACCIDENT REPAIR ESTIMATE

Date of Accident : 20/9/2020 Engine No. : 12RX534006		AC	CIDENT N	LI AIN LOTI	<u> </u>	
COST OF CLAIMS Parts Cost / List Items: \$ -	TP INSURER :	MSIG	_		Vehicle Reg. No. :	SKZ9330X
Date of Accident : 20/9/2020 Engine No. : 12RX534006	OWN INSURER :	AXA	_		Vehicle Reg. Date	: 16-Feb-2016
Cost of Accident: 20/9/2020 Chassis No.: MR053REH10453990:	CLAIM TYPE :	TP	-		Make / Model :	TOYOTA COROLLA ALTIS (
COST OF CLAIMS Parts Cost / List Items: \$ - Surveyor Name and Company: Plus/Less 25% \$ - Date of survey: Total Cost / List: \$ - Date of survey: Special Nett Items: \$ 350.00 Part by Part / Lump Sum: O Total Parts Amount: \$ 350.00 Resurvey Before Paint / After Paint Total Labour Amount: \$ 3,830.00 Authorize/Not Authorize/Without Prejudic Gross Total: \$ 4,180.00 Email: GST%: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	Date of Accident :	20/9/2020	_		Engine No.:	1ZRX534006
Parts Cost / List Items: \$ - Surveyor Name and Company: Plus/Less 25% \$ - Total Cost / List: \$ - Date of survey: Special Nett Items: \$ 350.00 Part by Part / Lump Sum: 0 Total Parts Amount: \$ 350.00 Resurvey Before Paint / After Paint Total Labour Amount: \$ 3,830.00 Authorize/Not Authorize/Without Prejudice Gross Total: \$ 4,180.00 Email: GST %: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	_				Chassis No.:	MR053REH104539903
Parts Cost / List Items: \$ - Surveyor Name and Company: Plus/Less 25% \$ - Total Cost / List: \$ - Date of survey: Special Nett Items: \$ 350.00 Part by Part / Lump Sum: 0 Total Parts Amount: \$ 350.00 Resurvey Before Paint / After Paint Total Labour Amount: \$ 3,830.00 Authorize/Not Authorize/Without Prejudice Gross Total: \$ 4,180.00 Email: GST %: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	COST OF CLAIM	<u>1S</u>		=		
Date of survey :					Surveyor f	Name and Company:
Special Nett Items: \$ 350.00 Part by Part / Lump Sum: d Total Parts Amount: \$ 350.00 Resurvey Before Paint / After Paint Total Labour Amount: \$ 3,830.00 Authorize/Not Authorize/Without Prejudic Gross Total: \$ 4,180.00 Email: GST%: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	Plus/Less25%	\$				
Special Nett Items: \$ 350.00 Resurvey Before Paint / After Paint Total Parts Amount: \$ 3,830.00 Authorize/Not Authorize/Without Prejudic Gross Total: \$ 4,180.00 Email: GST %: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	Total Cost / List :	\$			Date of survey:	
Total Labour Amount : \$ 3,830.00 Authorize/Not Authorize/Without Prejudice Gross Total : \$ 4,180.00 Email : GST % : 7% \$ 292.60 Fax No : Nett Amount : \$ 4,472.60 HP No :	Special Nett Items :	\$	350.00		Part by Part / Lum	np Sum : days
Gross Total: \$ 4,180.00 Email: GST %: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	Total Parts Amount :	\$	350.00		Resurvey Before F	Paint / After Paint
GST %: 7% \$ 292.60 Fax No: Nett Amount: \$ 4,472.60 HP No:	Total Labour Amount :	\$	3,830.00		Authorize/Not Au	thorize/Without Prejudice
Nett Amount : \$ 4,472.60 HP No :	Gross Total :	\$	4,180.00		Email :	
	GST % : 7%	\$	292.60		Fax No :	
This claim is handled by : PAULO	Nett Amount :	\$ 4,	,472.60		HP No :	
This claim is handled by : PAULO						
	This claim is handled b	y:	PAULO	:	-	

CARZ HAVEN PTE.LTD.

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869

Tel: 6904 4596 | Fax No: 6694 4929

Vehicle Reg. No. :

SKZ9330X

Vehicle Reg. Date:

Make / Model :

16/2/2016 TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Engine No.:

1ZRX534006

Chassis No.:

MR053REH104539903

PAGE 1

Estimates on Parts

						ADJUSTED
No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	AMOUNT
1	1	BONNET	XR			
2	2	BONNET HINGE LH/RH	×			
3	1	BONNET LOCK	×			
4	1	BONNET INSULATOR	×			
5	1set	BONNET INSULATOR CLIPS	×			
6	1	FRONT BUMPER	/cru			
7	1set	FRONT BUMPER CLIPS	/ Nec			
8	12	FRONT BUMPER RETAINER LA/RH	/ Mis.			
9	1	FRONT BUMPER SPONGE	./cnu			
10	1	FRONT BUMPER REINFORCEMENT	×			
11	1	FRONT BRACE BRACKET	XE			
12	1	FRONT GRILLE LOGO	/Nec			
13	1	FRONT UPPER GRILLE BASE 7 CPV	1 CRA			
14	1	FRONT UPPER GRILLE CHROME	×			
15	1	FRONT LOWER GRILLE	/cur-			
16	1	FOG LAMP RH	X			
17	1	FOG LAMP GARNISH RH	×			
18	1	HEAD LAMP RH	SCR			
19	1	HEAD LAMP CHROME GARNISH RH	X			
20	1	HEAD LAMP SUPPORT RH	XR			
21	1	FRONT TOP SUPPORT PANEL	×R			
22	1	FRONT FENDER RH	× R			
23	1	FRONT FENDER EMBLEM RH	/NPC-			
24	1	FRONT FENDER INNER SHIELD RH	/ CUE			
25	1set	FRONT FENDER INNER SHIELD RH CLIPS	/Nec			
26	1	FRONT ENGINE UNDERCOVER	/ cut.			
27	1set	FRONT ENGINE UNDERCOVER CLIPS	Ner.		L	
28	1	FRONT RIM RH	(ut			
29	1	FRONT SHOCK ABSORBER RH	×			
30	1	FRONT SHOCK MOUNTING RH	×			
31	1	FRONT LOWER ARM RH	У.			
32	1	FRONT BALL JOINT RH	×			
33	1	FRONT KNUCKLE ARM RH	×			
34	1	FRONT WHEEL HUB RH	×			
35	1	FRONT WHEEL BEARING RH	×			
36	1	FRONT STABILIZER LINK RH	×			
37	1	WASHER TANK	×			
38	1	WASHER TANK MOTOR	X			
39	1	FRONT TYRE RH	×		\$ 300.00	
40	1	FRONT NUMBER PLATE WITH FRAME	/CRY.		\$ 50.00	35

CARZ HAVEN PTE. LTD.

60 JALAN LAM HUAT, #03-35-36 CARROS CENTRE SINGAPORE 737869 Tel: 6904 4596 | Fax No: 6694 4929

Vehicle Reg. No.:

SKZ9330X

Vehicle Reg. Date:

16/2/2016

Make / Model:

TOYOTA COROLLA ALTIS CLASSIC 1.6 CVT

Engine No.:

1ZRX534006

Chassis No.:

MR053REH104539903

PAGE 1

Estimates on Labour

	MECHANICAL / ELECTRICAL / PANEL / PAINT LABOUR		MOUNT	ADJUSTED AMOUNT
No	To straighten and panel beating accident area. To remove and replace damaged parts.	Ś	1,500.00	400
1	To straighten and panel beating accident area. To remove and replace damages pares	Ť		
	parts. FRONT RH Portion.			
2	To putty,re-spray painting and polish affected areas. Front RH Portion.	\$	1,500.00	700
3	To check and rectify wiring after disconnect and reconnect.	\$	280.00	30
4	To remove & refit undercarriage to assist work load.	\$	280.00	Х
5	To do wheel alignment.	\$	150.00	60
6	To do tyre balancing	\$	120.00	X
		\vdash		i
		t		
		+		
		Į		L
		F		
		1		

Repair dy - 3 dys

LIS

After paini phono

Son Pon Chili)

Let 22/00/2020

To withou projedu

LKK Auto Consultants hence notify

the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: