

DATE: N/A REF: FCI

ASSIGNMENT

File No: _____ Date: _____

Name of Case: _____

☒ PERS / ☐ REP / ☐ QO RES / ☐ EVA / ☐ INV / ☐ MV

Insured Vehicle No: _____

Workshop No: _____

Veh No: SHD 3409U Yr Regn: 14 NOV 2019

Type: M.Car / M.Cyclo / BUS / Van / Lorry ☒ (Taxi) ☐ (Prime Mover)

Truck / Tractor or _____

Make: HYUNDAI IONIQ cc: 1580

Colour: BLUE A/C: Insured / N/A

Sp Reading: N/A T/P: Insured / N/A

Engine: _____

Chassis: KMHCG51CVCU89329

Gen. Cond. Good / Fair / Poor Burnt

Steering: In order / Jammed / Locked Burnt or

Brakes: In order / Jammed / Leaked Burnt or

Wheels: ☒ (L) ☐ (R) SIRIM / STD / AIR / or

Tyre Size: F: 195/65R15

R: 11

BSI / DUH / EX / NOVA / GY / ES / L / ZA / H / C / O / H / S / P / R / S / U / M /

W / Y / O / K / O or WESTLAKE

Front: Burnt mm

Rear: Burnt mm

UB: 4 mm

UB: Burnt mm

UB: 18/9/2020 22/9/2020

Survey held at: CDGE LOYANG

Occ. of Damages: Frl / Rear / O/S / N/S / U/C / Rodtop or

Whole vehicle burnt

The U/C / Chassis / Frame / Body Structure affected due to _____

_____ : Profile Report

_____ : Final Report

7/10/20-Typist

Report prepared: Uneconomical T/L

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invo (\$

☐ Weekend (\$

304-10=294

294X15=4410

4410+170=4580

INV-S500

SCDF-S170

Survey Fee: 4580

Transport: 50
