

REPAIR ESTIMATE*

VEHICLE NO SHD3072G

DATE 01/09/20 12:00 AM

NAME :

CHIANG / N AIG

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	HEADLAMP LH			\$1,388.00
1	FRONT BUMPER SIDE BRACKET LH			\$22.40
1	FRT FENDER LH			\$663.00
1	FRONT BUMPER ASSY			\$1,052.20
1	FRT BUMPER GRILLE LH			\$93.60
	SUB TOTAL			\$3,219.20
	20.00%			\$643.84
	DISCOUNTED TOTAL			\$2,575.36
				\$-
	Labour Charge			
	Panel Beating			\$540.00
	Spray Painting Charge			\$450.00
	Check wiring			\$60.00
	Tuff kote			\$60.00
	TOTAL LABOUR			\$1,110.00
	ESTIMATE TOTAL			\$3,685.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan/Min 97445744
 WP' 21/9/2005 pm
 C/S Resurvey after repair
 Tan/Min C/Chantawan
 2-3 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701
Mainline + 65 6383 5280 Facsimile + 65 6280 9755

Workshops

53 Loyang Drive Singapore 508969
382 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 500285
820 Choa Chuang Road Singapore 600449

24 Serangoon Road Singapore 758198
7 Sungei Kadut Way Singapore 728141
501 Yishun Industrial Park A Singapore 768

A member of COMFORTDELGRO

Date/Time: 21.09.2020 13:20

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305423724

STOMER

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(R) (Q)
(P)

ICOUNT CARD NO.

REGN NO:

SHD3072G

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....

MODEL

I-40

DATE/TIME IN

21.09.2020 09:25

YR OF MANU

16.06.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU091446

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 20.09.2020

NATURE: 3P 20.09.2020

S/NO

LABOR CODE

DESCRIPTION



ED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

gement Slip

Exit Pass

SHD3072G

CLC

Vehicle No.:

SHD3072G

ervice Advisor

Signature/Date

Name of Service Advisor

Date

ned to Service Reception upon collection

To be kept by Security Guard