



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20010118/Uqf3e2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 01-10-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBP 9589B	Veh. Inspected	SMS 1616M
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002753/AGC	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	22/09/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W. X1 SDRIVE20I MSPT (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	WBA72AA0405R39536	Colour	GREY
Odometer	2206	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45 R19	CONTINENTAL	9 mm
L/H Front Tyre	225/45 R19	CONTINENTAL	9 mm
R/H Rear Tyre	225/45 R19	CONTINENTAL	9 mm
L/H Rear Tyre	225/45 R19	CONTINENTAL	9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/09/2020	Inspection Date	22/09/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------