

ASS. REC. BY:

REF: CS3/CTI20010125/Eqf3

Special Instruction:

Surveyor: STEVE ASSIGNMENT (Office)

From (Person): Adeline Chng of CTI Date/Time: 22/9/2020 9:58 AM

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBK 4606U Insured: GBB 4130Y

at Workshop m/s Sin Foo Hing Battery Service Tel: 97336031

of 27A Jurong Port Road #01-30 Singapore 619101

Policy No: _____ Claim No: SNM20D203449C02

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19 SEPTEMBER 2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 22-9-20 10.21A.M Person Contacted: SIN Vehicle IN OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	GBK 4606U- <input checked="" type="checkbox"/>
	GBB 4130Y- NBA/INC13013806/y1 DOA :22/07/2013