

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd								
60 Woodlands Industrial Park E4, Singapore 757705								
FAX Number : 63685592								
Estimator Telephone Number : 68662623								
Accident Reporting Number : 68662672								

Date Generated : 09/10/2020 : CatherineLee

			Secti	on D - Deta	ils of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope				Quotation from AR				Adjusted by Surveyor, if applicable	
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.				\$530.00				\$265.00	
Total Labour				\$530.00				\$265.00	
Part 2 - Spray	/ Painting & Pa	nel Beating Rela	ited Works						
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
TO PUTTY & RESPRAY				\$432.00			\$262.00		
Total Spray Painting & Panel Beating				\$432.00				\$262.00	
Part 3 - Other	Costs - Accide	ent and Acciden	t Repair Related Expens	se					
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Lump Sum Adjustment by Surveyor				\$0.00				(\$105.40)	
Total Other Costs				\$0.00				(\$105.40)	
Part 4 - Spare	Parts / Materia	al Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6008240	Body	111049	BLADE,WIPER:1000MM, MB OC500 & MBG	2.00	\$40.44	10.00	\$72.79	Replace	Replace
			SGLOVEBUS STICKER	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6008239	BODY LH		ARM,WIPER:LEFT HAND	1.00	\$832.50	10.00	\$749.25	Replace	Replace
6008238	BODY RH	104301	ARM,WIPER:RIGHT HAND	1.00	\$832.50	10.00	\$749.25	Replace	Replace
Total					\$1,780.44		\$1,646.29		
Added Spare	Parts / Materia	I Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

2,782.88#

265 262 2,173,29 - 20% 1,738.63 2days