

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB54E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Sep 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	OC500LE1830H
Primary Colour:	Black
Manufacturing Year:	2008
Engine No.:	45796600149746
Chassis No.:	WEB63442021000126
Maximum Power Output:	-
Open Market Value:	\$320,024.00
Original Registration Date:	26 Dec 2008
First Registration Date:	26 Dec 2008
Transfer Count:	0
Actual ARF Paid:	\$16,002.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 22 Sep 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/09/2020 10:22
Date Of Accident	17/09/2020 10:55
Exact Location Of Accident	JUNCTION OF KRANJI ROAD AND JALAN LAM HUAT BEFORE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB54E
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXX292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	MBOC500

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-20095488MFBP
Cover Note Number	

Driver

Name of Driver	WANG LONG
Passport No/FIN	GXXXX300K
Date Of Birth	16/09/1988
Occupation	OUTDOOR
Date Of Driving Pass	13/11/2017
Driving Experience	2 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address NO ADDRESS
Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -
-

Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles (including own vehicle) involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

On 17/09/2020 at around 1057hrs, I was travelling on the left lane of 2 lanes along Kranji Road approaching the signalized Cross junction of Jalan Lam Huat heading toward the direction of Kranji Depot on service OSB. While bus was approaching the signalized traffic junction, the traffic light was showing red in color so I slow down my bus speed and stopped my bus at the stop line behind a private lorry. While waiting, I noticed that the front vehicle is a private lorry which had stopped beyond the stop line. So I maintained a safe distance of 1 car length apart from the private lorry in front. While both vehicle (my bus and the private lorry) were stationary, the third party vehicle in front began to reverse backward (third party lorry (YP4142S) showing reversing light). Upon seeing this, I immediately horned at the third party driver but it failed and continued to reverse and collided onto my bus front portion to result in this Reversing accident case. As my bus was stationary, I immediately alighted from bus to conduct checks for damage. While checking, I realized that my bus front windscreen wiper damage with wiper holder loosen and the third party lorry rear portion no damage. We exchange particulars with each other at scene and left. Third party driver admitted fault to me at scene. My bus was stationary at the point of accident. That's all.

Attachment(s)

Are accident photos available for attachment? NOT AVAILABLE DUE TO CIRCUMSTANCES OF ACCIDENT
Was there any video captured by Car Camera? YES
Remarks/ Reasons: PENDING DOWNLOAD
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number YP4142S
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver ONG SOON SENG
NRIC/Passport Number
Contact Number

Address

Postcode

Insurance Company Name

NTUC INCOME INSURANCE CO-OPERATIVE LTD

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

SMB 54 E

PAX = 0
Bus/09/20/5024

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

2/12

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Junction of Kranji Road and
Jalan Lam Huat / Before (BS: 4911) -
after Jalan Lam Huat

DECLARATION

I/We dec

; particulars are true in every respect.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number 63685592
Estimator Telephone Number 68662623
Accident Reporting Number 68662672

Date Generated : 21/09/2020

User ID : JeongCH

Section A - Accident Details

Registration Number	SMB54E
Case Reference Number	BUS/09/20/5024
Registration Date	12/26/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Wang Long
Type of Accident	Rear To Head
Accident Date and Time	9/17/2020 10:57 AM
Accident Reported Date and Time	9/17/2020 1 15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB54E-FRONT PORTION YP4142S (TP) INSURED WITH NTUC
Prepared Date and Time	9/21/2020 1:55 PM
Chassis Number	WEB63442021000126
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$0.00
Total Spray Cost	\$432.00	\$0.00
Total Spare Part Cost	\$118.23	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,080.23	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	2.0	
Prepared / Adjusted By	Jeong Choon Hwee	
ARC / Surveyor Sign Off Date	21/09/2020 1:56 PM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd	
60 Woodlands Industrial Park E4, Singapore 757705	
FAX Number	63685592
Estimator Telephone Number	68662623
Accident Reporting Number	68662672

Date Generated : 21/09/2020

User ID : JeongCH

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$530.00	265
Total Labour	\$530.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$432.00	262
Total Spray Painting & Panel Beating	\$432.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
008240	Body	111049	BLADE, WIPER, 1000MM, MB OC500 & MBG	2.00	\$40.44	10.00	\$72.79	Replace	/CKA
			SGLOVEBUS STICKER	1.00	\$75.00	0.00	\$75.00		/CKA
Total					\$115.44		\$147.79		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair dy - 2dys.

45.

be after part photo

See Pn C4467

21/09/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: