



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 09/10/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB54E
Case Reference Number	BUS/09/20/5024
Registration Date	26/12/2008
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC500
Name of Driver	Wang Long
Type of Accident	Rear To Head
Accident Date and Time	17/9/2020 10:57 AM
Accident Reported Date and Time	17/9/2020 1:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24108232
Special Instruction to ARC, if any	SMB54E-FRONT PORTION YP4142S (TP) INSURED WITH NTUC
Prepared Date and Time	21/9/2020 1:55 PM
Chassis Number	WEB63442021000126
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$530.00	\$265.00
Total Spray Cost	\$432.00	\$262.00
Total Spare Part Cost	\$1,317.03	\$1,317.03
Total Other Cost	\$0.00	(\$105.40)
TOTAL COST	\$2,279.03	\$1,738.63
Lump Sum Total	\$0.00	\$1,750.00
Number of Repair Days	2.0	2.0
Prepared / Adjusted By	Jeong Choon Hwee	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	21/09/2020 1:56 PM	21/09/2020 3:35 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/10/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$530.00	\$265.00 ✓
Total Labour	\$530.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PUTTY & RESPRAY	\$432.00	\$262.00 ✓
Total Spray Painting & Panel Beating	\$432.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$105.40)
Total Other Costs	\$0.00	(\$105.40)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6008240	Body	111049	BLADE,WIPER:1000MM, MB OC500 & MBG	2.00	\$40.44	10.00	\$72.79	Replace	Replace
			SGLOVEBUS STICKER	1.00	\$75.00	0.00	\$75.00	Replace	Replace
6008239	BODY LH		ARM,WIPER:LEFT HAND	1.00	\$832.50	10.00	\$749.25	Replace	Replace
6008238	BODY RH	104301	ARM,WIPER:RIGHT HAND	1.00	\$832.50	10.00	\$749.25	Replace	Replace
Total					\$1,780.44		\$1,646.29		

✓CRA
✓Nec
✓SCR
✓SCR

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,646.29
 265
 262

 2,173.29
 - 20%

 1,738.63

2/15
 \$1,750
 2 days