

ASS. REC. BY:

REF: CS3/MSG20010144/Qvf3

Special Instruction:

Surveyor: SUN PIN

ASSIGNMENT (Office)

From (Person): Shawn Ngo Sau Wei of MSIG Date/Time: 22 Sep 2020 13:48

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJL 1218B Insured: SLM 2797K

at Workshop m/s Yong Chin Car Care Centre Tel: 63675052

of Blk 4 Kranji Loop #01-12, Singapore 739540

Policy No: Claim No: 628874

Sum Insured: Excess:

Make of Veh: D.O.A. 19/09/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement:

Date/Time: 22-9-20 1.57P.M

Person Contacted: CATHERINE

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (X) Estimate
	SJL 1218B- X
	SLM 2797K- X
25/9/20	Submit PRS, repair range \$2,000-\$3,000 (4 days)