

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Sep 2020 12:52 Sendback Est	21 Sep 2020 12:57 \$2,504.12	22 Sep 2020 13:27 Edit Adj Rpt	\$1,542.12 Edit Estimates	\$1,542.12 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	CHEW HEOK HUI , Co. Reg. No.: S1205665F		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA2205M	Date of Loss:	20/09/2020 13:00 - :59 [13 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / M2004643	Policy/Cover Note No.:	MS009907 (TP, Fire & Theft) Coverage: 01/10/2019 - 30/09/2020
Vehicle Reg. No. (Insured):	SGF1399D	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive, 508969 Loyang - Tel: 6214 8300		
Handling Insurer:	Tokio Marine Insurance Singapore Ltd (HQ) - Tel: 6221 6111 ... [Handled by Ng Kwai Kay Francis]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 01/10/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SHA2205M (M2004643)
[SGF1399D]
TP
COMFORT TRANSPORTATION PTE LTD
Sep 20 2020 1:00PM
[CHEW HEOK HUI]
ComfortDelGro Engineering Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▾
Assessment Reports			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail Print
1	21/09/20 12:57	Repairer Estimates	<input type="checkbox"/> Load HTM <input type="checkbox"/>
No	Finalized On	Tokio Marine Insurance Singapore Ltd (HQ)	Thumbnail Print
1	22/09/20 13:25	Accident Statement <small>From:SC - Reg. No: SGF1399D, Claimant: CHEW HEOK HUI</small>	<input type="checkbox"/> Load HTM <input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	24/09/20 18:01	Adjuster Immediate Advice	<input type="checkbox"/> Load HTM <input type="checkbox"/>
Photos/Images			3 per page ▾ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	24/09/20 12:25	Odometer Reading	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	24/09/20 12:25	Chassis Number	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	24/09/20 12:25	General View	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	25/09/20 12:59	Reinspection Photo	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	25/09/20 12:59	Reinspection Photo	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	25/09/20 12:59	Reinspection Photo	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	25/09/20 13:00	Replacement Part Photo	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
22	25/09/20 13:00	Replacement Part Photo	<input type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page ▾ <input checked="" type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Braddell)	Thumbnail Print
1	28/09/20 14:11	LOD, Invoice, LOR, Mileage Record, LA, LTA Search Fee	<input type="checkbox"/> Load PDF <input type="checkbox"/>
No	Finalized On	ComfortDelGro Engineering Pte Ltd (Loyang)	Thumbnail Print
1	21/09/20 12:59	E-filed GIA report	<input type="checkbox"/> Load PDF <input type="checkbox"/>
2	21/09/20 13:03	E-filed GIA report	<input type="checkbox"/> Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/>
There are no document checklists configured.	

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Repairer Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI20010149/T1SD3S2**Date:** 28/09/2020REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS009907
Claimant Vehicle No :	SHA2205M	Insured Vehicle No :	SGF1399D
Date of Loss:	20/09/2020	Nature of Claim:	TP
		Claim No:	M2004643

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA2205M	Engine No:	G4LEKU298721
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU164992
Reg. Date:	01/08/2019 (Man. Year: 2019)	Odometer:	82160 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,773.12	981.12	792.00	44.67
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,504.12	1,542.12	962.00	38.42
+ GST 7.00/7.00% (S\$)	175.29	107.95	67.34	38.42
Nett Amount (S\$)	2,679.41	1,650.07	1,029.34	38.42

INSPECTION

Date of Assignment:	22/09/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	21/09/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Hiew May Fung*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Sep 2020)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHA2205M)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	459.40 FL	-	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Not Necessary	294.80 FL	-	*- FL
3	2		*REAR BUMPER REINFORCEMENT BRACKET RH/LH	Not Necessary	276.20 FL	-	*- FL
4	1		*REAR BUMPER UPR CTR MOULDING	Deformed	451.25 FL	-	*451.25 FL
5	1		*REAR BUMPER LWR CTR MOULDING	Repair	155.00 FL	-	*- FL
6	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
7	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	-	*- FL
8	1		*REAR BUMPER MAT	Not Necessary	50.00 F	-	*- F
9	1		*REVERSE SENSOR	Necessary	180.00 F	-	*180.00 F
10	1		*REAR NO.PLATE WITH TRIM COVER	Cracked	55.00 F	-	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,145.15	1,167.65
- List Item Discount on L Items 20.00/20.00% (\$\$)	372.03	186.53
Total Parts (\$\$)	1,773.12	981.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			720.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >