

# CS/TMI20010149/T1sd3

ASS. REC. BY: Taufik


REF: TMI

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: Lim JS Vehicle: IN / OUT

Veh No: 3HA2205M Yr Regn: 2019 Aug  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Hyundai Logic c.c. 1580  
 Colour: Blue A/C: \_\_\_\_\_ Insured / Std / NI / NA  
 Sp. Reading: 82160 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KMH C851CV K4164992  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In Order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD AIRim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: u  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>21/9/20</u>

 Survey held at Compuhelp Logic  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TAUFIKH CONFIRMED P/P \$ 1,542.12/2 DAYS WITH TIEN SIONG (\$ 962.00/RED - 38%)

Date/Time, File Pass to? 25/09/2020  
 1) TYPIST  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

: Preli. Report  
 : Final Report

Days Of Repair: 2  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS \$ \_\_\_\_\_  
 Photos: \_\_\_\_\_

Per ~~Form~~ Form: P/P \$ 1,542.12

**ComfortDelGro Engineering Pte Ltd** (Co.Reg.No:199506048W)  
 59 Loyang Drive  
 Singapore 508969  
 Tel: 6214 8300

Lim Tien Siong

**TP INSURER:** Tokio Marine Insurance Singapore Ltd (HQ) *UPP*  
**CTPL**

Singapore

*Lee-Taufik.*

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/09/2020
Vehicle Reg. No.:	<b>SHA2205M</b>	Driveable?	NO
Party At Fault:	UNKNOWN		

Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	01/08/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU298721	Chassis No:	KMHC851CVKU16499
Odometer:	0 KM		

Paint Type:  
 List Item Discount: 20.00 %  
 Total Loss? **NO**  
 Est. Duration of Repair (day) 3

Present Location: COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,773.12
Miscellaneous Items	11.00
Labour	720.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,504.12</b>
<b>+ GST 7.00% (S\$)</b>	<b>175.29</b>
<b>Nett Amount (S\$)</b>	<b>2,679.41</b>

**This claim is handled by: LIM TIEN SIONG**

## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Sep 2020)  
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue: Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: ComfortDelGro Engineering Pte Ltd/SHA2205M/21/09/2020 12:57  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	367.52	20.00	0.00 ✓ *459.40 FL <i>de</i>
2	1		*REAR BUMPER REINFORCEMENT		20.00	0.00 *294.80 FL <i>un</i>
3	2		*REAR BUMPER REINFORCEMENT BRACKET RH/LH		20.00	0.00 *276.20 FL <i>un</i>
4	1		*REAR BUMPER UPR CTR MOULDING	361	20.00	0.00 ✓ *451.25 FL <i>de</i>
5	1		*REAR BUMPER LWR CTR MOULDING		20.00	0.00 *155.00 FL <i>Rx</i>
6	10		*REAR BUMPER CLIPS	176	20.00	0.00 ✓ *22.00 FL <i>all</i>
7	1		*REAR BUMPER FOGLAMP		20.00	0.00 *201.50 FL <i>un</i>
8	1		*REAR BUMPER MAT		0.00	0.00 *50.00 FL <i>un</i>
9	1		*REVERSE SENSOR		0.00	0.00 ✓ *180.00 FL <i>un</i>
10	1		*REAR NO.PLATE WITH TRIM COVER		0.00	0.00 ✓ *55.00 FL <i>un</i>

F=Franchise part. L=ListItemDisc

Sub Total (S\$)	2,145.15
- List Item Discount on L Items (S\$)	372.03
<b>Total Parts (S\$)</b>	<b>1,773.12</b>

ComfortDelGro Engineering Pte Ltd/SHA2205M/21/09/2020 12:57. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

746.12  
 SN 235  
 981.12

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			11.00
1	1	OD/TP Case (Insurer)	
<b>Sub Total (S\$)</b>			<b>11.00</b>

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	320 350.00
2	SPRAY PAINTING	New	200 250.00
3	R/I REVERSE SENSOR	New	30 120.00
<b>Gross Labour Cost (S\$)</b>			<b>550 720.00</b>

ComfortDelGro Engineering Pte Ltd/SHA2205M/21/09/2020 12:57. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tan Kah 9749574"  
-wp' 21/9/2020 5pm  
P/P Repair after repair  
Tan Kah (thank you)  
2 days MIC

981.12  
11  
550  
91542.12  
2 days #

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: