

ASS REC. BY:

REF: C93 / ALH18008648 / U-48

Special Instruction:

MARCUS

ASSIGNMENT (Office)

22/9/2020 3:22 PM

Survivor

Melmen

LEE MING YAO

From (Person):

of

ALH

Date/Time:

Estimated Cost:

Bill to:

OD / EV / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 5698 P

Insured:

SLR 5329H

at Workshop m/s

Tek Soon Motor.

Tel:

6747 5484

of

Blk 1 Kaki Bukit Ave 6 #01-93

Policy No:

Claim No:

4211777329SG

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04052018

(Client's Record)

CA / REV / REP. / REV 24 HRS wpt

H.O.D. Endorsement:

Date/Time:

08052018 4:14pm

Person Contacted:

Tek Soon

Vehicle (IN) / OUT

Date/Time	Action/Instruction ( X ) Estimate
	GY 5698P - X
	SLR 5329H - X
23/5/18	Dismantled
23/9/20	Submit LS \$11,000 (Red 6600, 38%) , 16 days

MV:\$16,000 (est) LTA: \$10,922 NV:\$5078

REF:

AIG

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: GY 5698P  
 at Workshop m/s: Rek Soon Motor  
 of 1 Kaki Bukit Ave 6 #01-93.

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res: Yes or No

Lump Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

401993/

Vehicle: IN / OUT

19986

Veh No: GY 5698P Yr Regn: 5 05  
 Type: M/Car / M/Cycle / Bus / ☒ Lorri / Taxi / Prime Mover /

Truck / Trailer or (M)

Make:

NISSAN cabstarc.c. 3153

Colour:

Silver

A/C

Insured / Std / NI / NA

Sp. Reading

498947

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1SF4F2320854236Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F:

195-215

R:

155-1212 YokohamaBS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5/5

mm

L/Bal:

5

mm

L/Bal:

5/5

mm

D.O.A.

4/5/18

D.O.I.

9/5/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

R.P.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

PRS LTA 8/0922  
not sur

102 until 30/4/2020  
14rs 11ml.

13/8Submit DAR report.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 23/9/20-TypistDays Of Repair: 12 16Resurvey No. of Trip: 1

Survey Fee:

Transportation

) S + P ( )

) Photos

) Others

TOTAL

Report Format:

DAR TP

Lump Sum / I.B.:

LS \$11,000

Add Fee:

☐

Site Insp: (\$

☐

Interview: (\$

☐

Tech Invs: (\$

☐

Weekend: (\$

- Pre repair inspection request - GY5698P VS SLR5329H (OI) DOA: 04/05/2018

From: Lim, Sheng Yang  
 To: admin-a@lkkauto.com, assignments@lkkauto.com  
 Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Bajjit, Chin, Lee-Ying, Abu Kassim, Noor Marissa, Md Ishak, Mohd Imran, Chan, Yoke Shi, Supramaniam, Darshene, Fan, Winnie-LW  
 Sent: Tuesday, 8 May, 2018 4:07:37 PM  
 Attachments: ☐ Fax394D.TIF

Hi,

Please refer to the enclosed request from **TEK SOON MOTOR REPAIR & SPRAY PAINTING**.Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thank you.

Best Regards,

Lim Sheng Yang  
 AIG

Claim Adjuster II, Singapore FNOL Claims Operations – Auto  
 Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)  
 Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia  
 Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

ShengYang.Lim@aig.com | www.aig.com

08052018 @ 4.14pm  
 Tek Soon veh in.

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: limng.dawn@gmail.com

To: ShengYang.Lim@aig.com

Subject: Re: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLR5329H AND GY5698P ON 04/05/2018

Date: Tue, 8 May 2018 07:24:54 +0000

Noted. Please select any surveyor from LKK Auto Consultants. Thanks much.

On Tue, 8 May 2018 at 3:19 PM, Lim, Sheng Yang &lt;ShengYang.Lim@aig.com&gt; wrote:

Without Prejudice

Your Reference : GY5698P

Our Reference : SLR5329H

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd

Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repairs survey carried out by the single joint expert.

Thank you.

Best Regards,

Lim Sheng Yang

AIG

Claim Adjuster II, Singapore FNOL, Claims Operations – Auto  
Shared Services – Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)

Menara Worldwide, Level 12, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia

Tel +6 03 2719 6000 | Ext 1012101 | Fax +6 03 2685 5898

[ShengYang.Lim@aig.com](mailto:ShengYang.Lim@aig.com) | [www.aig.com](http://www.aig.com)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Specialist in repairing of  
Motor Vehicles, Welding,  
Spraying, Painting Car,  
Insurance Agent

德 順 摩 哆 噴 漆 廠

**TEK SOON MOTOR REPAIR & SPRAY PAINTING**

Autobay @ Kaki Bukit, 1 Kaki Bukit Avenue 6, #01-93/95, Singapore 417883  
Tel: 6745484, Fax: 67466822  
Reg No. 252083/00-L

本 廠 專 門 代 理  
汽 車 噴 漆 保 險  
機 油 換 油 等  
工 務 打 漆 等

FACSIMILE TRANSMITTAL

DATE:	8/5/2018	FAX NO:	68357416
TO :	AIG Asia Pacific Insurance Pte Ltd	(MOTOR CLAIMS DEPT)	
ATTN:	The Officer-in-charge	NUMBER OF PAGES:	
FROM:	TEK SOON MOTOR REPAIR & SPRAY PAINTING		
SUBJECT:	ACCIDENT ON <u>4/5/2018</u> INVOLVING YOUR INSURED 'S VEHICLE <u>SLR 5329 H</u> AND OUR CLIENT 'S VEHICLE <u>GY 5698 P</u> ALONG <u>Holland Road &gt;City</u>		

We fax herein the relevant documents to you.

Kindly look into it and arrange for survey as soon as possible.

Thank you.

PSE CALL BACK TEL: 67475484 OR H/P: 81232600

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	07/05/2018 11:09
Date Of Accident	04/05/2018 13:50
Exact Location Of Accident	HOLLAND ROAD > CITY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY5698P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	KOOKA PAPER PRODUCTS PTE LTD
Co Reg No	199801993G
Email Address	KOOKASG@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-90000000

### Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5013814237-11
Cover Note Number	

### Driver

Name of Driver	KOH KIAN SENG
NRIC No	S1666078G
Date Of Birth	15/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	02/03/1992
Driving Experience	26 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-85811128
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 803 TAMPINES AVE 04 #06-75  
 Postcode 520803  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD ON COLLISION  
 Weather Conditions CLEAR  
 Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? YES  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1  
 NAME: AH PING  
 GENDER: MALE

#### Details of Police Action

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name TAMPINES N.P.C  
 Police Station Address ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

#### Circumstances of Accident

AS PER POLICE REPORT No.T/20180505/2125.

#### Attachment(s)

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLR5329H  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category PRIVATE CAR  
 Name of Driver CHONG YEW CHEE  
 NRIC/Passport Number S0081796A  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	KOH KIAN SENG
Approximate Age	53
Injuries Sustain	
Injured person in which vehicle?	GY5698P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	803 TAMPINES AVENUE 4 #06-75
Postcode	520803

**DETAILS OF INJURED PERSON 2**

Name	AH PING
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GY5698P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	YES
Address	
Postcode	



## Accident Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

07 MAY 2018

IDAC KAKI BUKIT (VAC)

23 Kaki Bukit Ave 4

Reporting Centre Personnel's Signature  
Singapore 415933


Name: Tel: 67416697 Fax: 67492305

NRIC/FRNS:

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer  
Police Report

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

07 MAY 2018

IDAC KAKI BUKIT (VAC)  
23 Kaki Bukit Ave 4

Reporting Centre Singapore 415933  
Name Tel: 67416697 Fax: 67492305  
NRIC/ID No Email: vackb@singnet.com.sg

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180505/2125

1 of 3

Police Station Of Origin:  
Tampines N.P.C.  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

Report No. T/20180505/2125

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 05/05/2018 17:59		Vide Report No.:		Station Diary No.: 85
<b>Informant's Particulars</b>				
Name of Informant: KOH KIAN SENG		Address: APT BLK 803 TAMPINES AVENUE 4 #06-75 SINGAPORE 520803		
ID Type / ID No.: NRIC NO / S1666078G		Contact No.: Home/Office: Mobile: 85811128		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 53	Date of Birth: 15/09/1964	Type of Informant: Driver	
Race: Chinese		Language:		Institution / School Name:
Occupation: DELIVERY DRIVER		Driving Licence Information: Class: 3 Date of Expiry:		

## General Information of the Accident

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 04/05/2018 13:50	Type of Location: Straight Road
Location: Along Road 1 HOLLAND ROAD TOWARDS CITY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Controlled by Others e.g. Workmen	Traffic Volume: Light	
Type of Collision: Between Moving Vehicles - Head On			Anyone conveyed by ambulance: Yes	

## Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GY5698P	Lorry				Seriously Damaged	1
SLR5329H	Car				Seriously Damaged	0

## Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20180505/2125

Police Station Of Origin:

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

2 of 3

Report No. T/20180505/2125

## CONTINUATION OF REPORT

Driver			
Name	KOH KIAN SENG	ID No.	S1666078G
Related Vehicle	GY5698P (Lorry)	Contact No.	85811128
Hospital/Clinic	NATIONAL UNIVERSITY HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	04/05/2018	Date Discharge	04/05/2018
No. of Days granted Medical Leave	01	Degree of Injury	Slight

### **Brief Details.**

On 04/05/2018 at about 1350hr, I was driving my vehicle GY5698P towards the city. As I was approaching Coronation Rd West, there was some road works at that area. There was also a traffic marshal that was controlling the traffic. I saw the traffic marshal signaling to me to proceed straight thus I proceed. As I was inching out, a vehicle SLR5329H from the opposite direction was turning into Coronation Rd West collided into the front right side of my vehicle. I got out of the vehicle to take photo of the damages and exchange particulars with the other driver.

I wish to state that traffic police and ambulance came to the incident and I was conveyed to NUH. I was discharge on the same day and was given 1 day MC. However there is no injuries to my passenger. I am lodging this report as I received a call from the traffic police and was advice to lodge a report. I wish to state that I have a in car camera in my vehicle. That's is all.

Accident Sketch Plan Pg. 1



SINGAPORE  
POLICE FORCE



T/20180505/2125

Police Station Of Origin:  
Tampines N.P.C  
6 Tampines Avenue 4 SINGAPORE 529682  
Tel No: 1800-5871999

3 of 3

Report No. T/20180505/2125

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 3 SIM FAWWAZ BIN SIM HASHIM

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

05/05/2018 17:59

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMED FADZLY BIN ABDUL AZIZ

Contact No.: 65472078

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	1993G

### Vehicle Details

Vehicle No.:	GY5698P
Vehicle to be Exported:	No
Intended De-registration Date:	09 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR
Primary Colour:	Silver
Manufacturing Year:	2005
Engine No.:	QD32207276
Chassis No.:	JN1SF4F23Z0854236
Maximum Power Output:	-
Open Market Value:	\$20,311.00
Original Registration Date:	28 May 2005
First Registration Date:	28 May 2005
Transfer Count:	0
Actual ARF Paid:	\$1,016.00

### Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

### Intended COE Rebate Details

COE Expiry Date:	30 Apr 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$27,653.00
COE Rebate Amount:	\$10,922.00
<b>Total Rebate Amount:</b>	<b>\$10,922.00</b>

### Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 09 May 2018

OK

DATA x INFINITY

gives you unlimited data at less than \$2/

Nissan Cabstar

Price Range

Depreciation

&gt; 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » M City Motor Trading » Nissan Cabstar (COE till 08/2020)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Leasing

**CL LEASING**  
YOUR PREFERRED CAR LEASING  
OPTION IN SINGAPORE



6769 7117 8720 5000 8720 8000

## Nissan Cabstar (COE till 08/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

**Price** \$15,800**Depreciation** \$6,960 /yr**Reg Date** 16-Aug-2000  
(2yrs 3mths 6days COE left)**Lifespan** 15-Aug-2020**Manufactured** 2000**Mileage** -**Transmission** Manual**Engine Cap** 3,153 cc**Curb Weight** 1,680 kg**Fuel type** Diesel**Features** -**Accessories** Audio Player.**Description** Super Rare Y Plate Lorry For Sale! Original Paintwork, Good Condition, Well Maintained, Easy In House Loan Available, Trade In Welcome, Call Now!**COE** \$25,292**OMV** \$23,301**ARF** \$1,166**Dereg Value** \$11,489 as of today (change)**No. of Owners** 4**Type of Veh** Truck**Category** COE Car**Availability** Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 06-May-2018 | Last Updated on: 07-May-2018

Tags: Nissan Cabstar, 2000 Nissan Cabstar, Nissan, Cabstar, Used Nissan

## Upfront Payment

» more Financial Info

**Transfer Fee** \$25**Down Payment** \$1,580 (change)

Maximum 90% Loan

**1st Instalment** \$580**Total Upfront Payment** \$2,185 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



Location Map

## Seller Information

## Company

M City Motor Trading

» dealer's pricelist

» 10 vehs sold | 19 vehs available

## Address

180 Woodlands Industrial Park E5  
#01-17

Search cars nearby this location

## Location

Woodlands Auto Hub

## Office No

63658880

## Contact Person(s)

Davis	98265151
Joel Ang	96302488
Jack Tan	96686090

## Useful Services

Make sure of this car condition  
with STA Evaluation.

Vehicle Evaluation

Find out the market value for your car.  
Get a free Car Valuation.

Free Valuation

DATA x  
INFINITY

Compare





## CONNECTING CAR BUYERS &amp; SELLERS.

We'll handle your loans, insurance &amp; other paperwork for FREE.

Find out more



Nissan Cabstar

Price Range

Depreciation

&gt; 10 year

Vehicle Type



Submit

Advanced Search

Home » Used Cars » Direct Owners » Nissan Cabstar (COE till 11/2020)

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Tyres



FORTYTWO

up to 50% off  
MATTRESSES

100 DAY FREE RETURNS

SHOP MATTRESSES

Compare

## Nissan Cabstar (COE till 11/2020)

Overview

Financial

Accessories

Similar

Research

Photos

Map

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price \$17,000

Depreciation \$6,780 /yr

Reg Date 10-Nov-2005  
(2yrs 6mths COE left)

Lifespan 09-Nov-2025

Manufactured 2005

Mileage 500,000 km (40k /yr)

Transmission Manual

Engine Cap 3,153 cc

Curb Weight 1,500 kg

Fuel type Diesel

Features -

Accessories Cargo Roof

Description In Very Good Running Condition.

COE \$22,924

OMV \$19,764

ARF \$989

Dereg Value \$11,493 as of today (change)

No. of Owners 3

Type of Veh Truck

Category COE Car, Direct Owner Sale

Availability Available

DIRECT OWNER

Add to Shortlist

Add to Compare

Add a Note

Posted on: 01-May-2018 | Last Updated on: 08-May-2018

Tags: Nissan Cabstar, 2005 Nissan Cabstar, Nissan, Cabstar, Used Nissan

## Upfront Payment

» more Financial info

Transfer Fee \$25

Down Payment \$1,700 (change) Maximum 90% Loan

1st Instalment \$567

Total Upfront Payment \$2,292 (excluding insurance)

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.

100% FREE  
PAPERWORK  
SUPPORT FOR  
BOTH BUYER  
& SELLER

## Seller Information

Contact Person(s) John Pablo Herrera

Contact No. 97277591

Enquiry Contact Seller

## USEFUL FORMS

- » Indemnity form
- » Receipt
- » M01
- » Sales agreement
- » Hand-over form

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans &amp; insurance for FREE.



## Useful Services



Make sure of this car condition with STA Evaluation.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation





	front windscreen	crooked
	front windscreen rubber	rec
	front wiper garnish	one
	cabstar sticker	rec
	front panel	3x500
	front corner panel o/s	3x500
	front grille	300
	front grille logo	rec
2 pcs	headlamps @	disc one o/s 300
	front signal lamp o/s	300
	front bumper	D.S
	front bumper cover o/s	great
	front bumper bracket o/s	3x5
	front cabin mounting o/s	twisted
	front door pillar o/s	3x500
	front door o/s	300
	front door hinges x2	3x5
	front door cheek o/s	700
	front door inner board o/s	one
	front door inner board clips	rec
	front door Roc sticker o/s	rec
	front door glass o/s	slight
	front door glass moulding o/s	3x5
	front door inner lock o/s	300
	front door rubber o/s	rec
	front dashboard	7
	front dashboard frame	7
	front step garnish o/s	D.S
	front step panel o/s	2 x
	front wheel arch panel o/s	2 x
	front tyre o/s	107
	front door cabstar sticker o/s	rec
	Radiator	200
	Radiator fan blade	one
	brake master pump	?

NO:

645698p

Date:

Air con blower  
Wiper linkage  
ERP bracket  
Front door nls

?

?

me

R X

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 May 2018 <a href="#">Edit Reg</a>		08 May 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)

### CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	<b>TEO SIEW PENG</b> , ID: S1067402F		
Main Claimant:	<b>KOOKA PAPER PRODUCTS PTE LTD</b> , Co. Reg. No.: 199801993G		
Vehicle Reg. No.:	<b>GY5698P</b>	Date of Loss:	04/05/2018 13:00 - :59 [155 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 4211777329SG</b>	Policy/Cover Note No.:	(Third Party Only)
Vehicle Reg. No. (Insured):	<b>SLR5329H</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>TEK SOON MOTOR REPAIR &amp; SPRAY PAINTING (HQ)</b> 1 KAKI BUKIT AVE 6, BLK D #01-93,, AUTOBAY@KAKI BUKIT, 417883 Kaki Bukit - Tel: 67475484		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Kesaval, Jaclyn-M</b> ] Jaclyn-M.Kesaval@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 22/05/2018]		

### ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

### ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*GY5698P (4211777329SG)  
[SLR5329H]**



































**TP**
















































**KOOKA PAPER PRODUCTS PTE LTD**























**May 4 2018 1:00PM**

**[TEO SIEW PENG]**

**TEK SOON MOTOR REPAIR & SPRAY PAINTING**

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<a href="#">View</a> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
2	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
3	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
4	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
5	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
6	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
7	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
8	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
9	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
10	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
11	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
12	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
13	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
14	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
15	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
16	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
17	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
18	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
19	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
20	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
21	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
22	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
23	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
24	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
25	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
26	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
27	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
28	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
29	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
30	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
31	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
32	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
33	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
34	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>
35	11/05/18 18:20	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	11/05/18 18:20	General View	 Load JPG	✓
37	11/05/18 18:20	General View	 Load JPG	✓
38	11/05/18 18:20	General View	 Load JPG	✓
39	11/05/18 18:20	General View	 Load JPG	✓
40	11/05/18 18:20	General View	 Load JPG	✓
41	11/05/18 18:20	General View	 Load JPG	✓
42	11/05/18 18:20	General View	 Load JPG	✓
43	11/05/18 18:20	General View	 Load JPG	✓
44	11/05/18 18:20	General View	 Load JPG	✓
45	11/05/18 18:20	General View	 Load JPG	✓
46	11/05/18 18:20	General View	 Load JPG	✓
47	11/05/18 18:20	General View	 Load JPG	✓
48	11/05/18 18:20	General View	 Load JPG	✓
49	11/05/18 18:20	General View	 Load JPG	✓
50	11/05/18 18:20	General View	 Load JPG	✓
51	11/05/18 18:20	General View	 Load JPG	✓
52	11/05/18 18:20	General View	 Load JPG	✓
53	11/05/18 18:20	General View	 Load JPG	✓
54	11/05/18 18:20	General View	 Load JPG	✓
55	11/05/18 18:20	General View	 Load JPG	✓
56	11/05/18 18:20	General View	 Load JPG	✓
57	11/05/18 18:20	General View	 Load JPG	✓
58	11/05/18 18:20	General View	 Load JPG	✓
59	11/05/18 18:20	General View	 Load JPG	✓
60	11/05/18 18:20	General View	 Load JPG	✓
61	11/05/18 18:20	General View	 Load JPG	✓
62	11/05/18 18:20	General View	 Load JPG	✓
63	11/05/18 18:20	General View	 Load JPG	✓
64	11/05/18 18:20	General View	 Load JPG	✓
65	11/05/18 18:20	General View	 Load JPG	✓
66	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
67	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
68	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
69	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
70	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
71	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
72	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
73	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
74	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
75	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
76	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
77	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
78	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
79	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
80	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
81	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
82	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
83	19/06/18 20:23	Dismantled Parts	Load JPG	✓

Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
85	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
86	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
87	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
88	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
89	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
90	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
91	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
92	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
93	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
94	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
95	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
96	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
97	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
98	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
99	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
100	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
101	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
102	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
103	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
104	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
105	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
106	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
107	19/06/18 20:23	Dismantled Parts	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	14/05/18 09:58	OI GIA REPORT	 Load PDF	

## Documents Checklist

### DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18008648/UZ4BS2

Date: 31/08/2018

## REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GY5698P

Insured Vehicle No : SLR5329H

Date of Loss: 04/05/2018

Nature of Claim: TP

Claim No: 4211777329SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: GY5698P

Make &amp; Model: NISSAN CABSTAR, 3.2 D (M)

Engine No: QD32207276

Reg. Date: 28/05/2005 (Man. Year: 2005)

Chassis No: JN1SF4F23Z0854236

Colour: Silver

Odometer: 498947 km

Engine Capacity: 3153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size:

155 R12 (D)

Front Left Side: Michelin 5 mm

Rear Left Side:

Michelin 5/5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side:

Yokohama 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 08/05/2018

TEK SOON MOTOR REPAIR &amp; SPRAY PAINTING (HQ)

Date Inspected: 09/05/2018 Inspected At:

1 KAKI BUKIT AVE 6, BLK D #01-93,,  
AUTOBAY@KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN	Cracked	0.00 F	*- F
2	1		*FRONT WINDSCREEN RUBBER	Necessary	0.00 F	*- F
3	1		*FRONT WIPER GARNISH	Cracked	0.00 F	*- F
4	1		*CABSTAR STICKER	Necessary	0.00 F	*- F
5	1		*FRONT PANEL	Badly Dented	0.00 F	*- F
6	1		*FRONT CORNER PANEL O/S	Badly Dented	0.00 F	*- F
7	1		*FRONT GRILLE	Broken	0.00 F	*- F
8	1		*FRONT GRILLE LOGO	Necessary	0.00 F	*- F
9	2		*HEADLAMPS	N/s Cracked / O/s Broken	0.00 F	*- F
10	1		*FRONT SIGNAL LAMP O/S	Broken	0.00 F	*- F
11	1		*FRONT BUMPER	Distorted	0.00 F	*- F
12	1		*FRONT BUMPER COVER O/S	Grazed	0.00 F	*- F
13	1		*FRONT BUMPER BRACKET O/S	Bent	0.00 F	*- F
14	1		*FRONT CABIN MOUNTING O/S	Twisted	0.00 F	*- F
15	1		*FRONT DOOR PILLAR O/S	Badly Dented	0.00 F	*- F
16	1		*FRONT DOOR O/S	Buckled	0.00 F	*- F
17	2		*FRONT DOOR HINGES	Bent	0.00 F	*- F
18	1		*FRONT DOOR CHECKER O/S	Twisted	0.00 F	*- F
19	1		*FRONT DOOR INNER BOARD O/S	Cracked	0.00 F	*- F
20	1		*FRONT DOOR INNER BOARD CLIPS	Necessary	0.00 F	*- F
21	1		*FRONT DOOR ROC STICKER O/S	Necessary	0.00 F	*- F
22	1		*FRONT DOOR GLASS O/S	Shattered	0.00 F	*- F
23	1		*FRONT DOOR GLASS MOULDING O/S	Bent	0.00 F	*- F
24	1		*FRONT DOOR INNER LOCK O/S	Jammed	0.00 F	*- F
25	1		*FRONT DOOR RUBBER O/S	Necessary	0.00 F	*- F
26	1		*FRONT DASHBOARD	*Check	0.00 F	*- F
27	1		*FRONT DASHBOARD FRAME	*Check	0.00 F	*- F
28	1		*FRONT STEP GARNISH O/S	Distorted	0.00 F	*- F
29	1		*FRONT STEP PANEL O/S	Repair	0.00 F	*- F
30	1		*FRONT WHEEL ARCH PANEL O/S	Repair	0.00 F	*- F
31	1		*FRONT TYRE O/S	Cut	0.00 F	*- F
32	1		*FRONT DOOR CABSTAR STICKER O/S	Necessary	0.00 F	*- F
33	1		*RADIATOR	Punctured	0.00 F	*- F
34	1		*RADIATOR FAN BLADE	Cracked	0.00 F	*- F
35	1		*BRAKE MASTER PUMP	*Check	0.00 F	*- F
36	1		*AIRCON BLOWER	*Check	0.00 F	*- F
37	1		*WIPER LINKAGE	*Check	0.00 F	*- F
38	1		*ERP BRACKET	Necessary	0.00 F	*- F
39	1		*FRONT DOOR N/S	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)

0.00

0.00

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >