

LC: 654H

10. PRELIM

STJ2697E

2008, Sept

Type: ☒ M Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Trail / ☐ Prime Mover /

Truck / Trailer or

Make: Head Fit

1339

Color: Blue

AN Insured / Std / NI / NA

Ch. Register: 219091

U/Insured Insured / Std / NI / NA

Eng/Hdr

C/Nr: GE 61104117

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt

Mod: ☒ Nil / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size: F: 135/55R15

R: 135/55R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Cassa

Front

Rear

R/Bal: 06 mm

R/Bal: 06 mm

L/Bal: 06 mm

L/Bal: 06 mm

D.O.A

D.O.A

Survey held at

Dynamic

Des. of Damages: ☒ Frl / ☐ Rear / ☐ Q/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Standard Code
Type: TP / WS / LP / RES / OO / RES / EVA / INV / MY
Technical Vehicle No.
Vehicle description
ed
Insured
Policy No.
Claim No.
Insured
Excess
Vehicle's Record
Make of Vehicle

N/S	Q/S

(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection

Estimated Market Value

Consistent? Yes or No

Estimated Repair

Consistent? Yes or No

Estimated PP Cost

days Res. Yes or No

Estimated Repairs

3 Val Yes or No

Estimated

CA / REV / REP / 24 HRS

Vehicle IN / OUT

Date

Person Contacted

Date / Time

Action / Instruction
TP China

COE Exping: 04/09/23

MV: 201C
PV: 9-5K
Nett: 10-5K

C/S \$4800.00 (Red \$6917-04, 59%)

Date/Time: File/Photo

☐

Prel. Report

File

Date/Time: File/Photo

☐

Final Report

Days Of Repair: 6

Resurvey No. of Trip:

Survey Date

Inspection

File

File

File

File/Photo

☐

Site Insp

☐

Inspection

☐

File/Photo

Date/Time: File/Photo

C/S \$4800/-