

ASS. REC. BY:

REF: CS/MSG20010185/AGqf3

Special Instruction:

Surveyor: ADRIAN ASSIGNMENT (Office)

From (Person): Katherine Wong of MSIG Date/Time: 22 Sep 2020 16:34

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD  TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLB 4026Y Insured: SMQ 5688P

at Workshop m/s Sin Yu Sin Workshop (HQ) Tel: 91993103/97825292

of 1 Kaki Bukit Ave 6 #01-52 (Auto Bay @ Kaki Bukit), 417883 Kaki Bukit

Policy No: 29138602AVW Claim No: 628889

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 19/09/2020  
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 23-9-20 9.02 A.M Person Contacted: WEI LEANG Vehicle  IN  OUT

Date/Time	Action/Instruction ( <input checked="" type="checkbox"/> ) Estimate
	SLB 4026Y- <del>X</del>
	SMQ 5688P- <del>X</del>