

Your Ref: A0258513

Date: 03rd Nov 2020

Our Ref: CS1/LAW20010193/Ktf3e2

M/s Tokio Marine Insurance Singapore Ltd

C/o : Tan Kok Quan Partnership

1 Wallich Street #07-02

Guoco Tower

Singapore 078881

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJM 7710B**INSURED VEHICLE: VAQ 6200****ACCIDENT DATE: 05/06/2018**

We thank you for your instruction on 23/09/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJM 7710B from M/s Infiniti Appraisal Service.
- b) Final Repair Bill of SJM 7710B from M/s Hui Yang Motor Pte Ltd.
- c) Singapore Accident Statement of Vehicles SJM 7710B.
- d) Police Report of Vehicles SJM 7710B and VAQ 6200..
- e) Colour damaged vehicle photographs of SJM 7710B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJM 7710B
Make & Model	: Toyota Wish 1.8 Auto
Chassis Number	: JTDER12W403001637
Year of Registration	: 2009
Engine Capacity	: 1794 cc

2. We recommend that the repairs of the entire damage require about 10 (Ten) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.