

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/09/2020 08:50
Date Of Accident	18/09/2020 17:25
Exact Location Of Accident	OPEN AIR CARPARK AT BLK 410, ANG MO KIO AVE 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SFQ1878S
Insured/Policyholder	
Name Of Registered Owner	MUI WHYE KEE
NRIC No	S6918035C
Email Address	WHYEKEE@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-91272919
Alternative Phone No	Others-91272919

Vehicle Particulars

Manufacturer	TOYOTA
Model	NEW CAMRY 2.5
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100465292-04
Cover Note Number	

Driver

Name of Driver	MUI WHYE KEE
NRIC No	S6918035C
Date Of Birth	03/06/1969
Occupation	INDOOR
Date Of Driving Pass	30/07/1993
Driving Experience	27 YEARS AND 1 MONTH

Gender	MALE
Mobile Number	(LOCAL) +65-91272919
Fax Number	
Contact Number	OTHERS-91272919
E-Mail Address	WHYEKEE@SINGNET.COM.SG
Address	172B EDGEDALE PLAINS #14-480 SINGAPORE
Postcode	822172
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD ON COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WSVC20001469 Accident_Scenario Upload the drawing sketch plan WSV20001469 Accident_Description I Mui Whye Kee NRIC No S6918035C is the driver of SFQ1878S a silver Toyota Camry. On 18 Sep 2020 at around 1725 hrs I was attempting to do vertical parking at the open air carpark at Blk 410 Ang Mo Kio Ave 10. Vehicle SGU5996A a grey Mercedes Benz was following closely behind. I was attempting to park my vehicle at an empty carpark lot. After checking the rear mirror and confirmed that there was sufficient distance between my vehicle and the rear vehicle I positioned my vehicle to prepare for vertical parking. As I was reversing into the lot SGU5996A continues to inch forward and subsequently scratched the front left bumper of my vehicle. It resulted in some scratches on the left side of the front bumper. Some scratches were observed on the right hand front bumper of vehicle SGU5996A. My vehicle SFQ1878S has the luminous P-plate sign clearly displayed at the top right portion of the rear windscreen. SGU5996A should have paid more attention and gave my vehicle sufficient space to complete the vertical parking. The driver also attempted to pressure me to admit fault by accusing me of drink driving. I told him firmly I did not. We need to exhibit more graciousness to fellow motorists.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGU5996A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Driving License

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S6918035C

Name

MUI WHYE KEE


Birth Date: 03 Jun 1969

Issue Date: 07 Nov 2003

000972924H



Driving License



Identification Card



Identification Card

