

SLP45666.

Toyota Axio. 1486CC

NZE1416060587

Rear Bumper	Rebond	✓
Rear Bumper Clips.	Nec	✓
Rear Bumper Side Holder x02	Nec	✓
Rear Bumper Impact Bracket x02	Nec	X
Reverse Sensor.	Damaged	✓
Rear End Panel.	Dented	✓
Rear End Panel Top Garnish.	Rebond	✓
Rear End Panel Sealant.	Nec	✓
Taillamp x02	Cracked	✓
Taillamp Lower Bracket	LH. cracked	✓
Bootlid	Dented	✓
Bootlid Lock	OK	✓
Bootlid Weatherstripe.	OK	✓
Bootlid Outer Moulding.	Cracked	✓
Spare Tyre Panel Top Cover.	XLP Nec	X