

ASS. REC. BY: *Mcclus*

REF: CC4/Fc/20010222/4 da 3

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBP 30782

at Workshop m/s BMH

of _____

Insured: SMC 83802

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:	<u>614</u>	
IDAC Accident Rpt:	Consistent? : Yes or No	
GIA / PR Seen:	Consistent? : Yes or No	
Est. Repairs:	<u> </u> days	Res.: Yes or No
Lum Sum:	<u> </u> %	3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: F550782 Yr Regn: 5117
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Maruti CB300R c.c 286
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading 12012 T/Radio: Insured / Std / NI / NA
Eng/No:
C/No: MLHNC5578J5002287
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or offed
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 110 - 70 R 17
R: 150 - 60 R 17
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. mm L/Bal. mm
D.O.A. 16/9/20 D.O.I. 23/9/20
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
n/s frt, o/s body
The U/C / Chassis frame / Body Structure/ affected due to collision.

Date / Time	Action / Instruction
	NV \$14,000
	CTA \$2525
	NV \$11495
	Reject case?

Date/Time, File Pass to?

☐ : Preli. Report

1)

□: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: : Site Insp (\$

☐ : Site Insp (\$

$$) \quad \underline{\hspace{1cm}} S + RS, \underline{\hspace{1cm}} SI$$

☐: Interview (\$

) Photos

Tech. Invs (\$)

Others

: Weekend (\$)

2

Report Format :

Lump Sum / I.B.I: (\$)

TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	203B
Vehicle Details	
Vehicle No.:	FBP3078Z
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Sep 2020
Vehicle Make:	HONDA
Vehicle Model:	CB300R ABS MANUAL
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	NC55E0002287
Chassis No.:	MLHNC5578J5002287
Maximum Power Output:	-
Open Market Value:	\$5,334.00
Original Registration Date:	08 Mar 2019
First Registration Date:	08 Mar 2019
Transfer Count:	1
Actual ARF Paid:	\$917.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Mar 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$2,989.00
COE Rebate Amount:	\$2,525.00
Total Rebate Amount:	\$2,525.00

The information contained herein is correct as at 23 Sep 2020

OK

Vehicle Details

Vehicle No.	Make / Model
FBP3078Z	HONDA / CB300R ABS MANUAL
Vehicle Type :	Vehicle Attachment 1 :
P00 - Passenger Motorcycle/Autocycle /Moped	No Attachment
Vehicle Scheme :	Chassis No. :
Normal	MLHNC5578J5002287
Propellant :	Engine No. :
Petrol	NC55E0002287
Motor No. :	Engine Capacity :
-	286 cc
Power Rating :	Maximum Power Output :
-	-
Maximum Laden Weight :	Unladen Weight :
325 kg	143 kg
Year Of Manufacture :	Original Registration Date :
2018	08 Mar 2019
Lifespan Expiry Date :	COE Category :
-	D - Motorcycle
Quota Premium :	COE Expiry Date :
\$2,989.00	07 Mar 2029
Road Tax Expiry Date :	PARF Eligibility Expiry Date :
07 Mar 2021	-
Inspection Due Date :	Intended Transfer Date :
07 Mar 2022	22 Sep 2020
CO2 Emission :	CEV/VES Rebate Utilised Amount :
-	-
CO Emission :	HC Emission :