

LKE

AIG

COMFORTDELGRO ENGINEERING PTE LTD

Date: 23.09.2020

Time: 17:46:54

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305424311
 REGN NO : SHA3884X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 18.06.2015
 DATE/TIME IN : 23.09.2020 15:15
 ACCIDENT DATE : 23.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0103-2322-A	I40V3 BUMPER W LIP & FOG	1	1,052.20	20.00	841.76	de
0002	04-01-0103-0637-G	I40VC BRKT ASSY-FR BPR UP	1	22.40	20.00	17.92	?
0003	04-01-0103-0639-G	I40VC BRACKET-FR BUMPER S	1	24.60	20.00	19.68	?
0004	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	nee ✓
0005	04-01-0103-0574-G	I40VC PANEL-FENDER LH#	1	663.00	20.00	530.40	Rx
0006	04-01-0103-2834-A	I40V3 GUARD ASSY-FRONT WH	1	174.90	20.00	139.92	de ✓
0007	04-01-0103-0781-A	I40VC LAMP ASSY-HEAD LH#	1	1,388.00	20.00	1,110.40	cut ✓
0008	04-01-0103-0658-G	I40VC CAP ASSY-WHEEL HUB	1	112.50	20.00	90.00	cut ✓

SUB-TOTAL : 2,767.68

JOB NATURE

0000 L	PANEL BEATING	600.00	420
0001 23-502	SPRAYPAINT ON AFFECTED AREA	450.00	400
0002 17-01	CHECK ALL LIGHTING	50.00	30

Tan Kah 97445749
 WP 24/9/20 2-3 days
 L/S Resurvey after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from the

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 23.09.2020

Time: 17:46:54

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305424311
REGN NO : SHA3884X
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 18.06.2015
DATE/TIME IN : 23.09.2020 15:1
ACCIDENT DATE : 23.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-00 TUFF COAT ON AFFECTED PARTS.

50.00 30

0004 20-08 ADJUST FRONT WHEEL ALIGNMENT

80.00 60

SUB-TOTAL : 1,230.00

TOTAL : 3,997.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

53 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

420 Selegie Road Singapore 117649

24 Senoko Loop Singapore 758158

7 Sungei Kadut Way Singapore 728755

501 Yishun Industrial Park A Singapore 768699

Date/Time: 23.09.2020 17:10

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO.: 305424311

OWNER

AS COMFORT TRANSPORTATION PTE LTD
7010045

OWNER NO. 383 SIN MING DRIVE
RESS Singapore SINGAPORE 575717
65508755

(R)

(O)

(P)

OUNT CARD NO.

REGN NO. SHA3884X

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....

MODEL I-40

DATE/TIME IN 23.09.2020 15:15

YR OF MANU. 18.06.2015

TARGET DATE

CHASSIS CODE KMHLB41UMFU069545

COMPLETION DATE/TIME

JOB DESCRIPTION


Accident Date: 23.09.2020

NATURE: 3P 232.09.2020

3/NO

LABOR CODE

DESCRIPTION



BOOKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: SHA3884X

LKE

Vehicle No.:

SHA3884X

Service Advisor

Signature/Date

Name of Service Advisor

Date

Turned to Service Representative