

ASS. REC. BY:

REF:

CS/A1h 200 10277/R19d3

8254

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____


OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SME 9496Mat Workshop m/s CYCLE & CARRIAGEof 209, PANDAN GARDENInsured: MLPolicy No. 1800124828Claims No. 2851751159SGSum Insured: _____ Excess: TBA 300

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 68K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SME 9496M Yr Regn: 2018 / OCTType: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: KIA CERATO 1.6 CAT EX c.c. 1591Colour: BLACK A/C: Insured / Std / NI / NASp. Reading: 18504 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNMF 3416 MK 5019120Gen. Cond: Good / FA / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or NEXEN

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 24/09/2020D.O.I. 28/09/2020Survey held at CYCLE CARRIAGEDes. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/09/20@10.55am revert to Victor via Merimen.

28/09/20@11.09am Thaddaeus Ng informed C/A via Merimen.

28/09/20@12.38pm Informed Coco C/A & ex: TBA by email.

28/09/20@2.55pm Informed Coco ex:\$300/- by email.

15/10/20@6.55pm Rasul finalised with Ai Thing final fig \$7450, 5 days. (Red \$3122, 30%)

Date/Time, File Pass to?

☐ : Prel. Report

16/10 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: MER-OD7450Days Of Repair: 5Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

o Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Ezrein Shah Bin Selamat Reg No/Reg Date SME9496M*ECB / 24/10/201 Date In/Mileage / 0 Chassis No KNAF3416MK5019120 Engine No G4FGJH710275 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	24/09/2020/ 14:51	BLC	442 / CocoLu	21629		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2000.00
RENEW FRT BUMPER, FRT FENDER RH, BONNET, FRT SUPPORT PANEL							1000
REPAIR FRT DOOR RH							1400
E PNT98000							1750.00
SPRAY PAINT FOR FRT BUMPER, BONNET, FRT FENDER RH, FRT DOOR RH							?
E PNT88000							100.00
REMOVE & INSTALL AIRCON							?
M SUNDRY							80.00
TOP UP AIRCON GAS							30.00
A 90000001							120.00
CHECK WIRING & ELECTRICAL SYSTEM							40.00
A 10028901							20.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							
APPLY SEALANT FOR ACCIDENT PORTION							
M SUNDRY							
Sundry							
M	COVER-FR BUMPER	de		1.00	633.00	20.00	506.40
M	GRILLE-FRONT BUMPER	?		1.00	262.00	20.00	209.60
M	COVER-FR BUMPER FOG LAMP, RH	de	?	1.00	15.00	20.00	12.00
M	GRILLE ASSY-RADIATOR	cm	?	1.00	328.00	20.00	262.40
M	MOULDING-FRONT BUMPER, RH	?		1.00	36.00	20.00	28.80
M	LAMP ASSY-SIDE REPEATER, RH	?		1.00	143.00	20.00	114.40
M	AIR DUCT-FR BUMPER, RH	?		1.00	14.00	20.00	11.20
M	ABSORBER-FRONT BUMPER ENERGY	cm	?	1.00	84.00	20.00	67.20
M	BRACKET-FR BUMPER UPR SIDE MTG	?		1.00	22.00	20.00	17.60
M	PANEL ASSY-HOOD	st	?	1.00	1502.00	20.00	1201.60
M	PANEL-FENDER, RH	st	?	1.00	430.00	20.00	344.00
M	GUARD ASSY-FRONT WHEEL, RH	X		1.00	95.00	20.00	76.00
M	BEAM COMPLETE-FR BUMPER	?		1.00	497.00	20.00	397.60
M	CARRIER ASSY-FRONT END MODULE	?		1.00	675.00	20.00	540.00
M	LAMP ASSY-HEAD, RH	cm	?	1.00	1219.00	20.00	975.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Ezrein Shah Bin Selamat Reg No/Reg Date SME9496M*ECB / 24/10/201 Date In/Mileage / 0 Chassis No KNAF3416MK5019120 Engine No G4FGJH710275 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	24/09/2020/ 14:51	BLC	442 / CocoLu	21629			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RESERVOIR & PUMP ASSY-WASHER ?				1.00	146.00	20.00	116.80
M	GUARD-AIR,RH ?				1.00	28.00	20.00	22.40
M	CONDENSER ASSY-COOLER ?				1.00	687.00	20.00	549.60
M	RADIATOR ASSY ?				1.00	646.00	20.00	516.80

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rasul - Hp 90010018SURVEYOR SIGNATURE: [Signature]DATE: 25/09/2020 @ 1040REMARKS: 5 daysRenew / excess: TBARenew before paint

Confirm & accepted by

Nett	10,109.60
7% GST on	707.67
Total Payable	10,817.27

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 24/09/2020 15:23
Date Of Accident 24/09/2020 11:55
Exact Location Of Accident JALAN MASJID/UPPER CHANGI ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SME9496M
Insured/Policyholder
Name Of Registered Owner EZREIN SHAH BIN SALEMAT
NRIC No SXXXX825H
Email Address ENG90253@YAHOO.COM.SG
Mobile Phone No (LOCAL) +65-97619295
Alternative Phone No OTHERS-97619295

Vehicle Particulars

Manufacturer KIA
Model CERATO-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident BUY GROCERIES

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 1800124828
Cover Note Number

Driver

Name of Driver EZREIN SHAH BIN SALEMAT
NRIC No SXXXX825H
Date Of Birth 28/07/1978
Occupation OUTDOOR
Date Of Driving Pass 20/07/2010
Driving Experience 10 YEARS AND 2 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-97619295
Fax Number
Contact Number OTHERS-97619295
EMail Address ENG90253@YAHOO.COM.SG

Address	BLK 348 TAMPINES STREET 33 #07-412
Postcode	520348
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBK1536H
Vehicle Make/Model/Colour	TOYOTA HIACE
Details Of Properties	RIGHT HAND BUMPER
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUHAMMAD USMAN S/O SHAHID JAVAID
NRIC/Passport Number	SXXXX262H
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

- ACCIDENT HAPPENED AT THE JUNCTION OF SALAN MASSIO AND UPPER CHANCHI ROAD.
- CARS WERE PARKED ON THE LEFT SIDE OF THE T-JUNCTION AND SEVERAL TRUCKS INCLUDING A LORRY WAS ILLEGALLY PARKED ON THE RIGHT SIDE OF SALAN MASSIO.
- AT 11:51AM, TURNING RIGHT ONTO UPPER CHANCHI, AFTER CHECKING TRAFFIC CLEAR ON THE LEFT, I PROCEEDED TO TURN RIGHT AND BEFORE I COULD BRAKE, HIT A VAN THAT STOPPED SUDDENLY BECAUSE OF THE LORRY THAT WAS PARKED ILLEGALLY HAD STARTED TO MOVE OFF.
- BECAUSE OF THAT, I HAD NO TIME TO BRAKE AND HIT THE RIGHT BUMPER OF THE VAN (GBK 15364).
- THE LORRY THAT WAS PARKED ILLEGALLY WAS OF THE LICENSE PLATE (YP 39045).

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Ezrein Shah Bin Selamat
Period of Insurance : 24 Oct 2018 To 23 Oct 2020
Engine No. : G4FGJH710275
Chassis No. : KNAF3416MK5019120

Vehicle No. : SME9496M
Policy No. : 1800124828
Endorsement No. :
Issued Date : 02 Nov 2018

ABOUT THE COVER

Make/Model : KIA Cerato
Engine Capacity/Tonnage : 1,591.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 - b) Any other person who is driving on the Policyholder's order or with his/her permission.
- This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition
Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Ezrein Shah Bin Selamat - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
3. Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504624050
 FULCOKICP2 - CORPORATE
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monile

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:

Singapore NRIC

Owner ID:

825H

Vehicle No.:

SME9496M

Vehicle to be Exported:

No

Intended Deregistration Date:

27 Sep 2020

Vehicle Make:

KIA

Vehicle Model:

CERATO 1.6(A) EX

Primary Colour:

Blue

Manufacturing Year:

2018

Engine No.:

G4FGJH710275

Chassis No.:

KNAF3416MK5019120

Maximum Power Output:

93.8 kW (125 bhp)

Open Market Value:

\$13,841.00

Original Registration Date:

24 Oct 2018

First Registration Date:

24 Oct 2018

Transfer Count:

0

Actual ARF Paid:

\$13,841.00

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 Oct 2028

PARF Rebate Amount:

\$10,380.00

COE Expiry Date:

23 Oct 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$30,209.00

COE Rebate Amount:

\$24,379.00

Total Rebate Amount:

\$34,759.00

The information contained herein is correct as at 27 Sep 2020

OK



Merimen e-Claims



Used 2018 Kia Cerato 1.6A EX for



PARF/COE

carmart.com/used_cars/info.php?ID=928201&DL=2140

Kia Cerato 1.6A EX

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price

\$68,555

Depreciation ?

\$7,610 /yr

View models with similar depre

Reg Date

31-Oct-2018

(8yrs 1mth 3days COE left)

Mileage

38,000 km (19.9k /yr)

Manufactured ?

2018

Road Tax ?

\$738 /yr

Transmission

Auto

Dereg Value ?

\$34,934 as of today (change)

OMV ?

\$13,970

COE ?

\$30,209

ARF ?

\$13,970

Engine Cap

1,591 cc

Power

93.8 kW (125 bhp)

Curb Weight ?

1,287 kg

No. of Owners ?

1

Type of Vehicle

Mid-Sized Sedan

Features

Gamma 1.6 MPI Engine, 125Bhp, Torque 155Nm, 0-100 Km/h In 12s, 6 Speed (A)Transmission, 15.1Km/L Fuel Consumption, Keyless Start/Stop, Cruise Control.

Accessories

Keyless Entry/Start/Stop, 8" Touchscreen Infotainment System With Bluetooth, Apple CarPlay/Android Auto, Reverse Cam, Drive Mode Select, Sports Rims.

STORY



Dc

