




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS/SMO20010281/Kyd3e2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 03-11-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMJ 7247C	Veh. Inspected	SLX 8747H	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2002791/IJH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	24/09/2020	
2. Vehicle Particulars & Condition				
Make & Model	CHEVROLET ORLANDO (A)	c.c	1362	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KL1YA7589HK605546	Colour	WHITE	
Odometer	106284	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	YOKOHAMA	8 mm	
L/H Front Tyre	225/45 R18	YOKOHAMA	8 mm	
R/H Rear Tyre	225/45 R18	YOKOHAMA	8 mm	
L/H Rear Tyre	225/45 R18	YOKOHAMA	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/09/2020	Inspection Date	25/09/2020	
Survey held at	S THREE AUTOMOTIVE & RECOVERY PTE LTD BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		