

ASS. REC. BY: Paul

REF:

CS/AH20010285/R1d3

710F

## ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SMR 3113Pat Workshop m/s CYCLE & CARRIAGEof 209, PANDAN GARDEN

Insured:

Policy No.:

Claims No.:

Sum Insured:

Excess:

TBA

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

102k

IDAC Accident Rpt:

Consistent? : Yes or No

G/A / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMR 3113P

Yr Regn:

2019, NOVType: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

MITSUBISHI ECLIPSE CROSS 1.5 1499

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading:

022575

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

3MAXTGKIWL2000609Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or .

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

24/09/2020

D.O.I.

29/09/2020

Survey held at

CYCLE & CARRIAGEDes. of Damages ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format:

Lump Sum / U/C:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV01710/LIM JOO YONG Reg No/Reg Date SMR3113P / 18/11/201 Date In/Mileage / 0 Chassis No JMAXTGK1WLZ000609 Engine No 4B40HB0394 Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR Colour/Trim D00 LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	24/09/2020/ 16:26	QUD	247 / DonBong	57754		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, REPAIR RH FRONT DOOR				@450x2			900 2250.00
E PNT88000 REMOVE AND INSTALL PARKING ASSIST							60.00
E PNT88000 REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK							? 100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM							? 80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTION				@350x3			1050 2100.00
M SUNDRY PERFORM RUST PREVENTION							X 80.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							30.00
M SUNDRY APPLY BODY SEALANT							X 80.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME							50.00
M SUNDRY SUNDRIES							20 50.00
M PNL,HEADLAMP SUPT,UPR RH				1.00	59.00	23.00	45.43
M PANEL,HEADLAMP SUPPORT,UPR				1.00	171.00	23.00	131.67
M PNL,HEADLAMP SUPT,UPR LH				1.00	59.00	23.00	45.43
M PANEL,HEADLAMP SUPPORT,LWR				1.00	219.00	23.00	168.63
M PANEL,AIR GUIDE SIDE,RH				1.00	82.00	23.00	63.14
M PANEL,AIR GUIDE SIDE,LH				1.00	82.00	23.00	63.14

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV01710/LIM JOO YONG Reg No/Reg Date SMR3113P / 18/11/201 Date In/Mileage / 0 Chassis No JMAXTGK1WLZ000609 Engine No 4B40HB0394 Make/Model MIT/ECLIPSE CROSS 1.5 T/C STYLE SR Colour/Trim DOO LIGHTNING BLUE / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	24/09/2020/ 16:26	QUD	247 / DonBong	57754			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M CONDENSER ASSY,A/C REFRIGE ?					1.00	701.00	23.00	539.77
M LLC 4L ?					1.00	26.00	23.00	20.02
M COVER,FR BUMPER GRILLE ?					1.00	302.00	23.00	232.54
M GRILLE ASSY,RADIATOR ?					1.00	484.00	23.00	372.68
M CLIP,FR BUMPER na /					1.00	4.00	23.00	30.80
M BRKT,F/BMPR T/SIG LAMP,LH ?					1.00	17.00	23.00	13.09
M BRKT,F/BMPR T/SIG LAMP,RH ?					1.00	17.00	23.00	13.09
M FACE,FR BUMPER de /					1.00	714.00	23.00	549.78
M COVER,FR BUMPER cut /					1.00	380.00	23.00	292.60
M EXTENSION,FR BUMPER scd /					1.00	317.00	23.00	244.09
M LH GARNISH,FR BUMPER SIDE cut /					1.00	214.00	23.00	164.78
M RH GARNISH,FR BUMPER SIDE ca /					1.00	214.00	23.00	164.78
M LH GARNISH,FR BUMPER SIDE ?					1.00	73.00	23.00	56.21
M RH GARNISH,FR BUMPER SIDE in /					1.00	77.00	23.00	59.29
M REINFORCEMENT,FR BUMPER ?					1.00	552.00	23.00	425.04
M BAR,FR BUMPER GUARD ?					1.00	100.00	23.00	77.00
M BRACKET,FR BUMPER SIDE,LH ?					1.00	18.00	23.00	13.86
M BRACKET,FR BUMPER SIDE,RH ?					1.00	18.00	23.00	13.86
M LH CTR SENSOR,FWD DISTANCE WARNIN mtr ?					1.00	329.00	23.00	253.33
M RH CTR SENSOR,FWD DISTANCE WARNIN 3 dis /					1.00	329.00	23.00	253.33
M LH SENSOR,CORNER CLEARANCE X					1.00	329.00	23.00	253.33
M RH SENSOR,CORNER CLEARANCE X					1.00	329.00	23.00	253.33
M HEADLAMP ASSY,LH ?					1.00	1976.00	23.00	1521.52
M HEADLAMP ASSY,RH ca /					1.00	1976.00	23.00	1521.52
M LAMP A,T/SIG & FOG,FR LH X					1.00	506.00	23.00	389.62
M LAMP A,T/SIG & FOG,FR RH ?					1.00	506.00	23.00	389.62
M FRONT BUMPER GARNISH ?					1.00	384.00	23.00	295.68
M FRONT CORNER EXTENSION ?					1.00	238.00	23.00	183.26
M FENDER,FR RH rgr					1.00	599.00	23.00	461.23
M PAD,FR FENDER					1.00	57.00	23.00	43.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- Is subject to final approval from insurance

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

SURVEYOR NAME: Robert Hy 90000018

SURVEYOR SIGNATURE: [Signature]

24/09/2020 @ 10:20

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice"
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed

is subject to final approval from insurance

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Resurvey

SURVEYOR SIGNATURE: Resurvey

DATE: 24/09/2020 @ 10:20

REMARKS: 5 days

Resurvey before paint

Confirm &amp; accepted by

DATE:

REMARKS:

Resurvey before paint

Authorized signatory and company stamp

Nett

14,620.38

GST on

1023.43

Total Payable

15,643.81

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The Issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	24/09/2020 16:14
Date Of Accident	24/09/2020 07:30
Exact Location Of Accident	PIE 600M BEFORE EUNOS LINK EXIT
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMR3113P
<b>Insured/Policyholder</b>	
Name Of Registered Owner	LIM JOO YONG
NRIC No	SXXXX710F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97380628
Alternative Phone No	OTHERS-97770628

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	ECLIPSE CROSS-1.5 CVT S/R (A)
Exact Purpose for which vehicle was being used at time of accident	PERSONAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1900247717
Cover Note Number	

### Driver

Name of Driver	LIM JUN AN,LESTER
NRIC No	SXXXX075D
Date Of Birth	25/11/1995
Occupation	INDOOR
Date Of Driving Pass	04/02/2016
Driving Experience	4 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97770628
Fax Number	
Contact Number	
EEmail Address	LESTERLIM.JA@GMAIL.COM



Address BLK 213 JURONG EAST STREET 21 #08-287  
Postcode 600213  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured CHILDREN  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident CHAIN COLLISION  
Weather Conditions JUST AFTER RAIN/LIGHT DRIZZLE  
Road Surface WET

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 3  
Was any body injured in the Accident? NO  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO  
If Yes, Please state which Police Station  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? YES  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number SKL2327B  
Vehicle Make/Model/Colour MERCEDES/C-200/SILVER  
Details Of Properties 2ND CAR  
Vehicle Category PRIVATE CAR  
Name of Driver LEE TONG LENG  
NRIC/Passport Number SXXXX942B  
Contact Number 91792339  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

#### DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number SJX3114R

Vehicle Make/Model/Colour

TOYOTA/COROLLA ALTIS/BRONZE

Details Of Properties

1ST CAR

Vehicle Category

PRIVATE CAR

Name of Driver

VELOO S/O SUPPIAH

NRIC/Passport Number

SXXXX151E

Contact Number

97304051

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims, (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 24/07/20 14:40

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #2

### SKETCH PLAN



### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on the PIE Towards Changi on the right lane. The vehicle in front of me had to jam brake because there was a Mercedes. At about 600m along from the Eunos Link Exit, the Mercedes, SKL2322B, in front of me applied brakes to a stop because the car in front of him, Corolla altis, S3X311UR, had also applied brakes to a stop. ~~He had~~ The Mercedes, SKL2322B, had already hit the Corolla altis, S3X311UR. I had also applied brakes, but due to the wet road conditions, I had skidded and hit the Mercedes, SKL2322B.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIM JOO YONG  
 Period of Insurance : 18 Nov 2019 To 17 Nov 2021  
 Engine No. : 4B40HB0394  
 Chassis No. : JMAXTGK1WLZ000609

Vehicle No. : SMR3113P  
 Policy No. : 1900247717  
 Endorsement No. :  
 Issued Date : 21 Nov 2019

ABOUT THE COVER

Make/Model : MITSUBISHI Eclipse Cross 1.5  
 Engine Capacity/Tonnage : 1,499.00 CC  
 Driver Restriction : NA  
 Person or Classes of Persons Entitled to Drive\* :  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2019  
 Insuring with COE/PAFF : Yes

a) The Policyholder  
 b) Any other person who is driving on the Policyholder's order or with his/her permission.  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition  
 Limitation as to use\* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.  
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1  
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$800  
 Section 2  
 Property Damage - \$0  
 Windscreen : \$100

Named Driver and Excess (where applicable)  
 LIM JOO YONG - \$800 (Own Damage), \$800 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Body & Paint Centre Add: 208 Pandan Gardens Singapore 609339 65684501
2. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website [www.aig.sg](http://www.aig.sg) or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504620217  
 C&CMICP2 - ANNAL  
 239 ALEXANDRA ROAD  
 SINGAPORE 159930  
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.  
 This computer generated document does not require a signature.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Singapore NRIC  
Owner ID: 710F

Vehicle No.: SMR3113P  
Vehicle to be Exported: No  
Intended Deregistration Date: 29 Sep 2020  
Vehicle Make: MITSUBISHI  
Vehicle Model: ECLIPSE CROSS 1.5 CVT SUNROOF  
Primary Colour: Blue  
Manufacturing Year: 2019  
Engine No.: 4B40HB0394  
Chassis No.: JMAXTGK1WLZ000609  
Maximum Power Output: 120.0 kW (160 bhp)  
Open Market Value: \$27,002.00  
Original Registration Date: 18 Nov 2019  
First Registration Date: 18 Nov 2019  
Transfer Count: 0  
Actual ARF Paid: \$29,803.00

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 17 Nov 2029  
PARF Rebate Amount: \$22,352.00

COE Expiry Date: 17 Nov 2029  
COE Category: B - Car above 1600cc or 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$40,009.00  
COE Rebate Amount: \$36,551.00  
Total Rebate Amount: \$58,903.00

The information contained herein is correct as at 29 Sep 2020

OK

Blue







Merimen e-Claims



Used 2019 Mitsubishi Eclipse Cross



PARF/COE

rmart.com/used\_cars/info.php?ID=931215&amp;DL=3416

## ► Mitsubishi Eclipse Cross 1.5A Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

**Price** \$97,500**Depreciation** ⓘ \$9,640 /yr  
View models with similar depre**Reg Date** 02-May-2019  
(8yrs 7mths 2days COE left)**Mileage** 10,248 km (7.2k /yr)**Manufactured** ⓘ 2019**Road Tax** ⓘ \$684 /yr**Transmission** Auto**Dereg Value** ⓘ \$51,169 as of today (change)**OMV** ⓘ \$26,634**COE** ⓘ \$33,989**ARF** ⓘ \$29,288**Engine Cap** 1,499 cc**Power** 120.0 kW (160 bhp)**Curb Weight** ⓘ 1,490 kg**No. of Owners** ⓘ 1**Type of Vehicle** SUV**Features**

1.5L DOHC MIVEC Turbocharged Engine, Smooth 8-speed INVECS III CVT Transmission, LED Headlamps With LED DRL, Heads Up Display, Paddle Shifters. View specs of the Mitsubishi Eclipse Cross (2018)

**Accessories**

18" Original Alloy Sport Rim With Yokohama BluEarth E70 Tyres, Thinkware HD Front Recording Cam, HD Reverse Multi Around Monitor, Driver Electric Seat

D