| ASS. REC. BY: Sun Pin REF: CS/A19200 | 10303/d3 |
|---|---|
| *PRS ASS | IGNMENT |
| From: Date: | Veh No: SMB 3140U Yr Regn: 62/11 /2615 |
| Estimated Cost: | Type: M.Car / M.Cycle / Bus/ Van / Lorry / Taxi / Prime Mover / |
| OD / TP / WS / TP RES / OD RES / EVA / INV / MV | Truck / Trailer or |
| To Inspect Vehicle No: | Make: MAN NL 350F c.c 10518 |
| at Workshop m/s | Colour Multicolour A/C: Insured / Std / NI / NA |
| of | Sp.Reading 367231 T/Radio: Insured / Std / NI / NA |
| Insured: | Eng/No: |
| Policy No. | C/No: WMAA22728F7002688 |
| Claims No. | Gen. Cond: Good / Fair/ Poor / Burnt |
| Sum Insured: Excess: | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inorder / Jammed / Leaked / Burnt or |
| Make of Veh: | Modi: Nil / S/Rim / TD A)Rim or |
| | Tyre Size: F: 275/70 R22.5 |
| (Policy Condition) | R: 275/70 R22.5 |
| Remark: The veh had commenced its N/S O/S | BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / |
| repair at the time of inspection. | TOYO / YOKO or |
| Bal. or Market Value: | Front Rear |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal. 6 mm R/Bal. 6 mm |
| GIA / PR Seen: Consistent? : Yes or No | L/Bal. 6 mm L/Bal. 6 mm |
| Est. Repairs: days Res.: Yes or No | D.O.A. 28/08/2020 D.O.I. 29/09/2020 |
| Lum Sum: | Survey held at SBS Transit |
| CA / REV / REP. / 24 HRS | Des. of Damages : Frt / Rear / O/S) N/S / U/C / Rooftop or |
| Vehicle: IN / OUT Date:Person Contacted: | The U/C / Chassis frame / Body Structure affected due to collision. |
| Date / Time Action / Instruction | Post of Oak |
| | Repair day 2 days |
| SUBMIT DAR REPORT | |
| | |
| 8/4 - RECEIVED GIA REPORT | |
| de la companya de la | |
| 1 | |
| · | |
| Date/Time, File Pass to? : Preli. Report | Days Of Repair: 2 |
| 1) ; Final Report | Resurvey No. of Trip: Survey Fee: |
| Date/Time, File Return to? | Transportation: |
| 2) Add Fe | e: |
| | : Interview (\$) Photos |
| Report Format: | : Tech. Invs (\$) Others |
| Lump Sum / I.B.I: (\$ | :Weel:end (\$) |
| | TOTAL |

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars | |
|-------------------------------|----------------------------------|
| Owner ID Type: | Company |
| Owner ID: | 653M |
| Vehicle Details | |
| Vehicle No.: | SMB3140U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 30 Sep 2020 |
| Vehicle Make: | MAN |
| Vehicle Model: | NL 320F (A22) 11L AUTO ABS TURBO |
| Primary Colour: | Multicolor |
| Manufacturing Year: | 2014 |
| Engine No.: | 50339912063991 |
| Chassis No.: | WMAA22ZZ8F7002688 |
| Maximum Power Output: | - |
| Open Market Value: | \$249,830.00 |
| Original Registration Date: | 02 Nov 2015 |
| First Registration Date: | 02 Nov 2015 |
| Transfer Count: | 1 |
| Actual ARF Paid: | \$0.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | No |
| PARF Eligibility Expiry Date: | - |
| PARF Rebate Amount: | \$0.00 |
| Intended COE Rebate Details | |
| COE Rebate Amount: | \$0.00 |
| Total Rebate Amount: | \$0.00 |

The information contained herein is correct as at 30 Sep 2020

ОК

Rear Partian

| | | Partion | | | | |
|------|-------------------|------------------|---|-----------------|----------|----|
| | NAC | INC | Item | CON | 1C | Oi |
| | 1137 | 993620 | Rear Number Plate | | <u>~</u> | 30 |
| - | 1138 | 993627 | Rem Number Plate Base | | | |
| L | 3044 | 993628 | Rear Number Plate Bracket | | | |
| 1 | 1140 | | | | | |
| 1- | 1141 | 992958 | Rear Bumper | | | |
| - 1 | 1142 | 993108 | Rear Bumper Upper | | | |
| 1- | 1143 | - | Rear Bumper Lower . | | | |
| - 1- | 1144 | 1 | Rear Bumper Side | 1 | | |
| L | 1147 | 992976 | Rear Bumper Bracket | | | |
| | 1148 | 993068 | Rear Bumper Side Retainer | + | | |
| | 1149 | 993045 | Rear Bumper Reinforcement | | | |
| | 2045 | 993081 | Rear Bumper Step Panel | | | |
| - | 2046 | 993079 | Rear Bumper Step Garnish | | | |
| 1- | 2047 | 993186 | Rear Crash Bar | | - | |
| | 1158 | | | | | |
| 1- | 1159 | 993327 | Rear End Panel | | | |
| - | 1163 | 993851 | | | | |
| - | 1164 1165 | 993853 | Rear LH Taillamp Garnish | | | |
| - | | 993839 | Rear LH Taillamp Panel | | | |
| - | 1166 | | Rear RH Taillamp | | | |
| - | 1167 | 993853 | Rear RH Taillamp Garnish | | | |
| _ | 1168 1169 | 993859 | Rear RH Taillamp Panel | | | |
| | 1289 | | Rear Apron Panel | | | |
| | 1350 | | Rear LH Door Rear RH Door | | | |
| 1- | 2048 | | Rear Door Emblem | | | |
| - | 2049 | 993274 | Rear Door Outer Handle | | | |
| 1- | 2050 | 993228 | Rear Door Garnish | | \dashv | |
| | 2051 | 993294 | Rear Door Rubber | | - | |
| | 1291 | 995194 | Rear LH Door Hinge | | -1 | |
| | 1352 | 995307 | Rear RH Door Hinge | | | |
| | 1301 | 993261 | Rear LH Door Lock | | | |
| | 1362 | 993261 | Rear RH Door Lock | | - | |
| | 2052 | 993232 | Rear Door Glass | | _ | |
| | 2053 | | | | | |
| L | 1248 | 994729 | Third Brake Light | | | |
| 1- | 1181 | | Tailgate | | | |
| | 2054 | 993700 | Rear Rubber Stopper | | | |
| 1- | 1182 | 993701 | Rear Rubber Stopper Bracket | | - | |
| 1 | 1183 | 994643 | | | - | |
| - | 1185 | 994545 | | | \dashv | |
| 1- | 1193 | | Tailgate Glass | 1 | \dashv | |
| 1 | 1194 | | Tailgate Glass Rubber | 1 | \dashv | |
| - | 1195 | 994604 | | 1 1 | + | |
| - | 1196 | 994607 | Tailgate Glass Scalant | 1 | 7 | |
| | 2056 | 994597 | | 1 | + | |
| | 1197 | 994629 | Tailgate Lock | | | |
| _ | 1198 | 994651 | | | \Box | |
| 1 | 1199 | 994611 | Tailgate Hinge | | | |
| 1- | 200 | 994594 | Tailgate Damper | - - | _ | |
| 1- | 1201 | 994613 | Tailgate Inner Board | | _ | |
| 1 | 2057 | 993992 | | | 4 | |
| | 2058 | 993995 | | - - | - | |
| - | 059 | 993997 | Rear Wiper Motor | | | |
| | 204 | 993484 | Rear Floor Panel | - - | - | |
| | 204 | 995065 993785 | Spare Tyre | | - | _ |
| | 212 | 993785 | Spare Tyre Bracket | - | + | |
| | $\frac{212}{214}$ | 993361 | Rear Exhaust Pipe Rear Exhaust Mounting | - | - | |
| - | 216 | 995223 | Rear LH Chassis Member | - | | |
| 1- | 217 | 993165 | Rear RH Chassis Member | - | - - | |
| | | | | | | |

| | | Vehicle No: SMB 314 | ou | | |
|----------|---------|------------------------------------|--------------|--|---------------|
| NYC. | INC | Item | Tco | NIA | C QI |
| 2062 | 993748 | Rear Sidegate | | ~ | 17 |
| 2063 | 994225 | Rear Sidevate Lock | - | - - | + |
| 2064 | 993749 | Rear Sidegate Hinge | + | + | |
| 2065 | 994226 | Sidegate Lower Panel | - | + | |
| 2066 | 994227 | Sidegate Railing | - | - - | |
| 2067 | 994208 | Side Cover Hook | - | + | |
| 2068 | 991965 | Side Pour Me u | h | +- | |
| 2069 | 00 1400 | Side Panel NO 4, 5 Side Panel Lock | R | 12 | 2 |
| 2070 | 002057 | Side Panel Lock | SCR | 1 | |
| | 99285/ | Rear Body Pancl | 1 | | |
| 2071 | 992866 | Rear Body Panel Inner | | _ | _ |
| 2072 | 995329 | Sliding Door LH | 1 | ┪ | _ |
| 2073 | 995328 | Sliding Door RH | | 1 | 7- |
| 2074 | 994295 | Sliding Door Handle | | 1 | _ |
| 2075 | 994300 | Sliding Door Lock | | | - |
| 2076 | 994313 | Sliding Door Rubber | 1 | 1- | |
| 2077 | 994291 | Sliding Door Bottom Roller | _ | + | +- |
| 2078 | 994317 | Stiding Door Top Roller | | + | - |
| 2079 | 994306 | Sliding Door Rail | + | 十 | |
| 2080 | 994315 | Sliding Door Stepboard | + | ╁ | +- |
| 2081 | 00/216 | Cliding Door Stepbourd | | ╀ | ┿┈ |
| | 002/21 | Sliding Door Stepboard Garnish | ├ ─- | - | |
| 2006 | 993621 | Rear LH Mudflap | | 1_ | |
| #12251 | 993933 | Rear LII Wheel Rim | | \perp | |
| 112261 | 994025 | Rear LH Rim Cover | | L | |
| 31227 | 995065 | Rear LH Tyre | | | |
| 2025H | 993622 | Rear RH Mudflap | | \perp | |
| W12557 | 993934 | Rear RH Wheel Rim | | L | |
| 應12361 | 994025 | Rear RH Rim Cover | | | |
| #1257/21 | 995005 | Rear RH Tyre | | 1_ | |
| | | Fuel Tank | | | |
| 21253 | 992184 | Fuel Tank Bracket | | | |
| 111867 | 990247 | Sticker | | | |
| | | | | | |
| | | | | \vdash | 1 |
| | | | | - - | \vdash |
| | | | _ | +- | + |
| | | | | \vdash | - |
| | | ; | | - | |
| | | | | - | |
| | | | | - | |
| | • | | | _ | |
| | | | | | |
| | | | | | 1 |
| | | | | - | † |
| | | | | - | ├ |
| | | | | | |
| | | | | | |
| + | | | | - | |
| | | | | | |
| | | | | | |
| | | | | | |
| - | | | | | |
| | | | | | |
| - | | | | | |
| | | | | | |
| - | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | _ | |
| - | | | $\neg \neg$ | - | |
| | | | | | |
| | | | | | |
| | | | | | |

Ho of tems: Assessor: Sun Pin