

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

12/10/20
Smy & Repin morning
BKW



GST REG. NO : M2 - 0020081 - X

25 SEP 2020

ESTIMATE

Estimate No. : b1 56097
Date Estimated : 25/09/2020
Prepared By : Chua Kee Sin

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Stelzer Frank
106 Duchess Ave
#03-08

Singapore 266311

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV4243G	WBA8E36050NU82400	28/12/2017	318i	0

DESCRIPTION

To replace right front side fender, right front door includ
e remove attachment etc and re pair front bumper

2125 3,400.00

Spray painting front bumper, right front fender, front right
door, right lower side skirting and right mirror cover

2527 3,625.00

To carry out body cavity preservation.
(2 panel).

200 236.00

To transfer lock mechanism from old to new door including
conduct checks on new door power window system for proper
function. (1 door).

451 531.00

To conduct checks on all doors and bootlid central locking
system for proper function.

150 177.00

Sundries

? 150.00

Total Labour 1: 8,119.00

DESCRIPTION	QTY	PRIC	VALUE
PLUG-IN RETAINER	2	0.85	1.70
EXPANDING NUT	10	0.95	9.50
FRT RH DOOR	1	1,273.85	1,273.85
FRT RH SIDE PANEL	1	702.65	702.65
FRT RH 2 SIDE PANEL BRACKET	1	35.10	35.10
FRT RH 1 SIDE PANEL BRACKET	1	35.10	35.10
FRT RH 3 SIDE PANEL BRACKET	1	35.10	35.10
RH UPPER FRONT DOOR HINGE	1	56.30	56.30
RH LOWER FRT DOOR HINGE	1	56.30	56.30
MODEL DESIGNATION LETTERING SIDE (L	1	46.55	46.55
RIVET	10	0.50	5.00
RETAINING RING BLACK GRAINED RH	1	53.45	53.45
HOUSING LOWER SECTION RH (GENARBT)	1	43.90	43.90
RH HEATED OUTSIDE MIRROR	1	865.35	865.35
FRT RH DOOR BRAKE	1	77.60	77.60

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401519W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 56097
Date Estimated : 25/09/2020
Prepared By : Chua Kee Sin

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLV4243G	WBA8E36050NU82400	28/12/2017	318i	0

DESCRIPTION	QTY	PRIC	VALUE
FRT DOOR WEATHERSTRIP	1	141.40	141.40
FRT RH SEALING WINDOW FRAME INTERIO	1	61.45	61.45
Gasket, rail	1	6.95	6.95
FRT RH DOOR WINDOW GUIDE	1	122.90	122.90
FRT RH DOOR OUTER CHROM	1	106.75	106.75
FRT RH WHEEL HOUSING COVER	1	117.15	117.15
RH COVER BOTTOM	1	117.15	117.15

Total Parts : 3,971.20

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 12/10/20 @ 3pm Excess S\$ _____

Surveyor's Name Taphm Sign Taphm

Surveyor's Tel 97496349 Authorised Yes / No

Survey Date WP Time _____

RESURVEY PARTS PHOTO BY SURVEYOR YES / NO PML Yes / No

Surveyor's E-mail taphm@pikanto.com

Working Days Recommend 5-6 days



Labour 1	:	8,119.00
Parts	:	3,971.20
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	846.31
Grand Total	:	12,936.51

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **