ASS. REC. BY: Sun Pin REF: CS/CTI 200	010347/Qvf3
ASS	IGNMENT
From: Date: Estimated Cost:	Veh No: GBGQ738K Yr Regn: 06/12/2017 Type: M.Car / M.Cycle / Bus I(Van) / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mercedes Benz Citan 109 c.c 1461
at Workshop m/s	Colour Silver A/C: Insured / Std / NI / NA
of	Sp.Reading 52694 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
	C/No: wpF41560520221537
Policy No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 195/65 R15
(Policy Condition)	R: 95/65 R15
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MICY OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 18/09/2020 D.O.I. 28/09/2020
Lum Sum: % 3 Val.: Yes or No	Survey held at Tong luck
CA / REV / REP. / 24 HRS	Des. of Damages : Frt (Rear) O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
MV: 45,000	
PV: 33,680	
NV: 11,000	
	ь
:	
	-
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 4
1) : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	Transportation:
2) 15/10/20-Typist Add Fe	
	: Interview (\$) Photos
Report Format: Merimen	: Tech. Invs (\$) Others
Lump Sum / I.B.i : (\$ 4450)	:Weel:end (\$)
	. TOTAL

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company	
Owner ID:	778Z	
Vehicle Details		
Vehicle No.:	GBG9738K	
Vehicle to be Exported:	No	
Intended Deregistration Date:	29 Sep 2020	
Vehicle Make:	MERCEDES BENZ	
Vehicle Model:	CITAN 109 CDI EL 5MT 6DR	
Primary Colour:	Silver	
Manufacturing Year:	2017	
Engine No.:	K9KE628D403982	
Chassis No.:	WDF4156052U221537	
Maximum Power Output:	-	
Open Market Value:	\$25,085.00	
Original Registration Date:	06 Dec 2017	
First Registration Date:	06 Dec 2017	
Transfer Count:	0	
Actual ARF Paid:	\$1,255.00	
Intended PARF Rebate Details		
PARF Eligibility:	No	
PARF Eligibility Expiry Date:	-	
PARF Rebate Amount:	\$0.00	
Intended COE Rebate Details		
COE Expiry Date:	05 Dec 2027	
COE Category:	C - Goods Vehicle & Bus	
COE Period(Years):	10	
QP Paid:	\$46,890.00	
COE Rebate Amount:	\$33,680.00	
Total Rebate Amount:	\$33,680.00	

The information contained herein is correct as at 29 Sep 2020

MBHH20061119-01 / Ajax Mars Pte Ltd - Bukit Merah ENTRY DATE & TIME: 18/09/2020 12:49 SUBMITTEO BY: Mazlan

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACC	IDENT	CTA	T = M	ENT
AUU				

18/09/2020 12:49 Date Of Report Date Of Accident 18/09/2020 09:10

JUNCTION OF CORPORATION ROAD AND JURONG WEST AVE 2 **Exact Location Of Accident**

SINGAPORE Country/State of Loss

DETAILS OF OWN VEHICLE

GBG9738K Vehicle Registration Number

Insured/Policyholder

DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. Name Of Registered Owner

1XXXXX778Z Co Reg No NOEMAIL **Email Address**

Mobile Phone No

OFFICE-68498118 Alternative Phone No

Vehicle Particulars

MERCEDES-BENZ Manufacturer

CITAN 109 CDI EL 5MT 6DR Model

Exact Purpose for which vehicle was being used at COMMERCIAL USE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

COMMERCIAL VEHICLE

Insurance Company

AIG ASIA PACIFIC INSURANCE PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

YES Fleet Policy 999995580 Policy Number

NA Cover Note Number

Driver

LOH SEE KEE Name of Driver SXXXX919C NRIC No 07/08/1976 Date Of Birth OUTDOOR Occupation 08/12/1999 **Date Of Driving Pass**

20 YEARS AND 9 MONTHS **Driving Experience**

MALE Gender

(LOCAL) +65-89072956 Mobile Number

Fax Number

OTHERS-89072956 Contact Number

EMail Address NOEMAIL Address

NA

Postcode

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OTHER - HIRER

THE RESERVE OF THE PROPERTY OF

Vehicle Registration Number of Driver's Own

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

soliciting/offering accident claims assistance. Number of Passengers (Including Driver)

NO 2

Passenger 1

NAMF:

: LEE KIAN HEAN

GENDER:

: MALE

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I WAS DRIVING ALONG THE SAID MENTIONED ROAD AND ABOUT TO MAKE A RIGHT TURN, WHEN MY VEHICLE WAS HIT FROM THE REAR BY VEHICLE 'B'. NO ONE WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GX8368C

Vehicle Make/Model/Colour

TOYOTA / HIACE DIESEL

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

LIANG CHENG

NRIC/Passport Number SXXXX592Z Contact Number 90328034

Address

Postcode

Insurance Company Name

Nature Of Damage No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN GBG9738K

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.

The second secon

- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the
- (b) all insurer(s) who have insured vehicle(s) ingolasd in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process ma Force as information for one or more of the above Purposes; and
- (c) my Personal Information may/cas La sixclass/) or any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/jaw lights, ablich may be sleed outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be addressed and used to compile claims history for the purpose of fraud detection, investigation and management in present out all retire chains.
- (e) the information so collected under (d) shove may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

(If driver is not the policyholder)

Date & Time: 18 Sep 2020

VERIFY BY AJAX MARS (ARC) REPORTING OFFICER HASHIM BIN KAMARI

Reporting Centre Personnel's Signature NRIC/FIN No.:

Sketch Plan #2 SKETCH PLAN & Tentric Lant A1 GBG 9738K B: GX 8368C. MAMB Aroning bans 4 eoporation puns DESCRIBE CIRCUMSTANCES OF THE ACCIDENT REFER TO ATTACHED STATEMENT. VWe declare the foregoing particulars are true in every respect. VERIFY BY AJAX MARS (ARC) REPORTING OFFICER HASHIM BIN KAMARI Policyholder's Sgratue Derver's Signature Reporting Centre Personnel's Signature Date & Time (if driver is not the policyholder) ARICAIN NO Date & Time

Sketch Plan #3 Pg. 1

ACCIDENT STATEMENT (2000 characters)

(2000 01101000)	
ON THE DATE AND TIME MENTIONED MENTIONED ROAD AND ABOUT TO M WAS HIT FROM THE REAR BY VEHICL WAS READ TO ME AND I ACKNOWLED	AKE A RIGHT TURN, WHEN MY VEHICLE .E 'B'. NO ONE WAS INJURED. STATEMENT
Taxi Voucher No.:	
DECLARATION I/We declare that the above periodics & received a provide provide VERIFIED BY AJAX MARS REPORTING OFFICER - HASHIM BIN KAMARI	ed above are true in every aspect
MARS Officer	Registered Owner or Driver's Signature
Job Complete Date/Time	Date/Time: 18 September 2020 at 11:50 AM
18 September 2020 at 11:50 AM	10 Ochionos,



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL : 6849 8118

FAX:

ATTN: ACCOUNTS DEPT

ESTIMATE

NO ; QUOT202009-000072(00)

DATE : 25/09/2020 POLICY NO : 999995580

VEH REG NO : GBG9738K

MAKE/MODEL : MERCEDES BENZ CITAN 109

CDI EL 5MT 6DR

YOUR REF NO : GX8368C CHASSIS NO : WDF4156052U221537

CLAIM TYPE : THIRD PARTY ENGINE NO : K9KE628D403982 TP INS. CO. : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE : 2017

ACCIDENT DATE : 18/09/2020 TP VEH REG NO : GX8368C

Estimate Repair Cost to Vehicle No: GBG9738K

Description	Quantity	Unit Price	Amount
		<u>s\$</u>	<u>\$\$</u>
NET PRICE		/ co.co	28.00
1 Rear wiper cap / SC R	1	28.00	
2 Rear door - LH / Db	1	1,575.00	1,575.00
3 Rear door lock - LH ·X5VC	. 1	275.00	275.00
4 Rear door inner trimboard - LH X	.1	135.00	135.00
5 Rear door trimboard clips - LH 🗡	8	5.50	44.00
6 Rear door centre logo - LH / Nec	1	57.00	57.00
7 Rear door 'CITAN' emblem - LH	1	58.00	58.00
8 Rear door - RH /pb	1	1,080.00	1,080.00
9 Rear door '109 CDI' emblem - RH	1	58.00	58.00
10 Rear door inner timboard clips - RH	8	5.50	44.00
11 Rear door inner reflector - RH	1	58.00	58.00
12 Rear end panel (outer)	1	715.00	715.00
13 Rear bumper 🗶 🐇 / CRY.	1	1,200.00	1,200.00
14 Rear bumper reinforcement 7	1	325.00	325.00
15 Rear bumper clips / Ner.	15	9.00	135.00
· · · · · · · · · · · · · · · · · · ·			5,787.00
		Less 10%	578.70
			5,208.30
SPECIAL NET 16. Rear door glass sealant - I.H. / N&C	4	40.00	40.00
To Treat door glass scalarity Err	1	40.00	40.00 / 38.00 ²
1, 1,00,000	1	38.00	40.00
in the second se	1	40.00	
(24)	1	280.00	280.00
20 Mediador 4 para chance 211	1	25.00	25.00
21 Real door Toking Stoker - 1317	1	25.00	25.00
22 Rear number plate / SC R	1	40.00	40.00/
LABOUR			488.00
LABOUR 23 To remove and refix both side rear door glass	1	160.00	160.00
24 To transfer damaged both rear door interior mechanism to new	1		200.00
door		200.00	
25 To remove and refix rear bumper sensor	1	80.00	80.00
26 To check and rectify wiring system	1	60.00	60.00



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg

NO

DATE

GST No: 201700521W UEN No: 201700521W

PAGE: 2

: DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL : 6849 8118

ATTN: ACCOUNTS DEPT

FAX:

MAKE/MODEL: MERCEDES BENZ CITAN 109

POLICY NO

ESTIMATE

CDI EL 5MT 6DR

VEH REG NO : GBG9738K

CHASSIS NO : WDF4156052U221537

: QUOT202009-000072(00)

: 25/09/2020 : 999995580

: 2017

ENGINE NO

: K9KE628D403982

CLAIM TYPE TP INS. CO.

YOUR REF NO

: THIRD PARTY : CHINA TAIPING INSURANCE (SINGAPORE) PTE REG. DATE

ACCIDENT DATE : 18/09/2020

: GX8368C

TP VEH REG NO : GX8368C

Estimate Repair Cost to Vehicle No: GBG9738K

Description	Quantity	Unit Price	Amount
		S\$	SS
27 To panel beat and straighten rear floorboard panel, reaframe, to cut and weld rear end panel, including replace parts and align where necessary, to refit and adjust the	ement of	1,000.00	1,000.00
28 To putty and spray same on affected areas	1	1,200.00	1,200.00
29 To apply rust proofing on repaired and replaced panels	1	80.00	80.00
		-	2,780.00
		TOTAL	S\$ 8,476.30
	A	DD GST @ 7%	593.34
		GRAND TOTAL	S\$ 9,069.64
		GRAND TOTAL	5\$ 9,069.

SINGAPORE DOLLAR NINE THOUSAND SIXTY-NINE AND CENTS SIXTY-FOUR ONLY

Repuir days 14 days
19/10
before pain photo

Sun Pin (Hck) 28/00/2020 Thurthu pregude

Sunpin @ Ikkauto .com 8661 2627

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

UCK AUTO PTE LTD FOR TONG L

AUTHORISED SIGNATURE

