

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 28.09.2020

Time: 08:43:58

Page: 1/2 TS

AG BIC
CLIS)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305424683
 REGN NO : SH 7012C
 MILEAGE : 0000000000
 MAKE : TOYOTA
 MODEL : PRIUS HYBRID(G4)
 DATE OF REGN : 25.05.2017
 DATE TIME IN : 25.09.2020 16:55
 ACCIDENT DATE : 25.09.2020

JOB PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-A	FRONT BUMPER	1	499.90	25.00	374.92	Rx
0002 04-01-0302-2871-G	FRONT BUMPER BRKT LH	1	77.00	25.00	57.75	X u u
0003 04-01-0302-0574-A	FRONT FENDER LH	1	945.30	25.00	708.97	ht ✓
0004 04-01-0302-2834-G	FRONT FENDER SHIELD LH	1	199.50	25.00	149.62	X u u
0005 04-01-0302-2297-G	FRONT FENDER (HYBRID) LH	1	86.50	25.00	64.87	rec ✓
0006 03-01-0302-2020-G	FRONT WHEEL RIM LH	1	1,570.55	25.00	1,177.91	cut ✓

1951.75.

SUB-TOTAL : 2,534.04

JOB NATURE

0000 20-05	FRONT WHEEL TYRE LH	216.00	X u u
0001 PB	PANEL BEATING	700.00	480
0002 SP	SPRAYPAINT CHARGE	500.00	400
0003 20-00	TUFF COAT ON AFFECTED PARTS.	40.00	30.
0004 L	WHEEL ALIGNMENT	120.00	80 990.

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.09.2020

Time: 08:43:58

REPAIR ESTIMATE

Fig Abira CLS

Page: 2/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305424683
REGN NO : SH 7012C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID
DATE OF REGN : 25.05.2017
DATE/TIME IN : 25.09.2020 16:5
ACCIDENT DATE : 25.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 1,576.00

TOTAL : 4,110.04

LMF

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tariff 77495749 1951.75
WP' 28/9/2004 990
1/5 Resurvey after repair 2941.75
tariff @ 116kanto.com. 1/5 2350
2-3 days 3 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: