

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969

Our Ref : 305425050  
Date : 28092020  
Time of Fax: \_\_\_\_\_

Via Fax : Email  
Your Insured: SLP 7895 L  
Date of Acc : 25092020

Attn: Motor Claims Department

Dear Sirs

**SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH 6200H**

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident \_

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:-

◆ Lim Kwok Eng	Tel: 6214 8316 or HP: 9824 0811	} Fax no. 6546 8156
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305	
◆ <b>Lim Tien Siong</b>	Tel: 6214 8398 or HP: 9635 8546	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	
◆ Larry Ng Nyuk Phin	Tel: 6214 8315 or HP: 9230 2824	

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

**Lim Tien Siong**

for Vice President  
Crash Repairs & Claims Recovery

## COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ang Asia

Date: 28.09.2020

Time: 13:02:10

Page: 1

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305425050  
 REGN NO : SH 6200H  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 20.12.2017  
 DATE/TIME IN : 26.09.2020 18:35  
 ACCIDENT DATE : 25.09.2020

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	28-01-9999-2023-A	REAR DOOR APPS STICKER LH	1	80.00 <del>0.00</del> 80.00
0002	04-01-0103-0658-G	REAR WHEEL CAP LH	1	107.10 20.00 85.68
0003	04-01-0103-0658-G	REAR WHEEL CAP RH	1	107.10 20.00 85.68
0004	04-01-0103-0658-G	FRT WHEEL CAP RH	1	107.10 20.00 85.68

SUB-TOTAL : 337.04

## JOB NATURE

0000	PB	PANEL BEATING- <u>Rear Fender LH etc</u>		600.00
0001	SP	Spraypaint- <u>Rocker Pnl Garnish LH etc</u>		750.00
0002	20-00	TUFF COAT ON AFFECTED PARTS.		100.00
0003	L	WHEEL ALIGNMENT		120.00
0004	23-01	TOWING FEE		60.00

SUB-TOTAL : 1,630.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.09.2020

REPAIR ESTIMATE

Ang Asia

Time: 13:02:10

Page: 2

TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305425050  
REGN NO : SH 6200H  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : I-40  
DATE OF REGN : 20.12.2017  
DATE/TIME IN : 26.09.2020 18:3  
ACCIDENT DATE : 25.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Limf

TOTAL : 1,967.04

MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :  
AUTHORISED : YES / NO