

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Ang Asia CP/P

Date: 28.09.2020

Time: 13:02:10

Page: 1

1/2 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305425050
 REGN NO : SH 6200H
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 20.12.2017
 DATE/TIME IN : 26.09.2020 18:35
 ACCIDENT DATE : 25.09.2020

JOB / PARTS DESCRIPTION QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001 28-01-9959-2025-A REAR DOOR APPS STICKER LH	1		80.00		80.00 <i>cut</i>
0002 04-01-0103-0658-G REAR WHEEL CAP LH	1		107.10 20.00		85.68 <i>cut</i>
0003 04-01-0103-0658-G REAR WHEEL CAP RH	1		107.10 20.00		85.68 <i>cut</i>
0004 04-01-0103-0658-G FRT WHEEL CAP RH	1		107.10 20.00		85.68 <i>cut</i>
SUB-TOTAL :					337.04

JOB NATURE

0000 PB	PANEL BEATING- <u>Rear Fender LH etc</u>				600.00 <i>560.</i>
0001 SP	Spraypaint- <u>Rocker Pnl Garnish LH etc</u>				750.00 <i>500.</i>
0002 20-00	TUFF COAT ON AFFECTED PARTS.				100.00 <i>30</i>
0003 L	WHEEL ALIGNMENT				120.00 <i>80.</i>
0004 23-01	TOWING FEE				60.00 <i>✓</i>
SUB-TOTAL :					1,630.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 28.09.2020

REPAIR ESTIMATE

Ang Astita
cp/p

Time: 13:02:10

Page: 2

12 TS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305425050
REGN NO : SH 6200H
MILEAGE : 000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 20.12.2017
DATE/TIME IN : 26.09.2020 18:3
ACCIDENT DATE : 25.09.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

Limfs

TOTAL : 1,967.04

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Tan Sri 97495747
- WP' 28/9/20 @ 4pm
P/P Resurvey after repair
2-days
Tan Sri @ 11 hands on

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Upper Road Singapore 570649

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 729791
501 Yishun Industrial Park A Singapore 768732

member of COMFORTDELGRO

Date/Time: 28.09.2020 12:44 Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO.:305425050

OWNER AS COMFORT TRANSPORTATION PTE LTD OWNER NO. 7010045 ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717 (R) 65508755 (O) (P) QUANTITY CARD NO.	REGN NO. SH 6200H	MILEAGE
	MAKE: HYUNDAI	FUEL E.....1/2.....F
	MODEL I-40	DATE/TIME IN 26.09.2020 18:35
	YR OF MANU. 20.12.2017	TARGET DATE
	CHASSIS CODE KMHLEB41UMHU098908	COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 25.09.2020
NATURE: 3P 25.09.2020

S/NO	LABOR CODE	DESCRIPTION

BOOKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip No.: SH 6200H LIMTS	Exit Pass Vehicle No.: SH 6200H
_____ Signature/Date	_____ Name of Service Advisor
_____ Date	_____ Date

turned to Service Reception upon collection

To be kept by Security Guard