

Our Ref : T 0920 / SH 6200H /KS(st)
 Your Ref: _____
 Date : 8-Oct-2020

CDGE Taxi Claims Dept
 59 Loyang Drive 4th Floor
 Singapore 508969

ComfortDelGro Engineering Pte Ltd
 205 Braddell Road Singapore 579701

Mainline +65 6383 6280
 Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

AIG ASIA PACIFIC INSURANCE PTE LTD
AIG Building

78 Shenton Way
#07-16

Singapore 079120

Attn : Motor Claims Department

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SH 6200H YOUR INSURED SLP7895L
 AND OTHER _____ ON 25-Sep-2020**

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner of motor Vehicle No SH 6200H which was involved in the captioned accident with your insured vehicle. The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SLP7895L we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$	1,676.73
2	<u>4.5</u> days Loss of Rental @ \$ 116.95 per day	\$	526.28
3	Survey Report Fees (<i>Surveyed by M/s LKK</i>)	\$	-
4	GIA / LTA Search Fees	\$	2.00
5	GIA / Police Report Fees	\$	-
6	Towing Fee	\$	-
		\$	2,205.01

HIRER'S CLAIM

7	<u>4.5</u> days Loss of Income @ \$ 80.00 per days	\$	360.00
---	--	----	--------

Total Claims : \$ 2,565.01

We enclose herewith the following documents to support the claims: -

- a) Original repair bill :
 - b) LTA search slip/s of : SLP7895L
 - c) GIA / Police report/s of : SH 6200H
 - d) Letter of authority from owner / hirer / operator
- () Photograph/s of Accident Scene () Certificate of Insurance
 () Witness statement/s () PIR (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

Kazali Hj Selahudin

CDGE Taxi Claims Department

Tel : 6214 8736 Fax : 6214 1843 Email : kazali@cdge.com.sg

This is a computer generated letter. No signature is required.

Workshops

Braddell
 205 Braddell Road
 Singapore 579701

Loyang
 59 Loyang Drive
 Singapore 508969

Sin Ming
 383 Sin Ming Drive
 Singapore 575717

Pandan
 45 Pandan Road
 Singapore 609286

Ubi
 320 Ubi Road 3
 Singapore 408649

Sungei Kadut
 7 Sungei Kadut Way
 Singapore 728791

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, AIG BUILDING #07-16
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO
SH 6200H

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
20.12.2017

CHASSIS CODE
KMHLB41UMHU098908

INV. NO/DATE
91527293 07.10.2020

JOB NO.
305425050

ODOMETER READING

DATE/TIME IN
26.09.2020 18:35

Description : 3P 25.09.2020

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	28-01-9999-2023	REAR DOOR APPS STICKER LH	1	80.00	0.00	80.00
0002	04-01-0103-0658	REAR WHEEL CAP LH	1	107.10	20.00	85.68
0003	04-01-0103-0658	REAR WHEEL CAP RH	1	107.10	20.00	85.68
0004	04-01-0103-0658	FRT WHEEL CAP RH	1	107.10	20.00	85.68
SUB-TOTAL						337.04

JOB NATURE

0001	PB	PANEL BEATING-Rear Fender LH etc		560.00		560.00
0002	SP	Spraypaint-Rocker Pnl Garnish LH etc		500.00		500.00
0003	20-00	TUFF COAT ON AFFECTED PARTS.		30.00		30.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91527293	1,676.73	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010004

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY, AIG BUILDING #07-16
SINGAPORE SG 079120

CONTACT NO: 64193000 3225094

VEHICLE NO
SH 6200H

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
20.12.2017

CHASSIS CODE
KMHLB41UMHU098908

INV. NO/DATE
91527293 07.10.2020

JOB NO.
305425050

ODOMETER READING

DATE/TIME IN
26.09.2020 18:35

S/No	Part No.		Qty	Unit Price	%Disc	Net
0004	L	WHEEL ALIGNMENT		80.00		80.00
0005	23-01	TOWING FEE		60.00		60.00
SUB-TOTAL :						1,230.00

Items total	1,567.04
Add GST @ 7.000 %	109.69
Invoice amount	1,676.73

Issued by : KATHERINETAN 07.10.2020 10:02:21
Repair type : CLSO/57/57
Payment Type/Term: /Credit 30 days

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010004	91527293	1,676.73	

Our Ref: CT20090418

Date: 07 October 2020



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 25/09/2020 @ 22:05 hrs
ALONG SERANGOON AVE 3
INVOLVING SLP7895L, ,
KERB/DIVIDER/PAVEMENT/HUMP/PLATFORM

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SH6200H** (the "Taxi"). The Taxi was hired to **LEE WENG THONG WILLIAM IC NO SXXXX824Z** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$116.95** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia
Manager, Fleet Safety

This is a computer generated letter. No signature is required.

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING i 40 SH6200H , SLP7895L
ALONG SERANGOON AVE 3****ON 25-Sep-20 22:05**I / We **LEE WENG THONG WIL...** (Hirer) NRIC No.: **SXXXX824Z**and/or (Relief) NRIC No.: **SXXXX824Z**Taxi Number **SH6200H**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **28-Sep-2020**Name of Hirer **LEE WENG THONG WILLIAM**Hirer NRIC **SXXXX824Z**

Signature :

Address **135 EDGEDALE PLAINS #03-90
820135**Contact No. **98244223**

Third Party Insurer Enquiry

Our Ref No: GR-20-116519
Date of Request: 28/09/2020

Your Ref No: Online Purchase

ComfortDelGro Engineering Pte Ltd
205 Braddell Road
Singapore 579701

Dear Sir/Madam,

Enquiry Date 28/09/2020
Enquiry By Catherine Por Moy Juan
TP Vehicle No. SLP7895L
Accident Date 25/09/2020

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLP7895L	AIG Asia Pacific Insurance Pte. Ltd.	19/06/2020-18/06/2021	65-6419-3000

Thank You.

SN 62007

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.