

Claim Handling

Task TransferExit

▼ Accident MT/1104893

LOS SAL SUB

Policy No.	5118584003	Vehicle No.	SMU4525L	GST Registration No.	200503209M
Certificate No.					
Policyholder Name	IFISH PTE. LTD			Policyholder NRIC	200503209M
Product Code	PRIVATE CAR INSURANCE	Cover Type	drivo CLASSIC	Loading	0
Contact No.(Mobile)	90490490	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No ▾
KFK	☒ No ☐ Yes	TCA	☒ No ☐ Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	10	Private Hire	No

▼ Accident Details

Report Date	29/09/2020 09:50	Accident Report Within 24 hrs	Yes	Accident Type	Others
Date of Accident	27/09/2020	Time of Accident hh:mm	18:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTRE	Orange Force	No	ICM No.	
Accident Location	NEAR BLK 354A ADMIRALTY DR MSCP				

▼ Total Excess Applicable

Excess Type	Per Accident	Windscreen Excess	100.00		
OD Standard Excess	600.00	TP Standard Excess	0.00		
YIED OD Excess	0.00	YIED TP Excess	0.00	Driver is Covered?	Covered
Additional Excess	0.00				
Total OD Excess Applicable	600.00	Total TP Excess Applicable	0.00		

▼ Benefits

▼ GST Registered Information

GST Registered	Yes	GST Registration Date	18/04/2005
GST Registration No.	200503209M	GST Status Verified	Yes
Modification History	29/09/2020 09:52:47 System changed GST Status Verified from No to Yes		

▼ Policyholder Mailing Address

Address 1	31 WOODLANDS CLOSE	Address 2	#03-25 WOODLANDS HORIZON	Address 3	SINGAPORE 737855
Address 4		Address Type	Singapore address	Post Code	737855
Unit No.		Related Policy Number	5118584003		

▼ OI Driver Info

Driver Name	Unnamed Driver	Driver Type	Unnamed Driver		
Unnamed driver Name	LEE ENG SIEW	Driver NRIC	S1514480G	Driver DOB	30/08/1961
Register Date of Driver License	19/03/1979	Driver Age	59	Driving Experience	41
Contact No.(Mobile)	90490490	Contact No.(Office)		Contact No.(Home)	
Address 1	BLK 354A #03-256	Address 2	ADMIRALTY DRIVE	Address 3	SINGAPORE 751354
Address 4		Address Type	Singapore address	Post Code	751354
Unit No.	03-256				
Does he own a Singapore Registered car?	☐ Yes ☒ No	Driver Vehicle No.		Driver Insurer Company	

▼ Declaration

Breathalyser or Blood Test Reading?	0 mg	Any injury?	☐ Yes ☒ No
Modification History			

▼ Investigation

Claim 001 OD-MD

▼ Claim Case Officer Tan Siew Choo

Claim Type	OD-MD	Insured Name	IFISH PTE. LTD	Insured NRIC	20050320
Contact No.(Mobile)	90490490	Contact No. (Home)		Contact No. (Office)	66848476
Email Address		OI Vehicle Number	SMU4525L	TP Vehicle Number	WALL & KI
Claim Description	SMU4525L / WALL & KERB ON 27 Sept 2020			Name of Preferred Workshop	
Preferred Workshop Contact No.	☐ Yes ☒ No	Preferred Repair Option	income to assign workshop	Insured Claimability report	Fully at Resolved
Date Registered	29/09/2020 09:55	Claim Close Date		Date Received	29/09/2020
Report Taken By	LIEW SHAN HUI	Workshop Repairer		Total Loss but Repaired	
☒ Print AK letter				OD Excess Collected by Workshop	
Modification History					

▼ Special Claim Creation Approval

Approval

Reason

Remarks

damage assessment

Attachment

▼ Vehicle Info

Vehicle Make

NISSAN

Vehicle Model

SERENA

Engine Capcity

Date of Registration

14/08/2020

Classis No.

JN1EBAC27Z0000614

Towing Required *

☐ Yes

☒ No

Vehicle in IDAC *

☐ Yes

☒ No

Parallel Import *

☐ Yes

☒ No

Type of Tender *

Own Damage

Assessor Name *

BRYAN

Survey Current Status

IDAC/Workshop Name

NATIONAL ASSESSMENT CENTRE

IDAC/Workshop Location

51 UBI AVENUE 1 #01-25 PAYA

Windscreen Parts & Labour Cost

Total Loss *

☐ Yes

☒ No

Market Value(\$)

Scrape Value(\$)

Economical Repair Value(\$)

Remark

REMARK:NO OF REPAIR DAYS:2 DAYS.1X LH SLIDING DOOR LOWER MOULDING - REPLACE.1X LH SLIDING DOOR LOWER MOULDING BRACKET - REPLACE.1X LH REAR WHEEL - REPLACE.

Remark for Supplementary

▼ Damage Listing

Find a Part

root

Not Applicable

ABS

ABSORBER

ACCELERATOR

ACTUATOR

ADVERTISEMENT STICKER

AIR BAG

AIR BLOWER

AIR BOX

AIR CHAMBER BOX

AIR CLEANER

AIR COMPRESSOR

AIR CON

AIR CON (VAN)

AIR COOLER

AIR DISTRIBUTOR

AIR FILTER

AIR FLOW

AIR GRILLE

AIR HORN

No.

1

Part No.

419001

Description

TAIL GATE

Qty *

1

Repair Cost

Repair

Save

Submit