

Vehicle No. smJ2404Z
Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make of Vehicle Honda Shuttle

Colour Blue

Sp Reading 136742

Eng/No.

C/No. GK82001286

Gen. Cond. Good / Fair / Poor / Burnt

Steering Order / Jammed / Leaked / Burnt or

Brake Order / Jammed / Leaked / Burnt or

Modi. Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15
R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Falken

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A. 29/09/20

Survey held at N51

Des. of Damages: Frl / Rear / O/S / N/S / UIC / Rooftop or

Front o/s.

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP III

MV
PV
Nett.

Date/Time File Pass to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

Date/Time File Return to:

☐ : Prel. Report
☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Grid East:

☐ : Site Insp. IS
☐ : Insp. View IS
☐ : Insp. View IS
☐ : Insp. View IS

Survey Fee:

Transportation

Insurance

Other

Notes