ASS	CYCADACATO
VARANCE TIME	SIGNMENT
om: Date:	Veh No: SKK 1621M Yr Regn: 2017 104
imated Cost:	Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
INPIWS I TP RES I OD RES I EVA I INV I MV	Truck / Trailer or
Inspect Vehicle No: SKK 1621M	Make: B.M. w 370] . c.c 1998
Norkshop m/s 9 EXFORMINGE	Colour WHITE A/C: Insured / Std / NI / NA
307, MEROMORA RO	Sp.Reading 83474 T/Radio: Insured / Std / NI / NA
ured: CT(Eng/No:
licy No.	C/No: WBA8A12080A022452 .
tims No.	Gen. Cond: Good Falt Poor Burnt
m Insured: Excess:	Steering: Inforder)/ Jammed / Leaked / Burnt or
Client's Record)	Brake: Inordet / Jammed / Leaked / Burnt or
ike of Veh:	Modi: Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 225 458 18
Policy Condition)	R:
mark: The veh had commenced its N/S O/S	710
repair at the time of inspection.	TOYO / YOKO or
il. or Market Value:	
	— Front Rear R/Bal. A mm
	101
A / PR Seen: Consistent? : Yes or No tt Repairs: days Res.: Yes or No	L/Bal. 6 mm L/Bal. 6 mm
	0.0.A. 26/07/2020 0.0.1. 29/09/2020
m Sum: % 3 Val.: Yes or No	Survey held at PERFORMANCE
A / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / Cate; Person Contacted;	OUT FRE OIS & NIS FRET The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The old 7 chassis frame 7 Body Structure affected due to collision.
7,555,17,11,05,050,001	
Our client has reverted to OD claim and will be s	submitting recovery claim against your Principal in due course.
submit preli report.	
di '	7
ealerTime, File Pass to? : Prell. Report	Days Of Repair: 8
: Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add	Fee: : Site Insp (\$)s+Rssi
	: Interview (\$) Photos
Basimo Barrier	The state of the s
Roper Formel: Lunap Sum / LB.E. (%	: Tech. Invs (\$) others

Page No. : 1 of 7

ıer

Estimate No.

Performance Motors Limited

56108

A Sime Darby Motore Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

: b1

CTI

Pella ..

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Pax. 64796601 (AfterSales) 64796624 (Motorrad) 0

GST REG. NO : M2 - 0020081 - X

28 SEP 2020

ESTIMATE

Date Estimate For Prepared F	mated : 28/09/2020			rage No.	1 01 /
Tan Key J	Ris Terrace		- ACCOUNT - China Taiping 3 Anson Road #16-00 Springl Singapore 0799	eaf Tower	Pte Ltd
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL		MILEAGE
SKK1621M	WBA8A12080A022452	16/10/201	7 320iA/4Dr		0
	DESCRIPTION To replace bumper front cover, bonner, front wall attachment, front right whe chassis To remove and install front left side panel and knocking on the ac	elhouse, front			3 400 12 780.00
	To spray paint bumper front cover, bor panels, front right wheelhouse, front opillar right				3695 5,675.00
	To tow accident vehicle to PML worksh	nop.			195.00
\$ <u>\$</u>	To supply front emboss number plate.				?
1	To supply tyre. *Front left 70% -	purtured			350 500.00
t	To replace radiator assembly, fan hous to conduct pressure test, bleed bleed o for leak. (For all models except 7 serie	cooling system			743? 826.0
	To replace air con condenser and air c vacuum system, top up freon gas and (For all models except for 7 series).	on hose included the check for leak	ding to		902- 1,003.00
	To remove and install engine and auto facilitate jacking of chassis and mount bench including replacement of damage	ing of car on c	to elette		1486 7 1,652.00
	To mount accident vehicle on celette be to facilitate re-alignment of body/chase with BMW specifications.	ench OR Car- sis in accordar	O-liner Phoh?		2655 2,950.00 ? 478 521.00 94.00
	To conduct chassis alignment measur Car-O-Liner measuring system accord	ing check usin ding to BMW s	g pecification		? 478 521.00
	To replace tyre and wheel rim including front left	ng balancing. (1x).		94.00

|Sp.Reading

AAC.

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559K GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Pax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Pax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 54796601 (AfterSa) 64796624 (Mototrae (AfterSales) (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No	. : b1 56108				Page No. : 2	of 7
Estimate No Date Estima						
Prepared By		re .				J
Frepared by						
REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL			MILEAGE
SKK1621M	WBA8A12080A022452	16/10/2017	320iA/4Dr			0
	DESCRIPTION					VALUE
- -	ALCONITY TO STATE OF THE STATE					1.00
	o check steering geometry and co ecording to BMW specification (1X		ent			478 521.00
						432? 481.00
,	o replace left headlight and reprog	ramining				
T	o replace right headlight and repro	gramming				432 481.00
	o remove and install battery cables urrent tests and charge up battery.		high			478 ^{7, 531.00}
To	replace electromechanical powe	r steering including				796? 885.00
pr	ogram, initialize steering column		duct			
ch	necks for proper function.					- 1-6
To	check electrical wiring system at	the front and rear				265/295.00
	ctions for proper function including	g adjustment of				
Su	indries					7 150.00
				Tot	al Labour 1	29,613.00
DE	SCRIPTION			QTY	PRIC	VALUE
	tective film chassis number .			1	2.30	2.30
	TAKE SILENCER			1	503.55	503.55 75.30
	VER TOP?			1	75.30	784.45
RA	DIATOR ?			1	784.45	78.00
MC	DDULE CARRIER RH .	?		1	78.00	1,192.85
	N HOUSING WITH FAN 400W			1	1,192.85	283.30
	N SHROUD 400W/600W :	75.7		ı,	283.30	3,648.60
	CH STEERING BOX ELECTR. (1	3,648.60	
AL	LOY RIM 8Jx18 DOUBLE SPK 3	97 7-4-2		1	1,116.30	1,116.30
B(DNNET X repented			1	1,281.20	1,281.20
W.	hoolbourge from right 7				1,281.20	1,281.20
VV	heelhouse front right 7			1	1,681.15	1,681.15
	RACKET CABLE HARNESS 7			1	702.65	702.65
	RT RH 2 SIDE PANEL BRACKET	7		2	25.65	51.30
	RT RH 1 SIDE PANEL BRACKET			1	35.10 35.10	35.10
F	RT RH 3 SIDE PANEL BRACKET	ブ		1	35.10	35.10
P	ONNET LH HINGE 54 /	•		1	35.10 75.10	35.10
	SONNET RH HINGE L			1	75.10 75.10	75.10
	RT BUMPER TOP MOUNT?	_		1	380.00	75.10
	RT RH DEFORMATION ELEMEN	NT .		1	102.30	380.00
	FRT RH LOWER DEFORMATION	ELEMENT .		1	86.85	102.30 86.85

Policy No.

CIT

_ | Sp.Reading

A/C:

10 1-

1...

Performance Motors Limited

A Sime Darby MotorB Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Pax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Pax. 64796601 (AfterSa) 64796624 (Motorrad



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 56108 Page No. : 3 of 7

Date Estimated Prepared By

: 28/09/2020

Foong Shiuh Jye

MILEAGE

REGN. NO.

CHASSIS NO.

REGN. DATE 16/10/2017

SKK1621M

WBA8A12080A022452

3201A/4Dr

MODEL

VALUE PRIC QTY DESCRIPTION 7.05 7.05 MOUNT FOR SUPPORT 54.55 54.55 FINISHER ROD CENTRE (SPORT) 57.45 57.45 RH FINSIHER ROD (SPORT) 43.50 43.50 FRT BUMPER TOWING LUG COVER PRIMED > 53.45 53.45 RH AIR INLET FINISHER (SPORT) 54.55 54.55 FRT SHOCK ABSORBER ECE 41.10 41.10 RH AIR INLET FINISHER (BASIS) 67.30 67.30 SET MOUNTING PDC/PMA SENSOR FRT ... 1,037.05 FRT BUMPER PANEL PRIMED (SPORT LINE 1,037.05 95.05 95.05 RH PARTIALLY OPEN GRID (SPORT EDITI ? FRT LH GRILLE (BASIS)? 1 107.15 107.15 1 107.15 107.15 FRT RH GRILLE (BASIS) SUPPORT NUMBER PLATE ECE 69.60 69.60 0.80 1.60 GROMMET MA -GAS STRUT HOOD? 237.40 118.70 88.40 LH LOWER PART OF HOOK LOCK 88.40 RH LOWER PART OF HOOK LOCK ? TWIST PROTECTION ? 88.40 88.40 11.00 5.50 BONNET CATCH BRACKET ? 52.80 2 26.40 BONNET BOWDEN CABLE HOOD REAR 37.70 1 37.70 BONNET BOWDEN CABLE HOOD FRT ? 37.70 1 37.70 FRONT PANEL V STRUT 112.75 1 112.75 RH SUPPORT ? 132.15 132.15 FRT BUMPER LOWER MOUNT 134.45 134.45 RH HEADLIGHT BRACKET M 10.40 10.40 169.10 FRONT CROSSLINK 1 169.10 LH COVER FOR BULB REPLACEMENT 1 22.95 22.95 FRT RH WHEEL HOUSING COVER 1 117.15 117.15 RH COVER BOTTOM 1 117.15 117.15 DEFLECTOR LIP RH 1 64.75 64.75 AIR DUCT RADIATOR 105.35 105.35 FRT END SUPPORT 1 16.45 16.45 RH AIR DUCT BRAKE ? 1 71.20 71.20 AIR DUCT FRT BOTTOM 100.35 100.35 FRONT ENGINE HOOD SEALING 39.05 1 39.05 RH ENGINE HOOD SEALING 39.05 39.05 SEALING SIDE PANEL RH 7. 33.20 33.20 PLAQUE 82MM No / 71.60 71.60 EARTH STRAP TRUNK LID ? 50.90 50.90 (DG/SL) BMW AGM BATTERY 92 AH 740.10 740.10 BATTERY CABLE NEGATIVE IBS 2 378.05 378.05 WINDSHIELD CLEANING CONTAINER 7 127.70 127.70 BMW BLUE HALOGEN BULBS (2xH7) 76.45 76.45 BMW POWER HALOGEN BULBS 2 X H7 CA 76.45 76.45 Covering cap headlight right SET REPAIR HOLDER ? 32.85 32.85 81.70 81.70 SET SMALL PARTS headlight 7. LED Fan for headlight 49.85 49.85 437.15 **COVERING CAP** 437.15 22.60

22.60

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Pax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSa 64796624 (Motorra

(AfterSales) (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

Prepared By

: b1 56108 Page No. : 4 of 7

Date Estimated

: 28/09/2020

: Foong Shiuh Jye

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SKK1621M

WBA8A12080A022452

16/10/2017

3201A/4Dr

0

DESCRIPTION SET LED MODULE . RH LED MODULE DIRECTION INDICATOR LH HEADLIGHT LED TECHNOLOGY (BLACK ? RH HEADLIGHT LED TECHNOLOGY (BLACK FO CONTROL UNIT FRT LIGHT ELECTRONICS ? RH FOG LIGHT LED ? EVAPORATOR ? BLIND RIVET HEML OCK 813 ? BLIND RIVET AVIBVLB ?

(DG/SL) ADHESIVE GLUE? PUNCH RIVET N5 (DG) CLEANER R1 (100ML) . BLIND RIVET N7 150 STUCK (DG/SL) ADHESIVE SET K6 (S/L) SEAM SEAL 300ML

VALUE QTY PRIC 166.25 166.25 789.75 789.75 1 2,681.50 2,681.50 1 2,681.50 2,681.50 893.90 893.90 453.25 453.25 979.30 979.30 23.85 2.65 2.20 0.55 331.80 331.80 1 6.05 11 0.55 26.15 26.15 124.70 2.90 43 53.05 53.05 1 33.80 33.80

Total Parts

28,546.10

0.00

0.00

62,230.24

ress No.		losses / Direct Settlement Claim No
29	09/2020 P145	Excess S\$
s evor's Name	Rose	Sign
orveyor's Tel	90000068	Authorised Yes / No
horised Date		Time
	TS PHOTO BY SURVE	YOR Yes I No PML Yes I
Surveyor's E-mail		
No of Working D	eys Recommend	8-9 days

LKK Auto Consultants hence nouly the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Fron Estim

OD/T

To Inspe

at Workst.

sured:

licy No. ims No. Labour 1 29,613.00 Parts 28,546.10 Labour 2 Excess Total GST @ 7% 4,071.14

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Eng/No:

T/Radio: Insured / Std / Std

Grand Total

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

roi ilin Lli Inst Vork

/ No.

s No. nsurec

nt's Records

Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3, Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

	AGGIDENT:STATEMENT
Date Of Report	28/09/2020 10:38
Date Of Accident	26/09/2020 15:00
Exact Location Of Accident	JURONG GATEWAY ROAD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SKK1621M
Insured/Policyholder	
Name Of Registered Owner	TAN KEY JANG
NRIC No	SXXXX392G
Email Address	KJTAN9@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93876327
Alternative Phone No	OTHERS-93876327
Vehicle Particulars	
Manufacturer	BMW
Model	3201
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	UNAVAILABLE
Cover Note Number	
Driver	
Name of Driver	TAN KEY JANG
NRIC No	SXXXX392G
Date Of Birth	26/10/1962
Occupation	INDOOR
Date Of Driving Pass	28/05/1982
Driving Experience	38 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93876327
Fax Number	
CARDON NATIONAL PROPERTY OF THE CONTROL OF THE CONT	

OTHERS-93876327

KJTAN9@GMAIL.COM

dress

81 PASIR RIS TERRACE

sostcode

518725

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD ON COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle) involved in the accident

3

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

NO

ambulance?

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

YES

2

Number of Passengers (Including Driver)

Passenger 1

NAME:

: GOH TECK BUAY

GENDER:

: FEMALE

Details of Police Action

Was the accident reported to the police? If Yes, Please state which Police Station

YES

Police Station Name

KEBUN BARU NEIGHBOURHOOD POLICE POST

Police Station Address

ROAD: BLK 111 ANG MO KIO AVENUE 4, POSTCODE: 560111,

COUNTRY: SINGAPORE

Police Station Contact

TEL NO: 1800-4589999 - FAX NO: 64574454

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

30

14

11

ord)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

WITH POLICE

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 118

Vehicle Registration Number

SMA5281M

Vehicle Make/Model/Colour

TOYOTA

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

KARMEN

NRIC/Passport Number

SXXXX439G

Contact Number

88200896

Idress

ostcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

IDETAILS OF OTHER VEHICLE PROPERTY 28

Vehicle Registration Number

SKP9301H

Vehicle Make/Model/Colour

MAZDA

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder Signature Date & Time

Carlotte Contract Contract

Driver's Signature (If driver is not the policyholder) Date & Time:

Reporting Centre Personnel's Signature

NRIC/FIN No.:

ETCH PLAN	₹ 0	
	KP 930M	
	ξ, ε	
	len l	
	Somil scal m	
	SKN 69 m	
SCRIBE CIRCUMSTANCES OF		
Refer to police	ाध्या ।	
		The state of the s

	· · · · · · · · · · · · · · · · · · ·	
DECLARATION IVWo doc		
I/We declare the foregoing partic	ulars are true in every respect.	A.
1 IIX		-0y
Policyholders Mariature Date & Time.	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature
	Date & Time:	Name: NRIC/FIN No.:





Police Station Of Origin: Kebun Baru NPP 111 Ang Mo Kio Avenue 4 SINGAPORE 560111

1 of 4 Report No. T/20200926/2103

Tel No: 1800-4589999

o in

ila un (C ekt REPORT OF A TRAFFIC ACCIDENT

	e Report M 20 17:25	ade:	Vide Report No.: D/20200926/0075	Station Diary No.: 24		
inous	it's Partici	Litts.				
Name of TAN KE	Informant: Y JANG		Address:	CE SINGAPORE 518725		
	/ ID No.: D / S155339	92G	Contact No.: Home/Office: Mobile: 93876327			
National SINGAP	ity: ORE CITIZ	EN	Email:			
Sex: Male	Age: 57	Date of Birth: 26/10/1962	Type of Informant: Driver			
Race: Chinese			Language:	Institution / School Name:		
Occupation: Retiree		Driving Licence Informations: 3	ation: Date of Expiry:			

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 26/09/2020 14:50	Type of Location: X-Junction	
JURONG GA	TEWAY ROAD	Road Surface:		Road Speed Limit:	
Clear		Dry			
		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate	

/enice Nov	Alype	Make	Model	Color	Condition.	No of Passenge
SKK1621M	Car	BMW	3201	White	Seriously Damaged	1
SKP9301H	Car	MAZDA			Damagou	0
SMA5281M	Car	TOYOTA	Camry	Black		0

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





Police Station Of Origin: Kebun Baru NPP 111 Ang Mo Kio Avenue 4 SINGAPORE 560111

2 of 4 Report No. T/20200926/2103

Tel No: 1800-4589999

CONTINUATION OF REPORT

OH TECK BUAY			ID No.		S1576386H
KK1621M (Car)			Contact	No.	81574122
NIL			0.000		Class: NIL
1			Licence	. & e	Date of Expiry: NIL
NIII		Date Disc		-	
					
	ASSESSMENT OF THE PARTY OF THE	10000000000000000000000000000000000000	Sandy Color	Z Kr A - An	
TAN KEY JANG	以联系,2017年2月2日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月1日 1018年2月 1018年		ID No.		S1553392G
SKK1621M (Car)			Contac	t No.	93876327
NIL			Driving Licence	e &	Class: 3 Date of Expiry: NIL
			harge	NIL	
ed Medical Leave	NIL	Degree of	f Injury	NIL	
KARMEN			ID No.		S9004439G
SMA5281M (Car)			Conta	ct No.	88200896
NIL		n	Drivin Licen	g ce &	Class: NIL Date of Expiry: NIL
NIL		Date Dis	charge	NIL	
ited Medical Leave	NIL	Degree of	of Injury	NIL	
Carried West or at Trops of a			THE PARTY OF THE	12 18 2	
1			ID No.		S7043226I
NIL			Contact No.		. 91150150
NIL				ng	Class: NIL Date of Expiry: NIL
nt NIL		Date Dis	Expir	y Date	
	NIL NIL NIL NIL NIL MIL MIL MIL	NIL NIL NIL MIL MIL MIL TAN KEY JANG SKK1621M (Car) NIL MIL KARMEN SMA5281M (Car) NIL NIL NIL YAP SHAN SHAN NIL	NIL NIL Date Discled Medical Leave NIL Degree of TAN KEY JANG SKK1621M (Car) NIL NIL NIL Ed Medical Leave NIL Date Discled Medical Leave NIL NIL NIL NIL NIL NIL Date Discled Medical Leave NIL Date Discled Medical Leave NIL Date Discled Medical Leave NIL NIL NIL NIL NIL NIL NIL NI	SKK1621M (Car) NIL Date Discharge Expiry MIL Degree of Injury TAN KEY JANG SKK1621M (Car) NIL Class of Driving Licence Expiry NIL Contact Contact	Contact No. Class of Driving Licence & Expiry Date NIL Date Discharge NIL Degree of Injury NIL TAN KEY JANG ID No. SKK1621M (Car) Contact No. NIL Date Discharge NIL Class of Driving Licence & Expiry Date NIL Date Discharge NIL Ed Medical Leave NIL Degree of Injury NIL KARMEN ID No. SMA5281M (Car) Contact No. NIL Date Discharge NIL KARMEN ID No. Class of Driving Licence & Expiry Date NIL Degree of Injury NIL KARMEN ID No. NIL Date Discharge NIL Class of Driving Licence & Expiry Date NIL Date Discharge NIL YAP SHAN SHAN ID No. NIL Class of Driving





Police Station Of Origin: Kebun Baru NPP 111 Ang Mo Kio Avenue 4 SINGAPORE 560111 Tel No: 1800-4589999

3 of 4 Report No. T/20200926/2103

CONTINUATION OF REPORT

Brief Details.

On 26/09/2020 around 1450hrs, I was driving my car, one White BMW 320I (vehicle no. SKK1621M) with one passenger on the front left passenger seat. I was stationary at the junction of Jurong Gateway towards Jurong East Street 21. My car was at the right most lane of Jurong Gateway and I was waiting for the traffic light to turn green.

Suddenly, I felt an impact from the right side (driver side) of my car. I exited and saw that a Black Toyota Camry (vehicle no. SMA5281M) had collided front on to the right side of my car. I saw that the Toyota had mounted the kerb and hit onto the road divider from the opposite side before colliding onto my car.

I also spotted another car, one Red Mazda (vehicle no. SKP9301H) that was stopped somewhere on the opposite side of the road.

I exchanged particulars with the other drivers, Karmen - driver of SMA5281M & Yap Shan Shan - driver of SKP9301H.

Subsequently, traffic police officers attended to us reference D/20200926/0075.

Due to the collision, my car's front right side body (bonnet, bumper and lights) was seriously damaged, and the front left side tyre was punctured and the front left tyre rim was damaged. My car was towed away subsequently.

My passenger and I was not injured.

I have an in-car camera. I am lodging this report for my own record and action.





Police Station Of Origin: Kebun Baru NPP 111 Ang Mo Kio Avenue 4 SINGAPORE 560111 Tel No: 1800-4589999

T/20200926/2103

Report No. T/20200926/2103

CONTINUATION OF REPORT

Sketch Plan

mate TP, speci rksho, 5/8

ed: Record)

dition)

veh had


Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording F / Sgt 2 IZWAN BIN SANI	ng The Report:	Signature of Informant:	
Signature Of Interpreter: Not applicable		Date/Time: 26/09/2020 17:25	
Officer In Charge Of Case: TP / GIT / Sr Staff Sgt MOHAMMED F Contact No.: 65476206	EROZ BIN HUSSIEN	Classification Of Case:	
Authentication Stamp NP168	1 1 2 2 2 2 2 2	no Force	

> Back to OneMotoring Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type: Owner ID:	Singapore NRIC 392G
Vehicle No.	型形型型型型型型型型 SKK1621M 對於原理學與實施學的
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Sep 2020
Vehicle Make:	B.M.W.
Vehicle Model:	
Primary Colour:	3201 LED NAV SHAD. LIGHT
Manufacturing Year:	White
Engine No.:	2017
Chassis No.:	G2141794B48B20A
Maximum Power Output:	WBA8A12080A022452
Open Market Value:	135.0 kW (181 bhp)
Original Registration Date:	\$39,392.00
First Registration Date:	16 Oct 2017
Transfer Count:	16 Oct 2017
Actual ARF Paid:	0
Control Contro	\$42,149.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	15 Oct 2027 \$31,611.00
[+14-1-14-4-4-4-4] =+ (43-1-14-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	
COE Expiry Date:	15 Oct 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period (Years):	10
QP Paid:	\$53,711.00



Sports Steering Wheel.